

U.S. Department of Transportation

National Highway Traffic Safety Administration

DOT HS 812 769



July 2019

Special Crash Investigations On-Site Air Bag Non-Deployment Crash Investigation Vehicle: 2015 Chevrolet Camaro Location: California Crash Date: July 2017

Disclaimer

This publication is distributed by the U.S. Department of Transportation, National Highway Traffic Safety Administration, in the interest of information exchange. The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the Department of Transportation or the National Highway Traffic Safety Administration. The United States Government assumes no liability for its contents or use thereof. If trade or manufacturers' names or products are mentioned, it is because they are considered essential to the object of the publication and should not be construed as an endorsement. The United States Government does not endorse products or manufacturers.

Suggested APA Format Citation:

 Dynamic Science, Inc. (2019 July). Special Crash Investigations; On-Site Air Bag Non-Deployment Crash Investigation; Vehicle: 2015 Chevrolet Camaro; Location: California; Crash Date: July 2017 (Report No. DOT HS 812 769). Washington, DC: National Highway Traffic Safety Administration.

Technical Report Documentation Page

4. Title and Subtitle S. Report Date Special Crash Investigations; July 2019 On-Site Air Rag Non-Deployment Crash Investigation; Vehicle: 2015 Chevrolet Camaro; Location: California; Crash Date: July 2017 7. Author 6. Performing Organization Report No. Dynamic Science, Inc. 8. Performing Organization Report No. 299 West Cerritos Avenue 11. Contract or Grant No. Anaheim, CA 92805 11. Contract or Grant No. 212 Sponsofing Agency Name and Address 11. Contract or Grant No. National Highway Traffic Safety Administration 12. Sponsoring Agency Code 12. Sopresering Agency Name and Address 13. Type or Report and Period Covered Technical Report Technical Report 1200 New Jersey Ave, SE 13. Supplementary Notes This report documents the on-site investigation of the alleged non-deployment of the driver's air bags in a 2015 Chevrolet Camaro involved in a crash and the injuries sustained by the driver. Each crash represents a unique sequence of events, and generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicles or their safety systems. This report and associated case data are based on information available to the Special Crash Investigation team. 16. Abstract A notiffication stated the driver's air bags did	1. Report No. DOT HS 812 769	2. Government Accession No.	3. Recipient's Catalog No.
7. Author 6. Performing Organization Code 7. Author Dynamic Science, Inc. 6. Reforming Organization Report No. 29. Performing Organization Name and Address Case No. DS17013 299 West Cerritos Avenue 10. Work Unit No. (TRNIs) 299 West Cerritos Avenue 11. Contract or Grant No. Anaheim, CA 92805 DTINH22-12-C00271 12. Sponsoring Agency Name and Address 13. Type of Report and Period Covered Technical Report 1200 New Jersey Ave, SE Technical Report 1200 New Jersey Ave, SE 14. Sponsoring Agency Code 15. Supplementary Notes 13. Type of Report and Period Covered Technical Report This report documents the on-site investigation of the alleged non-deployment of the driver's air bags in a 2015 Chevrolet Camaro involved in a crash and the injuries sustained by the driver. Each crash represents a unique sequence of events, and generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicles or their safety systems. This report indicated both air bags did deploy while front right occupant's air bags did deploy. The SCI inspection revealed the driver's in bags did deploy while front right occupant is air bags did deplot the alleger of the chrored trastrate highway in the state of California during June 2017. The Chevrolet was being driven by a belted 20-year-old male. A belted 18-year-old female occupant was seated in the front right position. According to the interviewee, the driver's frontal a	4. Title and Subtitle Special Crash Investigations; On-Site Air Bag Non-Deployment Crash Investigation; Vehicle: 2015 Chevrolet Camaro; Location: California;		
Dynamic Science, Inc. Case No. DS17013 9. Performing Organization Name and Address Dynamic Science, Inc. 10. Work Unit No. (TRAIS) 299 West Cerritos Avenue Anaheim, CA 92805 11. Contract or Grant No. DTNH22-12-C00271 12. Sponsoring Agency Name and Address National Highway Traffic Safety Administration 1200 New Jersey Ave, SE 13. Type of Report and Period Covered Technical Report 15. Supplementary Notes 13. Type of Report and Period Covered Technical Report 15. Supplementary Notes 13. Sponsoring Agency Code 16. Supplementary Notes This report documents the on-site investigation of the alleged non-deployment of the driver's air bags in a 2015 Chevrolet Camaro involved in a crash and the injuries sustained by the driver. Each crash represents a unique sequence of events, and generalized conclusions cannot be made concerning the crash worthiness performance of the involved vehicles or their safety systems. This report and associated case data are based on information available to the Special Crash Investigation team. 16. Abstract A notification stated the driver's air bags did not deploy while front right occupant's air bags did deploy. The SCI inspection revealed the driver's air bags did not deploy while front right occupant's air bags did deploy. The SCI inspection revealed the driver's air bags did not deploy and the vehicle's EDR report indicated both air pags deployed during the crash. This single-vehicle rollover crash. Crash and credit hight position. According to the interviewee, the driver of the Chevrolet was strate-state highway in the state of California during June 2017. The Chevrolet w			6. Performing Organization Code
Dynamic Science, Inc. 11. Contract or Grant No. 299 West Cerritos Avenue 11. Contract or Grant No. Anaheim, CA 92805 DTNH22-12-C00271 12. Sponsoring Agency Name and Address 13. Type of Report and Period Covered Technical Report National Highway Traffic Safety Administration 13. Type of Report and Period Covered Technical Report 1200 New Jersey Ave, SE Crash Date: June 2017 Washington, DC 20590 14. Sponsoring Agency Code 15. Supplementary Notes This report documents the on-site investigation of the alleged non-deployment of the driver's air bags in a 2015 Chevrolet Camaro involved in a crash and the injuries sustained by the driver. Each crash represents a unique sequence of events, and generalized conclusions cannot be made concerning the crash. rashworthiness performance of the involved vehicles or their safety systems. This report and associated case data are based on information available to the Special Crash Investigation team. 16. Abstract A notification stated the driver's frontal and IC air bags did deploy and the vehicle's EDR report indicated both air bags deployed during the crash. This single-vehicle rollover crash occurred at night on a westbound interstate highway in the state of California during June 2017. The Chevrolet was being driver by a belted 20-year-old male. A belted 18-year-old female occupant was seated in the front right ogetion. According to the interviewee, the driver of the Chevrolet was street-racing another vehicle priot to the crash. The driver of the Chevrolet lost c			
Anaheim, CA 92805 DTNH22-12-C00271 12. Sponsoring Agency Name and Address National Highway Traffic Safety Administration 1200 New Jersey Ave, SE 13. Type of Report and Period Covered Technical Report 12.00 New Jersey Ave, SE 14. Sponsoring Agency Code 15. Supplementary Notes 14. Sponsoring Agency Code 15. Supplementary Notes 14. Sponsoring Agency Code 15. Supplementary Notes in the on-site investigation of the alleged non-deployment of the driver's air bags in a 2015 Chevrolet Camaro involved in a crash and the injuries sustained by the driver. Each crash represents a unique sequence of events, and generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicles or their safety systems. This report and associated case data are based on information available to the Special Crash Investigation team. 16. Abstract A notification stated the driver's in bags did not deploy while front right occupant's air bags did deploy. The SCI inspection revealed the driver's forntal and IC air bags did deploy and the vehicle's EDR report indicated both air bags deployed during the crash. This single-vehicle rollover crash occurred at night on a westbound interstate highway in the state of California during June 2017. The Chevrolet was being driven by a belted 20-year-old male. A belted 18-year-old female occupant was seated in the front right position. According to the interviewee, the driver of the Chevrolet was street-racing another vehicle prior to the crash. The driver of the Chevrolet lost control of the vehicle and it departed the roadway on the right dege and overturmed while traveling down an embankment, causing damage to all pl	Dynamic Science, Inc.		10. Work Unit No. (TRAIS)
National Highway Traffic Safety Administration 1200 New Jersey Ave, SE Technical Report Crash Date: June 2017 Washington, DC 20590 14. Sponsoring Agency Code 15. Supplementary Notes This report documents the on-site investigation of the alleged non-deployment of the driver's air bags in a 2015 Chevrolet Camaro involved in a crash and the injuries sustained by the driver. Each crash represents a unique sequence of events, and generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicles or their safety systems. This report and associated case data are based on information available to the Special Crash Investigation team. 16. Abstract A notification stated the driver's air bags did not deploy while front right occupant's air bags did deploy. The SCI inspection revealed the driver's frontal and IC air bags did deploy and the vehicle's EDR report indicated both air bags deployed during the crash. This single-vehicle rollover crash occurred at night on a westbound interstate highway in the state of California during June 2017. The Chevrolet was being driven by a belted 20-year-old male. A belted 18-year-old female occupant was seated in the front right position. According to the interviewee, the driver of the Chevrolet was street-racing another vehicle prior to the crash. The driver of the Chevrolet lost control of the vehicle and it departed the roadway on the right edge and overturned while traveling down an embankment, causing damage to all planes. Following the crash, the driver was transported to a local hospital, treated for minor injuries, and released. The Chevrolet was transported to a local hospital, treated for minor injuries, and released. The Chevrolet was transported to a local hospital, treated for minor injuries, and released. The Chevrolet was transp			
15. Supplementary Notes 15. Supplementary Notes This report documents the on-site investigation of the alleged non-deployment of the driver's air bags in a 2015 Chevrolet Camaro involved in a crash and the injuries sustained by the driver. Each crash represents a unique sequence of events, and generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicles or their safety systems. This report and associated case data are based on information available to the Special Crash Investigation team. 16. Abstract A notification stated the driver's frontal and IC air bags did deploy and the vehicle's EDR report indicated both air bags deployed during the crash. This single-vehicle rollover crash occurred at night on a westbound interstate highway in the state of California during June 2017. The Chevrolet was being driven by a belted 20-year-old male. A belted 18-year-old female occupant was seated in the front right position. According to the interviewee, the driver of the Chevrolet was street-racing another vehicle prior to the crash. The driver of the Chevrolet lost control of the vehicle and it departed the roadway on the right edge and overturned while traveling down an embankment, causing damage to all planes. Following the crash, the driver was transported to a local hospital, where he died four days later as a result of his injuries. The Chevrolet was transported to a local hospital, where he died four days later as a result of his injuries. The Chevrolet was transported to a local hospital, where he died four days later as a result of his injuries. The Chevrolet was transported to a local hospital, treated for minor injuries, and released. The Chevrolet was transported to a local hospital, where he died four days later as a result of his injury, fatality, rol	National Highway Traffic Safety Adm 1200 New Jersey Ave, SE	ninistration	Technical Report
This report documents the on-site investigation of the alleged non-deployment of the driver's air bags in a 2015 Chevrolet Camaro involved in a crash and the injuries sustained by the driver. Each crash represents a unique sequence of events, and generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicles or their safety systems. This report and associated case data are based on information available to the Special Crash Investigation team. 16. Abstract A notification stated the driver's air bags did not deploy while front right occupant's air bags did deploy. The SCI inspection revealed the driver's frontal and IC air bags did deploy and the vehicle's EDR report indicated both air bags deployed during the crash. This single-vehicle rollover crash occurred at night on a westbound interstate highway in the state of California during June 2017. The Chevrolet was being driven by a belted 20-year-old male. A belted 18-year-old female occupant was seated in the front right position. According to the interviewee, the driver of the Chevrolet was street-racing another vehicle prior to the crash. The driver of the Chevrolet lost control of the vehicle and it departed the roadway on the right edge and overturned while traveling down an embankment, causing damage to all planes. Following the crash, the driver was transported to a local hospital, where he died four days later as a result of his injuries. The front right occupant was transported to a local hospital, where he died four days later as a result of his injuries. The front right occupant was transported to a local hospital, where he died four days later as a result of his injuries. The front right occupant was transported to a local hospital, where he died four days later as a result of his injuries. The front right occupant was transported to a local h	Washington, DC 20590		14. Sponsoring Agency Code
A notification stated the driver's air bags did not deploy while front right occupant's air bags did deploy. The SCI inspection revealed the driver's frontal and IC air bags did deploy and the vehicle's EDR report indicated both air bags deployed during the crash. This single-vehicle rollover crash occurred at night on a westbound interstate highway in the state of California during June 2017. The Chevrolet was being driven by a belted 20-year-old male. A belted 18-year-old female occupant was seated in the front right position. According to the interviewee, the driver of the Chevrolet was street-racing another vehicle prior to the crash. The driver of the Chevrolet lost control of the vehicle and it departed the roadway on the right edge and overturned while traveling down an embankment, causing damage to all planes. Following the crash, the driver was transported to a local hospital, where he died four days later as a result of his injuries. The front right occupant was transported to a local hospital, where he died for minor injuries, and released. The Chevrolet was towed due to damage. 17. Key Words 18. Distribution Statement air bag, non-deployment, deployment, injury, fatality, rollover 18. Distribution Statement Document is available to the public from the National Technical Informational Technical Informational 19 Security Classif. (of this report) 20. Security Classif. (of this page) 21 No. of Pages 22. Price 19 Security Classified 21 No. of Pages 22. Price	Each crash represents a unique sequen crashworthiness performance of the in	nce of events, and generalized conclusion of events, and generalized conclusion of their safety systems	ons cannot be made concerning the . This report and associated case
air bag, non-deployment, deployment, injury, fatality, rolloverDocument is available to the public from the National Technical Information Service, www.ntis.gov.19 Security Classif. (of this report)20. Security Classif. (of this page) Unclassified21 No. of Pages 6722. Price	A notification stated the driver's air bainspection revealed the driver's fronta bags deployed during the crash. This shighway in the state of California duri male. A belted 18-year-old female occur the driver of the Chevrolet was street- control of the vehicle and it departed the embankment, causing damage to all pl where he died four days later as a result	I and IC air bags did deploy and the ve single-vehicle rollover crash occurred a ing June 2017. The Chevrolet was bein cupant was seated in the front right pos racing another vehicle prior to the crass the roadway on the right edge and over lanes. Following the crash, the driver v alt of his injuries. The front right occup	hicle's EDR report indicated both air it night on a westbound interstate g driven by a belted 20-year-old ition. According to the interviewee, h. The driver of the Chevrolet lost turned while traveling down an vas transported to a local hospital, ant was transported to
Unclassified Unclassified 67		, injury, fatality, rollover	Document is available to the public from the National Technical Information Service,

Form DOT F 1700.7 (8-72)

Reproduction of completed page authorized

BACKGROUND	1
SUMMARY	2
Crash Site	2
Pre-Crash	2
Crash	3
Post-Crash	4
2015 CHEVROLET CAMARO	4
Description	4
Exterior Damage	5
Event Data Recorder	6
Interior Damage	6
Manual Restraint Systems	7
Supplemental Restraint Systems	7
NHTSA Recalls and Investigations	8
Rollover Mitigation	9
2015 CHEVROLET CAMARO OCCUPANTS	10
Driver Demographics	10
Driver Injuries	10
Driver Kinematics	12
Front Right Occupant Demographics	12
Front Right Occupant Injuries	13
Front Right Occupant Kinematics	13
CRASH DIAGRAMS	14
APPENDIX A: Event Data Recorder Report 2015 Chevrolet Camaro	A-1

Table of Contents

Special Crash Investigations On-Site Air Bag Non-Deployment Crash Investigation Case Number: DS17013 Vehicle: 2015 Chevrolet Camaro Location: California Crash Date: July 2017

BACKGROUND

This report documents the on-site investigation of the alleged non-deployment of the driver's air bags and the injuries sustained by the driver of a 2015 Chevrolet Camaro (**Figure 1**) that was involved in a single-vehicle rollover crash. This case was initiated in response to a notification sent to the National Highway Traffic Safety Administration. The Special Crash Investigations (SCI) group assigned the case to Dynamic Science, Inc., in August 2017. The notification stated that the vehicle sustained significant damage to the front end and the air bags on the driver's side did not deploy while air bag deployment did occur on the passenger's side of the vehicle.



Figure 1. 2015 Chevrolet Camaro

The inspection revealed the frontal air bag did deploy at the driver seat position from the steering wheel hub and the left inflatable curtain (IC) air bag did deploy from the roof side rail. The investigation was intended to determine occupant restraint usage, kinematics, injury sources, and air bag deployment parameters for this vehicle. The Chevrolet was located at the home of the registered owner where the vehicle inspection was completed in August 2017. It was supported by the Bosch Crash Data Retrieval (CDR) system and the vehicle's event data recorder (EDR) was imaged during the inspection. The EDR report indicated the driver's frontal and side air bags deployed during the first event, which was a frontal impact. The passenger's frontal air bag, IC air bag, and seat-mounted side air bag also deployed during the crash. During the interview, the contact who submitted the notification clarified her belief that the driver's frontal air bag deployed late in the crash sequence sometime after the initial frontal impact, causing the driver to strike the steering wheel resulting in severe injuries to the face and head.

This single-vehicle rollover crash occurred at approximately 2330 hours on a westbound interstate highway in California during June 2017. The Chevrolet was being driven by a belted 20-year-old male. A belted 18-year-old female occupant was seated in the front right position. According to the interviewee, the driver of the Chevrolet was street-racing another vehicle. The driver of the Chevrolet lost control of the vehicle, it departed the roadway on the right edge, and overturned while traveling down an embankment. The vehicle sustained damage to all planes.

The driver of the vehicle was transported to a local hospital where he died 4 days later as a result of his injuries. The front right occupant was transported to a local hospital and treated for minor injuries. The Chevrolet was towed due to damage and later removed by the registered owner.

SUMMARY

Crash Site

The crash site was the westbound lanes of a threelane divided interstate highway in California (**Figure 2**). The concrete roadway was straight, level, and dry. The three travel lanes measured 3.6 m (12.0 ft) wide and were separated by dashed white lines. The roadway was bordered on the right by a white fog line, an asphalt shoulder, and a descending embankment. It was bordered on the left by a yellow fog line, an asphalt shoulder, an unpaved median, and a guardrail. The posted speed limit was 113 km/h (70 mph). Conditions were dark with illumination, clear and dry. Crash diagrams are included at the end of this technical report.

Pre-Crash

The Chevrolet was traveling westbound in the third lane from the right at an EDR-reported vehicle speed of 199.0 km/h (134.0 mph) at -4.0 seconds to algorithm enable (AE). The interviewee said the driver was street-racing another vehicle.



Figure 2. Crash site looking west



Figure 3. Crash site looking west, yaw marks indicate area of departure

Accelerator pedal position and engine throttle were 99 percent "Full," the service brake was "Off," engine rpm was 6,400, , and cruise control was "Off." At some point prior to impact, the driver attempted to pass a non-contact vehicle traveling directly ahead of the Chevrolet. He steered left, departing the roadway on the left edge, and traveled parallel to the roadway with the vehicle's left tires on the dirt median and the right tires on the paved shoulder. Tire yaw marks beginning on the paved shoulder suggested the driver lost control of the vehicle prior to returning to the roadway. The driver braked at -3.0 seconds and again at -2.0 seconds to AE. The Chevrolet then traveled to the right, crossing all lanes of the roadway and depositing three yaw marks while rotating clockwise (**Figure 3**). It departed the roadway on the right edge and traveled down a descending embankment with an estimated slope of -8.0 percent. EDR-reported vehicle-indicated speeds at -2.5 seconds and -1.0 second were used to calculate the distance traveled in the yaw as 41 m (135 ft). During the final 1.0 second prior to impact, the vehicle was airborne. The precrash distance traveled is shown in the table on the following page.

Time	Vehicle Speed			Distance	Traveled	
Time	v enicie s	speed	Incre	mental	Cumu	lative
-sec	km/h	mph	m	ft	m	ft
5	196	122	NA	NA	NA	NA
4.5	200	124	27.5	90.2	27.5	90.2
4	216	134	28.8	94.6	56.3	184.8
3.5	198	123	28.7	94.2	85	279
3	161	100	24.9	81.8	110	360.8
2.5	119	74	19.4	63.8	129.4	424.6
2	93	58	14.8	48.4	144.2	473
1.5	84	52	12.3	40.3	156.5	513.3
1	79	49	11.3	37	167.7	550.3
0.5	68	42	10.2	33.4	177.9	583.7

The vehicle's EDR-reported pre-crash driver input status at Time 0.0 seconds is stated in the table below:

Time (sec) -0.5 at Event	Accelerator Pedal (%)	Service Brake Activation	Engine rpm	Engine Throttle (%)	Speed, Vehicle Indicated (mph [km/h])
First Record	0	OFF	1,984	12	42 (67)

Crash

After going airborne the Chevrolet's front plane struck the ground of the descending embankment in a non-horizontal configuration (Event 1). The EDR report indicated a frontal event with a maximum longitudinal delta-V of -44 km/h (-27 mph) and maximum lateral delta-V of 11 km/h (7 mph). The driver's frontal air bag Time to 1st Stage Deployment was 58 milliseconds (ms) and the Time to 2nd Stage Deployment was 71 ms. The left inflatable curtain (IC) air bag Time to Deploy was 71 ms and the driver's seat belt pretensioner Time to Fire was 58 ms. Air bag deployments and times were identical on the front right passenger's side of the vehicle. The non-horizontal impact precluded a WinSMASH reconstruction.

The Chevrolet initiated a post-impact trip-over rollover, left side leading (Event 2). The EDR reported this as a rollover occurring 0.11 seconds after the prior event. It was identified as a deployment-level event but no air bag deployments or times were documented in this EDR record. The vehicle rolled downhill in a counterclockwise rotation along its longitudinal axis for a total of four quarter-turns. Scene evidence indicated a probable minimal roll distance of 15.0 m (49 ft).

At the base of the descending embankment the vehicle's right plane struck a concrete drainage culvert (Event 3), triggering the deployment of the front right occupant's seat-mounted side impact air bag at 0 ms. The EDR reported a third deployment event occurring 0.55 seconds after the prior event with maximum longitudinal and lateral delta-V's of 44 km/h (27 mph) and -32 km/h (-20 mph). The driver's seat-mounted side impact air bag was not commanded to deploy during this event.

The vehicle continued in a forward trajectory, striking and traveling through a chain-link fence (Event 4) in a non-deployment event. The Chevrolet came to rest near the fence upright and facing an unknown direction on level ground.

Post-Crash

Following the crash, the driver was unconscious and both doors were jammed shut. Responders forced open the driver's door and removed him from the vehicle due to his perceived serious injuries. The front right occupant was assisted from the vehicle through the same door. Both occupants were transported by ambulance to a local hospital. The driver was removed from life support four days after the crash and declared deceased. The front right occupant was treated and released the night of the crash. The Chevrolet was towed on orders of police and removed two days later by the registered owner to her residence.

2015 CHEVROLET CAMARO

Description

The 2015 Chevrolet Camaro was a two-door coupe identified by the Vehicle Identification Number 2G1FJ1EW8F9xxxxx. The vehicle was manufactured in June 2015 and the owner-estimated mileage was 51,500 km (32,000 mi). It was configured with an 8-cylinder, 6.2- liter, gasoline engine, with manual transmission and rear-wheel drive. Standard equipment included daytime running lights, tilt steering, and antilock brakes. Optional equipment included a power moon roof. The vehicle manufacturer recommended 285/35ZR20 tires for the front and rear. The vehicle was equipped with Falken Azenis FK493CC tires size 275/40R20 on the front and size 295/40R20 on the rear manufactured in April 2016. The specific tire data is in the table below.

Position	Measured Tread Depth	Restricted	Damage
LF	5 mm (6/32in.)	No	Cut, de-beaded and flat, wheel and tire off vehicle
LR	2 mm (2/32in.)	No	De-beaded and flat
RR	2 mm (2/32in.)	No	De-beaded and flat
RF	5 mm (6/32in.)	Yes	None

The Chevrolet was configured with seating for four occupants. The front row was equipped with bucket seats with integral head restraints. Both front seats were adjusted to the middle track position with the seat backs slightly reclined.

Exterior Damage

The Chevrolet sustained moderate severity front plane damage from the non-horizontal impact with the ground (Figure 4). The front bumper fascia and backing bar were displaced from the vehicle. A fractured section of fascia measuring 64 cm (23.2 in.) was missing. The backing bar was repositioned for the purpose of obtaining crush measurements during the inspection. The direct damage and Field L extended from bumper corner to bumper corner and measured 180 cm (70.9 in.). Thirteen measurements were taken at bumper level by the Nikon Total Station and the Faro Blitz program computed crush measurement in six increments, as follows: C1 = 18 cm (7.1 in.), C2 =16 cm (6.3 in.), C3 = 15 cm (5.9 in.), C4 = 12 cm(4.7 in.), C5 = 7 cm (2.8 in.), C6 = 3 cm (1.2 in.).The principal direction of force was calculated at 340 degrees. Both frame rails were shifted 15 cm (5.9 in.) to the right. The Collision Deformation Classification (CDC) for the Chevrolet in Event 1was 00FDEW1.

The Chevrolet sustained moderate severity damage to the top plane during the rollover event (**Figure 5**). Direct damage was distributed laterally from roof side rail to roof side rail and measured 124 cm (48.8 in.) in width. Direct damage was distributed



Figure 4. Front plane crush measurement, 2015 Chevrolet Camaro



Figure 5. Rollover measurements, 2015 Chevrolet Camaro

longitudinally beginning at the leading edge of the hood and extending to the trunk lid. Maximum vertical crush was located on the left roof at 40 cm (15.7 in.) forward of the rear axle and measured 15 cm (5.9 in.). Maximum lateral crush was documented at the same location and measured 22 cm (8.6 in.). The CDC for the rollover event was 00TDDO3.

The Chevrolet sustained estimated moderate severity damage to the right plane from the impact with the culvert. The sheet metal sustained crush damage from bumper corner to bumper corner and the right rear wheel was canted outboard of the wheel well. This was a non-horizontal impact and the CDC for this impact was 00RDEW2.

The vehicle sustained masked damage at the impact with the chain link fence. The fence yielded as the vehicle traveled through it displacing the fence and posts. The CDC for this event was 9999999.

Event Data Recorder

The Chevrolet's EDR was imaged during the vehicle inspection using the data link connector interface with power supplied by a jump box connected to the vehicle's service battery. The EDR was imaged using Bosch CDR Tool version 17.4 and reported using version 18.0.2. The complete EDR report is included in this report as Appendix A.

The EDR report captured three records. Record 1 was a deployment level frontal impact with an embankment during which the driver's and passenger's frontal air bags deployed in two stages (58 ms and 71 ms, respectively), their seat belt pretensioners actuated (58 ms) and both IC air bags deployed (71 ms). This record suggested the alleged air bag non deployment claim by the vehicle owner was unfounded.

Record 2 was a deployment level rollover event occurring 0.11 seconds after the first event. The IC air bags had deployed in the prior event so there were no deployments in this event. The EDR indicated a negative sign notation roll rate in the crash pulse data indicated the vehicle rolled in a counterclockwise (right to left) rotation.

Record 3 was a deployment level right side impact occurring 0.55 seconds after the prior event during which the front right occupant's seat-mounted side impact air bag deployed at 0 ms. According to the vehicle owner's manual, the seat-mounted side air bags were designed to deploy on the side of the vehicle that is struck. Given those parameters, there was no evidence to suggest the driver's seat-mounted side impact air bag should have deployed. The EDR data suggested the vehicle's air bags deployed as intended by the manufacturer.

Interior Damage

The Chevrolet's interior sustained damage resulting from impact forces, air bag deployments and occupant contacts. Both doors were jammed shut and the driver's side door was later forced open. The windshield was fractured, the roof glass was displaced, the backlight and right front glazing was disintegrated. Five air bags deployed and two seat belt pretensioners actuated.

Both seat belts revealed evidence of occupant contact. Both rows of the interior were reduced by vertical and lateral intrusion. The front row was reduced by intrusion in order of the magnitude as follows: middle roof 9 cm (3.5 in.), middle windshield header 5 cm (2.0 in.), left roof side rail 3 cm (1.2 in.). The front row was reduced by vertical intrusion as follows: left front door/rear upper quadrant 3 cm (1.2 in.). The second row was reduced by vertical intrusion as follows: left roof 19 cm (7.5 in.) and left backlight header 7 cm (3.1 in.). The second row was reduced by lateral intrusion of the left side panel rear of B-pillar 20 cm (7.8 in.).

Manual Restraint Systems

The front row was equipped with driver and front right passenger lap and shoulder seat belts. The driver's belt was equipped with continuous loop belt webbing, a sliding latch plate, emergency locking retractor, and a non-adjustable D-ring. The front right occupant's belt was configured similarly with the addition of a switchable ELR/automatic locking retractor. The front row belts were equipped with retractor-mounted seat belt pretensioners which were configured to actuate during moderate-to-severe front, side and rear crashes, as well as rollover crashes. Both front row belts were commanded to actuate at 58 ms of the Event 1 impact.

Both belt components including the webbing and latch plates revealed evidence of historical usage. The driver was belted at the time of the crash. The EDR report indicated the seat belt was buckled. The latch plate revealed evidence of loading on the plastic and the belt revealed scuff marks at 27 cm (10.6 in.) above the stop button.

The front right occupant was belted at the time of the crash. The seat belt was reported as being buckled in the EDR report. The latch plate revealed scuff marks on the plastic and the belt was scuffed at 12 cm (4.7 in.) above the stop button.

Supplemental Restraint Systems

The Chevrolet's supplemental restraint systems included a restraint control module, driver and front passenger frontal air bags, seat-mounted front row side impact air bags, and front and second row combination side impact/roll-sensing IC air bags. The owner of the vehicle stated the air bags were original and had never been serviced. According to the vehicle owner's manual, the seat-mounted side impact air bags are configured to deploy only on the side of the vehicle that is struck. Both IC air bags will deploy in the event of a severe frontal impact, an impact to either side of the vehicle or if the system senses a rollover situation.

In this crash, both frontal and IC air bags deployed during Event 1. The frontal air bags deployed

the 1st stage at 58 ms and the 2nd stage at 71 ms. The IC air bags deployed at 71 ms and the seat belt pretensioners actuated at 58 ms. The front right passenger's seat-mounted air bag deployed at 0 ms during Event 3 and the driver's seat-mounted side air bag did not deploy.

The driver's frontal air bag deployed from the steering wheel hub (**Figures 6 and 7**). The air bag measured 57 cm (22.4 in.) in diameter and was configured with vent ports and tethers. The air bag and cover flaps were unremarkable. The notification stated this air bag did not deploy. During the interview the owner clarified the



Figure 6. Driver's deployed frontal air bag, front panel, 2015 Chevrolet Camaro

statement to indicate the driver's frontal air bag deployed late in the crash sequence and not at the time of the frontal impact. The EDR report indicated this air bag deployed both stages in the 1st Event at times 58 ms and 71 ms, respectively. The investigation has revealed no evidence to indicate otherwise. The steering wheel and cover flaps revealed no evidence of occupant contact.

The passenger's frontal air bag deployed from the top instrument panel. The front panel measured 40 cm (15.7 in.) wide and 50 cm (19.7 in.) long. It was configured with vent ports. This air bag revealed a ragged hole in the front panel measuring 3 cm (1.2 in.) in diameter (**Figure 8**). The source of this damage was unknown. The center region of the front panel exhibited a few striation marks. It was otherwise unremarkable.

The left IC air bag deployed from the roof side rails above the front and second rows. It measured 160 cm (63.3 in.) in width and 44 cm (17.3 in.) in length. In its deflated state the lower edge hung 18 cm (7.0 in.) below the bottom edge of the side glass. This air bag was configured without tethers and the leading edge attached directly to the left A-pillar. It covered the front and rear side glass entirely. The inner side of the air bag revealed a few drops of blood in the area above the left door armrest. No damage was documented.



Figure 7. Driver's deployed frontal air bag, back panel, 2015 Chevrolet Camaro



Figure 8. Front right passenger's deployed frontal air bag, hole in front panel, 2015 Chevrolet Camaro

The right IC air bag deployed from the roof side rail above the front and second rows. It was configured similar to the left IC air bag and was unremarkable.

The right seat-mounted air bag deployed from the outer aspect of the front right passenger's seat back. It measured 50 cm (19.7 in.) long and 20 cm (7.9 in.) wide. This air bag revealed no evidence of contact or damage.

NHTSA Recalls and Investigations

A VIN search on safercar.gov revealed no recalls for the Chevrolet. A Year/Make/Model search on the website revealed one potential air-bag-related recall for certain vehicles as outlined in the table below. The recall indicated the seat-mounted side air bag modules may rupture during

Deployment.¹ The vehicle owner indicated no recall notices were sent regarding the air bags. It is unknown whether the Chevrolet involved in this crash was subject to the recall. No NHTSA investigations were found for this vehicle.

NHTSA Campaign Number	Components	Potential Number of Units Affected
15V666000	Air Bags	395

Rollover Mitigation

According to the website safercar.gov, the Chevrolet had a 5-star (out of a possible 5) safety rating for rollover crashes. The vehicle was determined to have an 8.70 percent rollover resistance, meaning it had a relatively low probability of rolling in a single-vehicle crash. It was configured with the following equipment designed to mitigate the chance of rollover: traction control, to limit wheel spin; electronic stability control (ESC), to assist with directional control in difficult driving conditions; tire pressure monitoring system, to help maintain recommended tire pressure; antilock brake system to improve vehicle stability on hard stops; and brake assist, to assist the driver in stopping the vehicle in emergency driving conditions. In this crash, the driver was operating at an EDR-reported pre-crash speed of 199 km/h (134 mph). The driver began braking, likely engaging the vehicle's traction control, ESC and brake assist. The vehicle initiated a clockwise vaw and departed the roadway, which launched the vehicle into an airborne trajectory over a steep, descending embankment. The vehicle's front plane struck the ground causing a trip-over type rollover left-side-leading along its horizontal axis. The dynamics of the free-falling trajectory and non-horizontal impact superseded the rollover mitigation technology on this vehicle because it was not tracking. The vehicle continued to roll down the embankment impacting the concrete culvert and fence in its roll path. Following four quarter-turns the vehicle came to rest in an upright orientation on level ground. Scene evidence indicated a probable minimal roll distance of 15 m (49 ft).

¹ In the event of a crash necessitating deployment of one or both of the side impact air bags, the air bag's inflator may rupture and the air bag may not properly inflate. The rupture could cause metal fragments to strike the vehicle occupants, potentially resulting in serious injury or death. Additionally, if the air bag does not properly inflate, the driver or passenger is at an increased risk of injury.

2015 CHEVROLET CAMARO OCCUPANTS

Driver Demographics	
Age/Sex:	20 years/male
Height:	178 cm (70 in.)
Weight:	73 kg (160 lb)
Eyewear:	None
Seat type:	Bucket
Seat track position:	Middle-rearward
Manual restraint usage:	Lap and shoulder seat belt
Usage source:	Vehicle inspection, EDR report
Air Bags:	Frontal and IC air bags deployed, seat-mounted side impact air bag did not deploy
Alcohol/drug data:	None
Egress from vehicle:	Removed from vehicle while unconscious
Transport from scene:	Ambulance to hospital
Type of medical treatment:	Admitted, removed from life support systems, and declared
	deceased 4 days later

Driver Injuries

Inj. No.	Injury	AIS 2015	Involved Physical Component (IPC)	IPC Confidence Level
1	Brain swelling, cerebrum, obliterated basal cisterns with herniation	140666.5	Tandem IPC Roof - Roof or convertible top	Possible
2	Subdural hematoma, left cerebrum, 5 mm thickness	140656.5	Tandem IPC Roof - Roof or convertible top	Possible
3	Right basilar fracture, skull, extending through the right mastoid, extending through the roof and floor of right sphenoid sinus, comminuted extending from temporal to parietal	150206.4	Tandem IPC Roof - Roof or convertible top	Possible
4	Contusion, right temporal cerebrum NFS	140602.3	Tandem IPC Roof - Roof or convertible top	Possible

Inj. No.	Injury	AIS 2015	Involved Physical Component (IPC)	IPC Confidence Level
5	LOC; coma greater than 6 hours	161009.3	Tandem IPC Roof - Roof or convertible top	Possible
5	LOC; coma greater than 6 hours	161009.3	Tandem IPC Roof - Roof or convertible top	Possible
6	Contusions, bilateral lungs, scattered (multifocal)	441411.3	Tandem IPC Interior – Shoulder portion of belt restraint	Possible
7	Fracture, nasal septum	251006.2	Tandem IPC Left Air Bag - Steering wheel hub	Possible
8	pneumomediastinum	442209.2	Tandem IPC Interior – Shoulder portion of belt restraint	Possible
9 10	bilateral pneumothoraces	442202.2 442202.2	Tandem IPC Interior – Shoulder portion of belt restraint	Possible
11	Laceration, right posterior scalp	110602.1	Roof	Probable
12	Fracture, nasal bone	251000.1	Steering wheel	Probable
13	Abrasions, face	210202.1	Frontal air bag	Probable
14	Contusion, right eye	210402.1	Frontal air bag	Probable

Source: EMS report, police report

Driver Kinematics

The belted 20-year-old male driver was seated in an upright posture and operating the vehicle at high speeds exceeding 161 km/h (100 mph). The Chevrolet departed its original lane, initiated a clockwise yaw, and departed the roadway on the right edge while the driver steered and applied braking. After departing the roadway, the vehicle momentarily became airborne above a steep descending embankment prior to its front end striking the embankment in a frontal configuration. At impact, the driver was displaced sharply forward and left in response to the 340 degree PDOF. He loaded and stretched the actuated seat belt with his chest and possibly loaded the deployed frontal air bag with his chest, face and head. Abrasions to the face and a contusion to the right eye suggested possible contact with the air bag. The driver's face, head and chest continued to be displaced forward past the deployed frontal air bag possibly contacting the steering wheel and causing a fracture to the nasal bone and septum, a contusion to the right eye, contusions to the bilateral lungs, bilateral pneumothoraces and a pneumomediastinum.

The vehicle initiated a left-side-leading rollover and during the second quarter-turn the Chevrolet's roof contacted the ground, causing vertical intrusion and reducing the front row space. The driver was displaced toward the roof and his head possibly contacted the roof and left roof side rail, causing more severe injuries including brain swelling, subdural hematoma, complex and comminuted basal skull fractures, contusions of the cerebrum, and prolonged loss of consciousness. During the rollover, the vehicle's right plane struck a concrete culvert at the base of the embankment and the driver was displaced to the right, loading his seat back and the center console. The vehicle struck a fence, which yielded, and then completed a four-quarter turn rollover, coming to rest in upright on level ground.

Following the crash, the driver was unconscious and not oriented to time and place. He was removed from the vehicle and transported by ambulance to a local hospital, where he was admitted. Doctors decided surgery would be futile and not beneficial given the driver's injury severity. He did not regain consciousness and following 4 days of treatment the driver was removed from life support systems and pronounced deceased.

Front Right Occupant Demographics

Age/Sex:	18 years/female
Height:	170 cm (67 in.)
Weight:	82 kg (180 lb)
Eyewear:	None
Seat type:	Bucket
Seat track position:	Middle-rearward
Manual restraint usage:	Lap and shoulder seat belt
Usage source:	Vehicle inspection, EDR report
Air bags:	Frontal air bag, seat-mounted side air bag, and IC air bag
	deployed

Alcohol/drug data:	Unknown
Egress from vehicle:	Exited vehicle with assistance
Transport from scene:	Ambulance to hospital
Type of medical treatment:	Treated and released


Front Right Occupant Injuries


According to the police report, the front right occupant complained of pain throughout her body. Her posterior scalp revealed an unspecified swollen area caused by an unknown source. There were no documented codeable injuries. SCI requested her medical records but the hospital declined to release them.

Front Right Occupant Kinematics

The belted 18-year-old female occupant was seated in an upright posture. The vehicle departed the roadway, traveled over the embankment, and struck the ground in a frontal configuration. At impact, the occupant was displaced sharply forward and left in response to the 340-degree PDOF. She loaded and stretched the actuated seat belt with her chest and possibly loaded the deployed frontal air bag with her chest, face, and head. The vehicle initiated a left side leading rollover and traveled down the embankment. The occupant was displaced to the left and then in all directions, and while remaining in her seated position she possibly loaded the deployed right IC air bag with her head and face. She sustained swelling to her posterior scalp. The vehicle's right plane struck a concrete culvert at the base of the embankment and the occupant was displaced to the right, likely loading her seat back and the deployed right seat-mounted side air bag with her flank and arm. The vehicle struck a fence, which yielded, and then completed a four-quarter turn rollover, coming to rest in an upright orientation on level ground while the occupant remained in her seated position. Following the crash, the occupant exited the vehicle with assistance from responders. She was transported by ambulance to a local hospital, where she was treated and released. The police report stated she complained of pain to her entire body.

CRASH DIAGRAMS





APPENDIX A: Event Data Recorder Report 2015 Chevrolet Camaro²

² The EDR Report contained in this technical report was imaged using the current version of the Bosch CDR software at the time of the vehicle inspection. The CDR report in the associated Crash Viewer application may differ relative to this report.





IMPORTANT NOTICE: Robert Bosch LLC and the manufacturers whose vehicles are accessible using the CDR System urge end users to use the latest production release of the Crash Data Retrieval system software when viewing, printing or exporting any retrieved data from within the CDR program. Using the latest version of the CDR software is the best way to ensure that retrieved data has been translated using the most current information provided by the manufacturers of the vehicles supported by this product.

CDR File Information

User Entered VIN	2G1FJ1EW8F9*****
User	
Case Number	
EDR Data Imaging Date	
Crash Date	
Filename	DS17013_V1_ACM.CDRX
Saved on	
Imaged with CDR version	Crash Data Retrieval Tool 17.4
Imaged with Software Licensed to (Company	Company Name information was removed when this file was saved without
Name)	VIN sequence number
Reported with CDR version	Crash Data Retrieval Tool 18.0.2
Reported with Software Licensed to (Company Name)	NHTSA
EDR Device Type	Airbag Control Module
Event(s) recovered	Deployment, Deployment, Deployment

Comments

No comments entered.

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events for Front, Side, and Rear (FSR) Events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH [8 km/h]. A Non-Deployment Event contains Pre-Crash and Crash data. The oldest Non-Deployment event can be overwritten by a Deployment Event, if all three records are full and the Non-Deployment Event is older than approximately 250 ignition cycles. Also, a Non-Deployment event can be recorded if one of the following occurs without the Deployment of any of the frontal air bags, side air bags, or roll bars:

-Pretensioner(s) only Deployment

-Head Rest Deployment

-Battery Cut-Off Deployment

The second type of SDM recorded crash event for FSR Events is the Deployment Event. It also contains Pre-Crash and Crash data. Deployment Events cannot be overwritten or cleared by the SDM.

Rollover Events contains Pre-Crash and Crash data. Rollover event follow the same rules as FSR Deployment events. The SDM can store up to three Events.

Data:

For FSR Events, SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment and Non-Deployment Events, the SDM will record up to 300 milliseconds of data after time zero. The SDM will also record up to 300 milliseconds of Vehicle Acceleration data after time zero. For Rollover Events, the SDM will acceleration, Vertical Acceleration, and Roll Rate data, if the SDM is rollover capable. This data reflects what the sensing system experienced during the recorded portion of the event. For Rollover Deployment Events, the SDM will record up to 700 milliseconds of data before the Deployment criteria is met and 290 milliseconds after the Deployment criteria is met.

-Deployment loops may be displayed as being deployed in a Non-Deployment event record, if a Deployment event is qualified during the Non-Deployment event. That is, if two or more events are occurring at the same time and one is a Non-Deployment event and one of the others is a Deployment event, and the Deployment event is qualified while the Non-Deployment is still active, the deployed loops may be recorded in the Non-Deployment event record.

-Time between events is recorded in 10 msec intervals and is displayed in seconds for a maximum time of 655.33 seconds. The counter measures the time from the start of one event to the start of the next event if both events occur within the same ignition cycle.

-The Maximum SDM Recorded Vehicle Velocity Change may occur between the recorded 10 millisecond sample points of





the SDM Recorded Vehicle Velocity Change.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following: -Significant changes in the tire's rolling radius

-Final drive axle ratio changes

-Wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously. The 0.5 second Pre-crash data value (most recent recorded data point) is the data point last sampled before Time Zero. That is to say, the last data point may have been captured just before Time Zero but no more than 0.5 second before Time Zero. All subsequent Pre-crash data values are referenced from this data point.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

-The SDM receives a message with an "invalid" flag from the module sending the pre-crash data

-Pre-Crash Electronic Data Validity Check Status indicates "Data Not Available" if:

-No data is received from the module sending the pre-crash data

-For diesel powered vehicles, the data displayed as Throttle Position (%) is actually the data for the Air Inlet Flap Position. This is not the same as the throttle position for a gasoline powered engines.

-Belt Switch Circuit Status indicates the status of the seat belt switch circuit.

-The ignition cycle counter will increment when the power mode cycles from OFF/Accessory to RUN. Applying and removing of battery power to the module will not increment the ignition cycle counter.

-Ignition Cycles Since DTCs Were Last Cleared can record a maximum value of 253 cycles and can only be reset by a scan tool.

-Dynamic Deployment Event Counter tracks the number of Deployment events that have occurred during the SDM's lifetime.

-Dynamic Event Counter tracks the number of qualified events (either Deployments, Non-deploy, or Rollover events) that have occurred during the SDM's lifetime.


-For Deployment Events, DTC B0052 (Deployment commanded) shall be recorded with the remainder of the data for this event even though it occurred after Event Enable.

-Once a firing loop has been commanded to be deployed, it will not be commanded to be deployed again during the same ignition cycle. Firing loop times for subsequent deployment type events, during the same ignition cycle, will record the deployment times as N/A.

-A Concurrent Event is when two events are happening nearly simultaneously. The "Concurrent Event Flag Set" parameter will indicate "Yes" if one event begins, but before that event is qualified, another event begins and is qualified. A Non-Deployment event typically becomes qualified if that event exceeds the 5 MPH (8 km/h) delta V recording threshold and the event has concluded. A deployment event (FSR or Rollover) becomes qualified when a deployment has been commanded for that event.

Example of a Concurrent Event:

A Non-Deployment event begins. Before the Non-Deployment event is qualified, a Rollover Deployment event begins and is qualified. Sometime after the Rollover event is qualified, the Non-Deployment event is qualified. The Rollover event will be recorded in the first open record even though the Non-Deployment event enabled before the Rollover event. The Non-Deployment event will be recorded in the next open record. The "Concurrent Event Flag Set" parameter will indicate "Yes" for the Non-Deployment event. The "Time Between Events" parameter will indicate the time from the start of the Rollover event.







Event record Type = Rollover	Non-deployment
Concurrent Event Flag = No	Concurrent Event Flag = Yes
Time Between Events = N/A	Time Between Events = XX seconds

-The GM parameter name is displayed in parentheses after the NHTSA Part 563 parameter name.

-The reported range of the longitudinal and lateral acceleration values is approximately ± 50 g.

-All data should be examined in conjunction with other available physical evidence from the vehicle and scene.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following: -Vehicle Status Data (Pre-Crash) is transmitted by the Body Control Module, via the vehicle's communication network. -The Belt Switch Circuit is wired directly to the SDM.

Data Element Sign Convention:

The following table provides an explanation of the sign notation for data elements that may be included in this CDR report. Directional references to sign notation are all from the perspective of the driver when seated in the vehicle facing the direction of forward vehicle travel.

Data Element Name	Positive Sign Notation Indicates
Longitudinal Acceleration	Forward
Longitudinal Velocity Change	Forward
Lateral Acceleration	Left to Right
Lateral Velocity Change	Left to Right
Vertical Acceleration	Downward
Roll Rate	Clockwise Rotation

Hexadecimal Data:

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR tool.

01043 SDM10P-conti r015



System Status at Time of Retrieval

Dynamic Deployment Event Counter	3
Multi-Event, Number of Events (Dynamic Event Counter)	3
Dynamic OnStar Notification Event Counter	3
Vehicle Identification Number (VIN)	2G1FJ1EW8F9*****
Ignition Cycle, Download (Ignition Cycles at Investigation)	5881
End Model Part Number	00CF6757
System Type	Continental
Software Module Identifier 1	00CF6754
Software Module Identifier 2	015E810B
Software Module Identifier 3	00CF2D8A
Manufacturing Traceability Data, Component Identifier	AS
Manufacturing Traceability Data, Part Number/Broadcast Code	2407
Manufacturing Traceability Data, Supplier Code	Т
Manufacturing Traceability Data, Traceability Number	151373039
ESS # 1 Traceability Data, Component Identifier	AU
ESS # 1 Traceability Data, Part Number/Broadcast Code	2341
ESS # 1 Traceability Data, Supplier Code	Т
ESS # 1 Traceability Data, Traceability Number	6JJ5TQF8N
ESS # 2 Traceability Data, Component Identifier	AT
ESS # 2 Traceability Data, Part Number/Broadcast Code	2341
ESS # 2 Traceability Data, Supplier Code	Т
ESS # 2 Traceability Data, Traceability Number	MLR2LQN8N
ESS # 3 Traceability Data, Component Identifier	AH
ESS # 3 Traceability Data, Part Number/Broadcast Code	2340
ESS # 3 Traceability Data, Supplier Code	Т
ESS # 3 Traceability Data, Traceability Number	8G07EI38L
ESS # 4 Traceability Data, Component Identifier	AJ
ESS # 4 Traceability Data, Part Number/Broadcast Code	2340
ESS # 4 Traceability Data, Supplier Code	Т
ESS # 4 Traceability Data, Traceability Number	8GM32A38L
ESS # 5 Traceability Data, Component Identifier	00
ESS # 5 Traceability Data, Part Number/Broadcast Code	0000
ESS # 5 Traceability Data, Supplier Code	Т
ESS # 5 Traceability Data, Traceability Number	00000000
ESS # 6 Traceability Data, Component Identifier	00
ESS # 6 Traceability Data, Part Number/Broadcast Code	0000
ESS # 6 Traceability Data, Supplier Code	Т
ESS # 6 Traceability Data, Traceability Number	00000000
ESS # 7 Traceability Data, Component Identifier	00
ESS # 7 Traceability Data, Part Number/Broadcast Code	0000
ESS # 7 Traceability Data, Supplier Code	T
ESS # 7 Traceability Data, Traceability Number	00000000
ESS # 8 Traceability Data, Component Identifier	00
ESS # 8 Traceability Data, Part Number/Broadcast Code	0000
ESS # 8 Traceability Data, Supplier Code	T
ESS # 8 Traceability Data, Traceability Number	00000000



System Status at Event (Event Record 1)

Event Record Type	Deployment
OnStar Deployment Status Data Sent	Yes
Complete file recorded (Event Recording Complete)	Yes
Crash Record Locked	Yes
OnStar SDM Recorded Vehicle Velocity Change Data Sent	Yes
Deployment Event Counter	1
Multi-Event, Number of Events (Event Counter)	1
OnStar Notification Event Counter	1
Time From Event 1 to 2 (Time Between Events) (seconds)	Data Not Available
Ignition Cycle, Crash (Ignition Cycles at Event)	5848
Algorithm Active: Frontal	Yes
Algorithm Active: Side	Yes
Algorithm Active: Rollover	No
Algorithm Active: Rear	Yes
Concurrent Event Flag Set	No
Event Severity Status: Frontal Pretensioner	Yes
Event Severity Status: Frontal Stage 1	Yes
Event Severity Status: Frontal Stage 2	Yes
Event Severity Status: Left Side	No
Event Severity Status: Right Side	No
Event Severity Status: Rear	No
Event Severity Status: Rollover	No
Safety Belt Status, Driver (Driver Belt Switch Circuit Status)	Buckled
Safety Belt Status, Right Front Passenger (Passenger Belt Switch Circuit Status)	Buckled
Center Front Row Belt Switch Circuit Status (If Equipped)	Data Not Available
Left Row 3 Belt Switch Circuit Status (If Equipped)	Data Not Available
Center Row 3 Belt Switch Circuit Status (If Equipped)	Data Not Available
Right Row 3 Belt Switch Circuit Status (If Equipped)	Data Not Available
Seat Track Position Switch, Foremost, Status, Driver (Driver Seat Position Status)	No (Rearward)
Passenger Seat Occupancy Status	Occupied
Occupant Size Right Front Passenger Child (Passenger Classification Status)	No (Small Adult)
Passenger Air Bag ON Indicator Status	On
Passenger Air Bag OFF Indicator Status	Off
Low Tire Pressure Warning Lamp Status 0.5 Seconds Prior to Time Zero	Off
Frontal Air Bag Warning Lamp (SIR Warning Lamp Status 0.5 Seconds Prior to Time	0
Zero)	Off
SIR Warning Lamp ON/OFF Time Continuously (seconds)	655330
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	5848
Ignition Cycles Since DTCs Were Last Cleared 0.5 Seconds Prior to Time Zero	216
Maximum Delta-V, Longitudinal (Maximum Longitudinal SDM Recorded Vehicle	210
Velocity Change for FSR Event) MPH [km/h]	-27 [-44]
Time, Maximum Delta-V (Time From FSR Time Zero to Maximum Longitudinal SDM Recorded Vehicle Velocity Change)(msec)	196
Maximum Delta-V, Lateral (Maximum Lateral SDM Recorded Vehicle Velocity Change for FSR Event) MPH [km/h]	7 [11]
Time Maximum Delta-V, Lateral (Time From FSR Time Zero to Maximum Lateral SDM Recorded Vehicle Velocity Change)(msec)	128





DTCs Present at Time of Event (Event Record 1) B0052-00




Event Data (Event Record 1)


Driver 1st Stage Deployment Loop Commanded	Yes
Passenger 1st Stage Deployment Loop Commanded	Yes
Driver 2nd Stage Deployment Loop Commanded	Yes
Passenger 2nd Stage Deployment Loop Commanded	Yes
Driver Pretensioner Deployment Loop #1 Commanded	Yes
Passenger Pretensioner Deployment Loop #1 Commanded	Yes
Driver Thorax Loop Commanded	No
Passenger Thorax Loop Commanded	No
Left Row 1 Roof Rail/Head Curtain Loop Commanded	Yes
Right Row 1 Roof Rail/Head Curtain Loop Commanded	Yes
Frontal Air Bag Deployment, Time to 1st Stage Deployment, Driver (Driver 1st Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	58
Frontal Air Bag Deployment, Time to 2nd Stage, Driver (Driver 2nd Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	71
Frontal Air Bag Deployment, Time to 1st Stage Deployment, Right Front Passenger	
(Passenger 1st Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	58
Frontal Air Bag Deployment, Time to 2nd Stage, Right Front Passenger (Passenger 2nd Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	71
Side air bag deployment, time to deploy, driver (Driver Thorax/Curtain Time From Time Zero to Deployment Command Criteria Met) (msec)	71
Side air bag deployment, time to deploy, right front passenger (Passenger Thorax/Curtain Time From Time Zero to Deployment Command Criteria Met) (msec)	71
Pretensioner Deployment, Time to Fire, Driver (Driver Pretensioner Time From Time Zero to Deployment Loop #1 or Loop #2 Command Criteria Met) (msec)	58
Pretensioner Deployment, Time to Fire, Right Front Passenger (Passenger Pretensioner Time From Time Zero to Deployment Loop #1 or Loop #2 Command Criteria Met) (msec)	58





Longitudinal Crash Pulse (Event Record 1)









Longitudinal Crash Pulse (Event Record 1)

Delta-V, Longitudinal Time (SDM Recorded Vehicle Longitudinal (msec) Velocity Change for FSR Event) (MPH)		Delta-V, Longitudinal (SDM Recorded Vehicle Longitudina Velocity Change for FSR Event) (km/h)		
10	-0.6	-1.0		
20	-0.6	-1.0		
30	-2.5	-4.0		
40	-3.7	-6.0		
50	-5.6	-9.0		
60	-8.1	-13.0		
70	-11.2	-18.0		
80	-12.4	-20.0		
90	-14.3	-23.0		
100	-16.8	-27.0		
110	-18.0	-29.0		
120	-21.1	-34.0		
130	-23.0	-37.0		
140	-24.2	-39.0		
150	-25.5	-41.0		
160	-25.5	-41.0		
170	-26.1	-42.0		
180	-26.7	-43.0		
190	-26.7	-43.0		
200	-27.3	-44.0		
210	-27.3	-44.0		
220	-27.3	-44.0		
230	-27.3	-44.0		
240	-27.3	-44.0		
250	-27.3	-44.0		
260	-27.3	-44.0		
270	-27.3	-44.0		
280	-27.3	-44.0		
290	-27.3	-44.0		
300	-27.3	-44.0		






Longitudinal Crash Pulse (Event Record 1)


Time (msec)	UCINAL CRASH PUISE Longitudinal Acceleration (SDM Recorded Vehicle Longitudinal Acceleration for FSR Event) (g)	Time (msec)	Longitudinal Acceleration (SDM Recorded Vehicle Longitudinal Acceleration for FSR Event) (g)	Time (msec)	Longitudinal Acceleration (SDM Recorded Vehicle Longitudinal Acceleration for FSR Event) (g)
2	-4.2	102	-18.2	202	-0.2
4	-2.2	104	-5.0	204	-0.2
6	-1.0	106	-11.0	206	-0.2
8	-2.2	108	3.0	208	-0.2
10	-0.2	110	-1.0	210	-2.2
12	-9.0	112	-10.2	212	-0.2
14	-1.0	114	-15.0	214	-0.2
16	-0.2	116	-14.2	216	-1.0
18	1.8	118	-14.2	218	-0.2
20	7.0	120	-10.2	220	-1.0
22	3.8	122	-10.2	222	-0.2
24 26	-8.2	124	-11.0	224	-0.2
20	-9.0 -17.0	126 128	-4.2 -7.0	226 228	-0.2
30	-17.0	120	-7.0 -6.2	220	-0.2
30	-0.2	130	-0.2	230	-0.2
34	1.8	132	-5.0	232	-0.2
36	1.0	134	-9.0	234	-0.2
38	-14.2	138	-8.2	238	-0.2
40	-17.0	140	-8.2	240	-0.2
42	-0.2	142	-7.0	242	-0.2
44	-1.0	144	-6.2	244	-0.2
46	-0.2	146	-10.2	246	-0.2
48	-17.0	148	-4.2	248	-0.2
50	-16.2	150	-5.0	250	-0.2
52	-15.0	152	-2.2	252	-0.2
54	-8.2	154	7.0	254	-0.2
56	-15.0	156	5.0	256	-0.2
58	-10.2	158	-4.2	258	-0.2
60	-8.2	160	-3.0	260	-0.2
62	-17.0	162	-2.2	262	-0.2
64	-20.2	164	-2.2	264	-0.2
66	-10.2	166	-2.2	266	-0.2
68 70	-15.0 -0.2	168 170	-2.2 -1.0	268 270	-0.2
70	-0.2	170	-1.0 -0.2	270	-0.2
72	-7.0	172	-0.2 -3.0	272	-0.2
74	-7.0	174	-5.0	274	-0.2
78	-6.2	178	-3.0	278	-0.2
80	-9.0	180	-3.0	280	-0.2
82	-8.2	182	-2.2	282	-0.2
84	-6.2	184	-2.2	284	-0.2
86	-9.0	186	-0.2	286	-0.2
88	-9.0	188	-0.2	288	-0.2
90	-12.2	190	-0.2	290	-0.2
92	-13.0	192	-1.0	292	-0.2
94	-4.2	194	-0.2	294	-0.2
96	-5.0	196	-2.2	296	-0.2
98	-4.2	198	-1.0	298	-0.2
100	-22.2	200	-0.2	300	-0.2





Lateral Crash Pulse (Event Record 1)







Lateral Crash Pulse (Event Record 1)

Time (msec)	Delta-V, Lateral (SDM Recorded Vehicle Lateral Velocity Change for FSR Event) (MPH)	Delta-V, Lateral (SDM Recorded Vehicle Lateral Velocity Change for FSR Event) (km/h)		
10	0.0	0.0		
20	0.0	0.0		
30	0.6	1.0		
40	2.5	4.0		
50	3.1	5.0		
60	2.5	4.0		
70	3.7	6.0		
80	3.7	6.0		
90	3.7	6.0		
100	4.3	7.0		
110	5.6	9.0		
120	6.2	10.0		
130	6.8	11.0		
140	6.8	11.0		
150	6.2	10.0		
160	6.8	11.0		
170	6.2	10.0		
180	6.2	10.0		
190	6.2	10.0		
200	6.2	10.0		
210	6.2	10.0		
220	6.8	11.0		
230	6.8	11.0		
240	6.8	11.0		
250	6.8	11.0		
260	6.8	11.0		
270	6.8	11.0		
280	6.8	11.0		
290	6.8	11.0		
300	6.8	11.0		





Lateral Crash Pulse (Event Record 1)

Time	Lateral Acceleration	Time	Lateral Acceleration	Time	Lateral Acceleration
(msec)	(SDM Recorded Vehicle	(msec)	(SDM Recorded Vehicle	(msec)	(SDM Recorded Vehicle
	Lateral Acceleration for		Lateral Acceleration for		Lateral Acceleration for
	FSR Event) (g)		FSR Event) (g)		FSR Event) (g)
2	-0.2	102	3.0	202	-0.2
4	-0.2	104	9.0	204	1.8
6	-1.0	106	1.8	206	-0.2
8	1.0	108	3.8	208	-0.2
10	3.0	110	1.8	210	-0.2
12	5.0	112	1.0	212	3.0
14	7.8	114	-0.2	214	-0.2
16	-3.0	116	7.0	216	1.0
18	-3.0	118	1.8	218	-0.2
20	-2.2	120	3.0	220	1.0
22	3.0	122	-3.0	222	-0.2
24	3.8	124	3.0	224	-0.2
26	-0.2	126	-0.2	226	-0.2
28	9.8	128	3.0	228	-0.2
30	-6.2	130	9.8	230	-0.2
32	7.8	132	-1.0	232	-0.2
34	-0.2	134	-0.2	234	-0.2
36	-1.0	136	3.0	236	-0.2
38	17.8	138	-0.2	238	-0.2
40	9.8	140	-2.2	240	-0.2
42	1.0	142	-4.2	242	1.0
44	-2.2	144	-2.2	244	-0.2
46	-2.2	146	3.0	246	-0.2
48	7.0	148	-3.0	248	-0.2
50	9.8	150	-0.2	250	-0.2
52	-4.2	152	-1.0	252	-0.2
54	-0.2	154	-0.2	254	-0.2
56 58	-0.2	156	-6.2	256	-0.2
50 60	-0.2	158	-0.2	258	
60	<u> </u>	160 162	-0.2	260 262	-1.0 -0.2
64	7.8	162	-0.2	262	-0.2
66	-3.0	166	-2.2	266	-0.2
68	3.0	168	-3.0	268	-0.2
70	1.0	170	-3.0	200	-0.2
70	-3.0	170	1.8	270	-0.2
74	-2.2	172	-2.2	272	-0.2
76	9.8	176	-0.2	276	-0.2
78	7.0	178	-1.0	278	-0.2
80	-8.2	180	-1.0	280	-0.2
82	-3.0	182	-3.0	282	-0.2
84	5.8	184	-0.2	284	-0.2
86	-0.2	186	-1.0	286	-0.2
88	3.8	188	-0.2	288	-0.2
90	-0.2	190	1.0	290	-0.2
92	1.0	192	-0.2	292	-0.2
94	-2.2	194	1.0	294	-0.2
96	7.0	196	-2.2	296	-0.2
98	5.8	198	3.0	298	-0.2
100	-0.2	200	-0.2	300	-0.2





Rollover Crash Pulse (Event Record 1) SDM Recorded Vehicle Roll Rate

Contains No Recorded Data

Rollover Crash Pulse (Event Record 1) Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for Rollover Event)

Contains No Recorded Data





Vertical Crash Pulse (Event Record 1) Normal Acceleration (SDM Recorded Vehicle Vertical Acceleration for Rollover Event)

Contains No Recorded Data



Times (sec)	Accelerator Pedal, % Full (Accelerator Pedal Position)	Service Brake (Brake Switch Circuit State)	Engine RPM (Engine Speed)	Engine Throttle, % Full (Throttle Position)	Speed, Vehicle Indicated (Vehicle Speed) (MPH [km/h])
-5.0	99	Off	5888	99	122 [196]
-4.5	99	Off	5888	99	124 [199]
-4.0	99	Off	6400	99	134 [215]
-3.5	0	Off	5824	23	123 [198]
-3.0	0	On	4736	19	100 [161]
-2.5	0	Off	3456	16	74 [119]
-2.0	0	On	2752	12	58 [93]
-1.5	0	On	2432	12	52 [84]
-1.0	0	Off	2304	12	49 [79]
-0.5	0	Off	1984	12	42 [67]

Pre-Crash Data -5.0 to -0.5 sec (Event Record 1)

Pre-Crash Data -2.0 to -0.5 sec (Event Record 1)

Times (sec)	Cruise Control Active	Cruise Control Resume Switch Active	Cruise Control Set Switch Active	Engine Torque (lb-ft [N-m])	Reduced Engine Power Mode Indicator
-2.0	No	No	No	-22 [-30]	Off
-1.5	No	No	No	-32 [-44]	Off
-1.0	No	No	No	-42 [-56]	Off
-0.5	No	No	No	-48 [-64]	Off



System Status at Event (Event Record 2)

Event Record Type	Deployment
OnStar Deployment Status Data Sent	No
Complete file recorded (Event Recording Complete)	Yes
Crash Record Locked	Yes
OnStar SDM Recorded Vehicle Velocity Change Data Sent	Yes
Deployment Event Counter	2
Multi-Event, Number of Events (Event Counter)	2
OnStar Notification Event Counter	2
Time From Event 1 to 2 (Time Between Events) (seconds)	0.11
Ignition Cycle, Crash (Ignition Cycles at Event)	5848
Algorithm Active: Frontal	No
Algorithm Active: Side	No
Algorithm Active: Rollover	Yes
Algorithm Active: Rear	No
Concurrent Event Flag Set	No
Event Severity Status: Frontal Pretensioner	No
Event Severity Status: Frontal Stage 1	No
Event Severity Status: Frontal Stage 2	No
Event Severity Status: Left Side	No
Event Severity Status: Right Side	No
Event Severity Status: Rear	No
Event Severity Status: Rollover	Yes
Safety Belt Status, Driver (Driver Belt Switch Circuit Status)	Buckled
Safety Belt Status, Right Front Passenger (Passenger Belt Switch Circuit Status)	Buckled
Center Front Row Belt Switch Circuit Status (If Equipped)	Data Not Available
Left Row 3 Belt Switch Circuit Status (If Equipped)	Data Not Available
Center Row 3 Belt Switch Circuit Status (If Equipped)	Data Not Available
Right Row 3 Belt Switch Circuit Status (If Equipped)	Data Not Available
Seat Track Position Switch, Foremost, Status, Driver (Driver Seat Position Status)	No (Rearward)
Passenger Seat Occupancy Status	Occupied
Occupant Size Right Front Passenger Child (Passenger Classification Status)	No (Small Adult)
Passenger Air Bag ON Indicator Status	On
Passenger Air Bag OFF Indicator Status	Off
Low Tire Pressure Warning Lamp Status 0.5 Seconds Prior to Time Zero	Off
Frontal Air Bag Warning Lamp (SIR Warning Lamp Status 0.5 Seconds Prior to Time	
Zero)	Off
SIR Warning Lamp ON/OFF Time Continuously (seconds)	655330
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	5848
Ignition Cycles Since DTCs Were Last Cleared 0.5 Seconds Prior to Time Zero	216
Maximum Delta-V, Longitudinal (Maximum Longitudinal SDM Recorded Vehicle	210
Velocity Change for FSR Event) MPH [km/h]	Data Not Available
Time, Maximum Delta-V (Time From FSR Time Zero to Maximum Longitudinal SDM Recorded Vehicle Velocity Change)(msec)	Data Not Available
Maximum Delta-V, Lateral (Maximum Lateral SDM Recorded Vehicle Velocity Change for FSR Event) MPH [km/h]	Data Not Available
Time Maximum Delta-V, Lateral (Time From FSR Time Zero to Maximum Lateral SDM Recorded Vehicle Velocity Change)(msec)	Data Not Available





DTCs Present at Time of Event (Event Record 2)

No Diagnostic Trouble Codes



Event Data (Event Record 2)

Driver 1st Stage Deployment Loop Commanded	No
Passenger 1st Stage Deployment Loop Commanded	No
Driver 2nd Stage Deployment Loop Commanded	No
Passenger 2nd Stage Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop #1 Commanded	No
Passenger Pretensioner Deployment Loop #1 Commanded	No
Driver Thorax Loop Commanded	No
Passenger Thorax Loop Commanded	No
Left Row 1 Roof Rail/Head Curtain Loop Commanded	No
Right Row 1 Roof Rail/Head Curtain Loop Commanded	No
Frontal Air Bag Deployment, Time to 1st Stage Deployment, Driver (Driver 1st Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Frontal Air Bag Deployment, Time to 2nd Stage, Driver (Driver 2nd Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Frontal Air Bag Deployment, Time to 1st Stage Deployment, Right Front Passenger	
(Passenger 1st Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Frontal Air Bag Deployment, Time to 2nd Stage, Right Front Passenger (Passenger 2nd Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Side air bag deployment, time to deploy, driver (Driver Thorax/Curtain Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Side air bag deployment, time to deploy, right front passenger (Passenger Thorax/Curtain Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Pretensioner Deployment, Time to Fire, Driver (Driver Pretensioner Time From Time Zero to Deployment Loop #1 or Loop #2 Command Criteria Met) (msec)	Data Not Available
Pretensioner Deployment, Time to Fire, Right Front Passenger (Passenger Pretensioner Time From Time Zero to Deployment Loop #1 or Loop #2 Command Criteria Met) (msec)	Data Not Available





Longitudinal Crash Pulse (Event Record 2) Delta-V, Longitudinal (SDM Recorded Vehicle Longitudinal Velocity Change for FSR Event)

Contains No Recorded Data

Longitudinal Crash Pulse (Event Record 2) Longitudinal Acceleration (SDM Recorded Vehicle Longitudinal Acceleration for FSR Event)

Contains No Recorded Data





Lateral Crash Pulse (Event Record 2) Delta-V, Lateral (SDM Recorded Vehicle Lateral Velocity Change for FSR Event)


Contains No Recorded Data

Lateral Crash Pulse (Event Record 2) Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for FSR Event)


Contains No Recorded Data







Rollover Crash Pulse (Event Record 2)







Rollover Crash Pulse (Event Record 2)

Time (msec)	SDM Recorded Vehicle Roll Rate (deg/sec)	Time (msec)	SDM Recorded Vehicle Roll Rate (deg/sec)
-700	-8	-200	-48
-690	-10	-190	
			-50
-680	-12	-180	-50
-670	-14	-170	-50
-660	-14	-160	-52
-650	-14	-150	-52
-640	-14	-140	-54
-630	-14	-130	-54
-620	-16	-120	-56
-610	-16	-110	-56
-600	-16	-100	-56
-590	-18	-90	-52
-580	-18	-80	-38
-570	-18	-70	-32
-560	-18	-60	-36
-550	-18	-50	-18
-540	-20	-40	-2
-530	-20	-30	-2
-520	-20	-20	-2
-510	-22	-10	-2
-500	-22	0	-22
-490	-24	10	-32
-480	-24	20	-38
-470	-24	30	-70
-460	-24	40	-100
-450	-26	50	-108
-440	-26	60	-138
-430	-28	70	-168
-420	-28	80	-180
-410	-28	90	-172
-400	-30	100	-164
-390	-30	110	-162
-380	-32	120	-166
			-100
-370	-32	130	
-360	-34	140	-182
-350	-34	150	-192
-340	-36	160	-200
-330	-36	170	-208
-320	-36	180	-216
-310	-38	190	-214
-300	-38	200	-206
-290	-40	210	-202
-280	-40	220	-202
-270	-42	230	-202
-260	-42	240	-204
-250	-44	250	-208
-240	-44	260	-210
-230	-46	270	-210
-220	-46	280	-210
-210	-46	290	-208






Rollover Crash Pulse (Event Record 2)

Time (msec)	Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for Rollover Event) (g)	Time (msec)	Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for Rollover Event) (g)
-700	0.1	-200	0.0
-690	0.1	-190	0.0
-680	0.0	-180	0.0
-670	0.1	-170	0.1
-660	0.1	-160	0.1
-650	0.1	-150	0.1
-640	0.1	-140	0.1
-630	0.1	-130	0.1
-620	0.1	-120	0.2
-610	0.1	-110	0.4
-600	0.1	-100	0.2
-590	0.1	-90	0.5
-580	0.1	-80	1.2
-570	0.1	-70	1.1
-560	0.1	-60	0.9
-550	0.1	-50	1.1
-540	0.1	-40	0.7
-530	0.1	-30	1.2
-520	0.1	-20	1.3
-510	0.1	-10	1.9
-500	0.1	0	1.9
-490	0.1	10	2.0
-480	0.1	20	1.4
-470	0.1	30	3.0
-460	0.0	40	0.9
-450	0.0	50	0.4
-440	0.0	60	-0.1
-430	0.0	70	-0.2
-420	0.0	80	0.1
-410	0.0	90	0.3
-400	0.0	100	0.4
-390	0.0	110	0.5
-380	0.0	120	0.5
-370	0.0	120	0.5
-360	0.0	140	0.3
-350	0.1	140	0.2
-340	0.1	160	-0.2
-330	0.1	100	-0.2
-320	0.1	170	-0.2
-320	0.1	190	-0.2
-300	0.0	200	-0.2
-290	0.0	200	-0.
-290		210	
	0.0		-0.2
-270	0.0	230	-0.2
-260	0.0	240	-0.2
-250	0.0	250	-0.2
-240	0.0	260	-0.2
-230	0.0	270	-0.1
-220	0.0	280	-0.1
-210	0.0	290	-0.1







Vertical Crash Pulse (Event Record 2)





Vertical Crash Pulse (Event Record 2)

Time (msec)	Normal Acceleration (SDM Recorded Vehicle Vertical Acceleration for Rollover Event) (g)	Time (msec)	Normal Acceleration (SDM Recorded Vehicle Vertical Acceleration for Rollover Event) (g)
-700	-1.0	-200	-1.3
-690			-1.3
	-1.0	-190	
-680 -670	-1.0 -1.1	-180 -170	-1.3 -1.3
-670	-1.1	-170	-1.3
-650	-1.1	-100	-1.3
-640	-1.1	-130	-1.3
-630	-1.1	-130	-1.3
-620	-1.1	-120	-1.3
-610	-1.1	-110	-1.3
-600	-1.1	-100	-0.5
-590	-1.1	-90	-0.6
-580	-1.1	-30	-0.0
-570	-1.1	-70	-0.1
-560	-1.1	-60	-0.3
-550	-1.2	-50	-0.2
-540	-1.2	-30	-0.3
-530	-1.2	-40	-0.3
-530	-1.2	-30	-0.3
-520	-1.2	-20	-0.4
-500	-1.2	-10	-0.7
-300	-1.2	10	-0.8
-490 -480	-1.2	20	-1.0 -0.7
-480	-1.2	30	-0.7
-470	-1.2	40	-0.8
-400	-1.2	40 50	-0.3
-440	-1.2	60	-0.9
-440	-1.2	70	-0.9
-420	-1.2	80	-1.0
-420	-1.2	90	-1.4
-400	-1.2	100	-1.7
-390	-1.2	110	-1.8
-380	-1.2	120	-1.6
-370	-1.2	130	-1.5
-360	-1.2	140	-1.4
-350	-1.2	150	-1.4
-340	-1.3	160	-1.5
-330	-1.3	170	-1.4
-320	-1.3	180	-1.4
-310	-1.3	190	-1.4
-300	-1.3	200	-1.5
-290	-1.3	210	-1.5
-280	-1.3	210	-1.4
-270	-1.3	230	-1.3
-260	-1.3	240	-1.2
-250	-1.3	250	-1.1
-240	-1.3	260	-1.1
-230	-1.3	270	-1.3
-220	-1.3	280	-1.3
-220	-1.3	200	-1.3



Times (sec)	Accelerator Pedal, % Full (Accelerator Pedal Position)	Service Brake (Brake Switch Circuit State)	Engine RPM (Engine Speed)	Engine Throttle, % Full (Throttle Position)	Speed, Vehicle Indicated (Vehicle Speed) (MPH [km/h])
-5.0	99	Off	5888	99	122 [196]
-4.5	99	Off	5888	99	124 [199]
-4.0	99	Off	6400	99	134 [215]
-3.5	0	Off	5824	23	123 [198]
-3.0	0	On	4736	19	100 [161]
-2.5	0	Off	3456	16	74 [119]
-2.0	0	On	2752	12	58 [93]
-1.5	0	On	2432	12	52 [84]
-1.0	0	Off	2304	12	49 [79]
-0.5	0	Off	1984	12	42 [67]

Pre-Crash Data -5.0 to -0.5 sec (Event Record 2)

Pre-Crash Data -2.0 to -0.5 sec (Event Record 2)

Times (sec)	Cruise Control Active	Cruise Control Resume Switch Active	Cruise Control Set Switch Active	Engine Torque (lb-ft [N-m])	Reduced Engine Power Mode Indicator
-2.0	No	No	No	-22 [-30]	Off
-1.5	No	No	No	-32 [-44]	Off
-1.0	No	No	No	-42 [-56]	Off
-0.5	No	No	No	-48 [-64]	Off



System Status at Event (Event Record 3)

Event Record Type	Deployment
OnStar Deployment Status Data Sent	No
Complete file recorded (Event Recording Complete)	Yes
Crash Record Locked	Yes
OnStar SDM Recorded Vehicle Velocity Change Data Sent	No
Deployment Event Counter	3
Multi-Event, Number of Events (Event Counter)	3
OnStar Notification Event Counter	3
Time From Event 1 to 2 (Time Between Events) (seconds)	0.55
Ignition Cycle, Crash (Ignition Cycles at Event)	5848
Algorithm Active: Frontal	Yes
Algorithm Active: Side	Yes
Algorithm Active: Rollover	No
Algorithm Active: Rear	Yes
Concurrent Event Flag Set	No
Event Severity Status: Frontal Pretensioner	No
Event Severity Status: Frontal Stage 1	No
Event Severity Status: Frontal Stage 2	No
Event Severity Status: Left Side	No
Event Severity Status: Right Side	Yes
Event Severity Status: Rear	Yes
Event Severity Status: Rollover	No
Safety Belt Status, Driver (Driver Belt Switch Circuit Status)	Buckled
Safety Belt Status, Right Front Passenger (Passenger Belt Switch Circuit Status)	Buckled
Center Front Row Belt Switch Circuit Status (If Equipped)	Data Not Available
Left Row 3 Belt Switch Circuit Status (If Equipped)	Data Not Available
Center Row 3 Belt Switch Circuit Status (If Equipped)	Data Not Available
Right Row 3 Belt Switch Circuit Status (If Equipped)	Data Not Available
Seat Track Position Switch, Foremost, Status, Driver (Driver Seat Position Status)	No (Rearward)
Passenger Seat Occupancy Status	Occupied
Occupant Size Right Front Passenger Child (Passenger Classification Status)	No (Small Adult)
Passenger Air Bag ON Indicator Status	On
Passenger Air Bag OFF Indicator Status	Off
Low Tire Pressure Warning Lamp Status 0.5 Seconds Prior to Time Zero	Off
Frontal Air Bag Warning Lamp (SIR Warning Lamp Status 0.5 Seconds Prior to Time Zero)	Off
SIR Warning Lamp ON/OFF Time Continuously (seconds)	655330
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	5848
Ignition Cycles Since DTCs Were Last Cleared 0.5 Seconds Prior to Time Zero	216
Maximum Delta-V, Longitudinal (Maximum Longitudinal SDM Recorded Vehicle	210
Velocity Change for FSR Event) MPH [km/h]	27 [44]
Time, Maximum Delta-V (Time From FSR Time Zero to Maximum Longitudinal SDM Recorded Vehicle Velocity Change)(msec)	278
Maximum Delta-V, Lateral (Maximum Lateral SDM Recorded Vehicle Velocity Change for FSR Event) MPH [km/h]	-20 [-32]
Time Maximum Delta-V, Lateral (Time From FSR Time Zero to Maximum Lateral SDM Recorded Vehicle Velocity Change)(msec)	196





DTCs Present at Time of Event (Event Record 3) B0052-00




Event Data (Event Record 3)


Driver 1st Stage Deployment Loop Commanded	No
Passenger 1st Stage Deployment Loop Commanded	No
Driver 2nd Stage Deployment Loop Commanded	No
Passenger 2nd Stage Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop #1 Commanded	No
Passenger Pretensioner Deployment Loop #1 Commanded	No
Driver Thorax Loop Commanded	No
Passenger Thorax Loop Commanded	Yes
Left Row 1 Roof Rail/Head Curtain Loop Commanded	No
Right Row 1 Roof Rail/Head Curtain Loop Commanded	No
Frontal Air Bag Deployment, Time to 1st Stage Deployment, Driver (Driver 1st Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Frontal Air Bag Deployment, Time to 2nd Stage, Driver (Driver 2nd Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Frontal Air Bag Deployment, Time to 1st Stage Deployment, Right Front Passenger (Passenger 1st Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Frontal Air Bag Deployment, Time to 2nd Stage, Right Front Passenger (Passenger 2nd Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Side air bag deployment, time to deploy, driver (Driver Thorax/Curtain Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Side air bag deployment, time to deploy, right front passenger (Passenger Thorax/Curtain Time From Time Zero to Deployment Command Criteria Met) (msec)	0
Pretensioner Deployment, Time to Fire, Driver (Driver Pretensioner Time From Time Zero to Deployment Loop #1 or Loop #2 Command Criteria Met) (msec)	Data Not Available
Pretensioner Deployment, Time to Fire, Right Front Passenger (Passenger Pretensioner Time From Time Zero to Deployment Loop #1 or Loop #2 Command Criteria Met) (msec)	Data Not Available





Longitudinal Crash Pulse (Event Record 3)









Longitudinal Crash Pulse (Event Record 3)

Time (msec)	Delta-V, Longitudinal (SDM Recorded Vehicle Longitudinal Velocity Change for FSR Event) (MPH)	Delta-V, Longitudinal (SDM Recorded Vehicle Longitudinal Velocity Change for FSR Event) (km/h)
10	1.2	2.0
20	5.6	9.0
30	8.1	13.0
40	10.6	17.0
50	14.3	23.0
60	15.5	25.0
70	18.0	29.0
80	18.6	30.0
90	20.5	33.0
100	21.7	35.0
110	21.7	35.0
120	23.0	37.0
130	23.0	37.0
140	23.6	38.0
150	23.0	37.0
160	23.6	38.0
170	23.6	38.0
180	23.6	38.0
190	24.2	39.0
200	24.2	39.0
210	24.9	40.0
220	25.5	41.0
230	25.5	41.0
240	26.1	42.0
250	26.1	42.0
260	26.7	43.0
270	26.7	43.0
280	27.3	44.0
290	27.3	44.0
300	27.3	44.0






Longitudinal Crash Pulse (Event Record 3)


Time (msec)	Longitudinal Acceleration (SDM Recorded Vehicle Longitudinal Acceleration for FSR	Time (msec)	Longitudinal Acceleration (SDM Recorded Vehicle Longitudinal Acceleration for FSR	Time (msec)	Longitudinal Acceleration (SDM Recorded Vehicle Longitudinal Acceleration for FSR
	Event) (g)	100	Event) (g)		Event) (g)
2	1.8	102	-0.2	202	1.8
4	1.0	104	-0.2	204	3.0
6 8	<u>5.0</u> 9.0	106 108	<u> </u>	206 208	<u> </u>
0 10	13.0	110	1.0	208	3.0
10	9.0	112	3.0	210	1.8
14	11.8	112	3.8	212	1.0
16	33.0	116	3.0	216	1.8
18	31.8	118	3.8	218	-0.2
20	5.0	120	3.0	220	-1.0
22	15.0	122	1.8	222	-1.0
24	15.8	124	1.0	224	-1.0
26	5.0	126	1.8	226	-0.2
28	7.0	128	-0.2	228	1.0
30	9.0	130	-0.2	230	1.8
32	-2.2	132	-0.2	232	1.0
34	-0.2	134	1.8	234	1.0
36	7.8	136	1.8	236	3.0
38	25.0	138	-0.2	238	1.8
40	33.8	140	-0.2	240	1.8
42	15.8	142	-0.2	242	1.0
44	11.8	144	-1.0	244	1.0
46	21.0	146	-0.2	246	1.0
48 50	<u> </u>	148 150	<u> </u>	248 250	<u> </u>
50	7.0	150	-1.0 -0.2	250	1.0
54	1.8	152	1.0	252	1.0
56	1.8	154	1.0	254	1.0
58	5.0	158	-0.2	258	-0.2
60	17.0	160	-0.2	260	-0.2
62	19.8	162	1.0	262	1.0
64	5.0	164	-0.2	264	-0.2
66	11.0	166	1.0	266	-0.2
68	5.0	168	-0.2	268	-0.2
70	7.8	170	-0.2	270	1.0
72	3.0	172	1.8	272	1.0
74	1.0	174	1.0	274	1.0
76	5.8	176	1.0	276	1.0
78	5.8	178	1.0	278	1.0
80	3.0	180	-0.2	280	1.8
82	9.0	182	1.0	282	1.0
84	7.0	184	1.0	284	-0.2
86	5.0	186	-0.2	286	1.0
88	9.8	188	-0.2	288	1.0
90 92	7.0	190	-0.2 -0.2	290	1.0
92 94	<u>5.8</u> 5.0	192 194	-0.2	292 294	<u> </u>
94 96	3.8	194	1.0	294	-0.2
90	3.0	198	1.0	290	-0.2
100	1.0	200	1.0	300	-0.2





Lateral Crash Pulse (Event Record 3)







Lateral Crash Pulse (Event Record 3)

Time (msec)	Delta-V, Lateral (SDM Recorded Vehicle Lateral Velocity Change for FSR Event) (MPH)	Delta-V, Lateral (SDM Recorded Vehicle Lateral Velocity Change for FSR Event) (km/h)
10	-3.7	-6.0
20	-4.3	-7.0
30	-8.1	-13.0
40	-11.8	-19.0
50	-16.8	-27.0
60	-16.8	-27.0
70	-17.4	-28.0
80	-18.0	-29.0
90	-18.6	-30.0
100	-18.0	-29.0
110	-18.6	-30.0
120	-19.3	-31.0
130	-19.3	-31.0
140	-18.6	-30.0
150	-18.6	-30.0
160	-19.3	-31.0
170	-19.3	-31.0
180	-19.3	-31.0
190	-19.3	-31.0
200	-19.3	-31.0
210	-19.3	-31.0
220	-19.3	-31.0
230	-18.6	-30.0
240	-18.0	-29.0
250	-18.6	-30.0
260	-18.6	-30.0
270	-18.6	-30.0
280	-18.6	-30.0
290	-18.6	-30.0
300	-18.6	-30.0





Lateral Crash Pulse (Event Record 3)

Time (msec)	I Crash Pulse (Evel Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for FSR Event) (g)	Time (msec)	Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for FSR Event) (g)	Time (msec)	Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for FSR Event) (g)
2	-25.0	102	1.8	202	3.0
4	-41.0	104	-0.2	204	1.0
6	-34.2	106	-2.2	206	-0.2
8	3.8	108	-4.2	208	1.0
10	21.8	110	-4.2	210	1.8
12	-30.2	112	-1.0	212	-0.2
14 16	-31.0	114	-0.2	214	-0.2
-	-8.2	116	-1.0 -2.2	216	-0.2
18	7.0	118 120		218	-0.2
20	37.8		-2.2	220	1.8
22 24	25.8	122 124	-1.0 -1.0	222	3.8
	-15.0			224	5.0
26	-35.0	126	-0.2	226	3.8
28 30	-17.0 -32.2	128 130	-0.2	228	1.0
30	-32.2	130	-0.2	230 232	-0.2 1.0
32	-37.0	132	<u> </u>	232	1.0
34	-30.2	134	3.0	234	-0.2
38		138	1.0	230	-0.2
40	-7.0 -9.0	130	-3.0	238	-1.0
40	-9.0	140	-3.0	240	-0.2
42	-27.0	142	3.0	242	-4.2
46	-21.0	144	1.0	244	-4.2
48	-24.2	148	-2.2	248	-2.2
50	-13.0	140	-2.2	240	-0.2
52	1.8	152	-0.2	252	-0.2
54	5.8	154	-0.2	254	-0.2
56	3.8	156	-2.2	256	1.0
58	-3.0	158	-2.2	258	-0.2
60	-13.0	160	-0.2	260	-0.2
62	-11.0	162	-0.2	262	-0.2
64	13.8	164	-0.2	264	-0.2
66	3.0	166	-1.0	266	-0.2
68	-5.0	168	-0.2	268	-0.2
70	-6.2	170	-0.2	270	1.0
72	-1.0	172	-1.0	272	1.0
74	3.8	174	-1.0	274	-0.2
76	-9.0	176	-0.2	276	-0.2
78	-5.0	178	-0.2	278	-0.2
80	-3.0	180	-0.2	280	1.0
82	-6.2	182	-0.2	282	1.0
84	-7.0	184	-0.2	284	-0.2
86	-3.0	186	1.0	286	-1.0
88	-3.0	188	1.0	288	-1.0
90	-0.2	190	-1.0	290	-0.2
92	3.0	192	-2.2	292	-0.2
94	-0.2	194	-0.2	294	-0.2
96	-0.2	196	-2.2	296	1.0
98	3.8	198	-4.2	298	-0.2
100	5.8	200	1.0	300	-1.0





Rollover Crash Pulse (Event Record 3) SDM Recorded Vehicle Roll Rate

Contains No Recorded Data

Rollover Crash Pulse (Event Record 3) Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for Rollover Event)

Contains No Recorded Data





Vertical Crash Pulse (Event Record 3) Normal Acceleration (SDM Recorded Vehicle Vertical Acceleration for Rollover Event)

Contains No Recorded Data



Times (sec)	Accelerator Pedal, % Full (Accelerator Pedal Position)	Service Brake (Brake Switch Circuit State)	Engine RPM (Engine Speed)	Engine Throttle, % Full (Throttle Position)	Speed, Vehicle Indicated (Vehicle Speed) (MPH [km/h])
-5.0	99	Off	5888	99	124 [199]
-4.5	99	Off	6400	99	134 [215]
-4.0	0	Off	5824	23	123 [198]
-3.5	0	On	4736	19	100 [161]
-3.0	0	Off	3456	16	74 [119]
-2.5	0	On	2752	12	58 [93]
-2.0	0	On	2432	12	52 [84]
-1.5	0	Off	2304	12	49 [79]
-1.0	0	Off	1984	12	42 [67]
-0.5	Data Not Available	Off	Data Not Available	25	Data Not Available

Pre-Crash Data -5.0 to -0.5 sec (Event Record 3)

Pre-Crash Data -2.0 to -0.5 sec (Event Record 3)

Times (sec)	Cruise Control Active	Cruise Control Resume Switch Active	Cruise Control Set Switch Active	Engine Torque (lb-ft [N-m])	Reduced Engine Power Mode Indicator
-2.0	No	No	No	-32 [-44]	Off
-1.5	No	No	No	-42 [-56]	Off
-1.0	No	No	No	-48 [-64]	Off
-0.5	No	No	No	Data Not Available	Off





Hexadecimal Data



00 CF 2D 8A

DID \$CB 00 CF 67 57

DID \$31

0430 7F <	0000 0010 0020 0030 0040 0050 0060 0070 0080 0090 0100 0110 0120 0130 0140 0150 0140 0150 0140 0150 0140 0190 0200 0210 0220 0220 0220 0220 022	$ \begin{array}{c} \text{A5 F0} \\ \text{F0} \\ \text{C0} \\ 0 \\ 0 \\ 0 \\ 4 \\ 8 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0$	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	$\begin{array}{c} 01 & 01\\ 0E & EB\\ 20 & 60\\ 00 & 63\\ 00C & 06\\ 0C & 06\\ 0C & 54\\ FF & FFF\\ FFF & FFF\\ FFF & FFF\\ 52 & 07\\ 47\\ 79 & 83\\ 58 & 8A\\ 53 & 8A\\ 53 & 8A\\ 53 & 8A\\ 55 & 84\\ 55 & 84\\ 55 & 84\\ 55 & 84\\ 55 & 84\\ 55 & 87\\ 70 & 88\\ 55 & 89\\ 55 &$	0000621051FFF53764653557975556766487660B38D8FFADFF	1000432660778FF2384699888877998828FF447887797787F27F	D0005BF318FFFAE2266335599EFFA5DBF26664EAAFFADFFFDF	F0001301CFFFF47888888788987877888777777877877877877877
	$\begin{array}{c} 0360\\ 0370\\ 0380\\ 0390\\ 0400\\ 0410\\ 0420\\ 0430\\ 0440\\ 0450\\ 0450\\ 0460\\ 0470\\ 0480\\ 0490 \end{array}$	78 7A 7A 7F 7F 82 7F 84 7F 7F 7F 7F	73 7F 7F 7D 7A 7A 7F 7F 7D 82 7F 7F 7F 7F	7A 7D 7F 7F 7D 87 7F 7F 7F 7F <tr td=""> 7F</tr>	78 7F 7D 7F 7F 7F 7F 7F 7F 7F FF	7D 82 7F 82 7F 7F 7F 7F 7F 7F 7F 7F	7A 7F 7F 7F 7F 7F 7F 7F 7F FF	78 7F 7F 7F 7F 7F 7F 7F 7F FF FF



DID \$32

0580 0590	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF
0600	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0610	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0620	FF	FF	FF	FF	FF	$\mathbf{F}\mathbf{F}$	$\mathbf{F}\mathbf{F}$	FF	FF	FF
0630	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0640	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0650 0660	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF
0670	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0680	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0690	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0700	FF	FF	FF	FF	FF	FF	FF	FF FF	FF FF	FF
0710 0720	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	rr FF	FF	FF FF
0730	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0740	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0750	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0760	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
0770 0780	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF 00	FF 00
0790	00	00	00	00	00	00	00	0B	00	0B
0800	00	00	7C	00	21	08	40	00	00	00
0810	00	19	05	00	00	00	00	2E	01	00
0820	00	00	00	00	07	00	5D	24	0D	8E
0830 0840	AA 0A	99 00	4D 06	01 F1	E6 06	21 FE	F8 FD	10 E6	03 04	FE FC
0850	07	01	FB	ED	ED	E3	F2	0A	0C	FD
0860	CF	FΕ	FD	FΒ	F8	27	19	19	04	FE
0870	FF	0D	30	1E	09	FA	15	4E	0B	3E
0880 0890	01 F2	06 3E	1F F7	10 03	1E FF	F0 11	02 FA	02 E2	09 03	10 00
0900	гZ FB	DF	09	13	сс 04	09	EC	50	FE	52
0910	02	04	16	5F	ÓВ	28	08	F3	F7	10
0920	04	F8	0C	0A	0в	03	07	F7	09	16
0930	F5	EB	1A	08	F4	06	27	36	0D	49 1 D
0940 0950	01 38	F8 1B	0F 15	47 0E	0C 22	3F OD	15 0D	02 1C	28 09	1B 0D
0960	24	29	2F	21	04	FE	20	1D	18	15
0970	1C	01	1E	1A	FΕ	20	ΕE	0C	ΟF	37
0980	28	3F	0A	F3	2E	51	0D	3C	09	F9
0990 1000	03 02	10 00	41 FA	14 0E	11 FE	12 FA	4F 0F	34 FA	EE FE	29 FA
1010	1C	FB	гд 11	0£	г <u>г</u> 17	0B	F2	27	FE	22
1020	2F	02	1C	0 D	00	21	16	18	0C	25
1030	1F	1C	1C	26	0 F	05	FA	21	FΒ	1D
1040	3A EE	37	25 FF	36 FF		26	16 FF			02
1050 1060	FF FF	FF FF	гг FF	гг FF	FF FF	FF FF	гг FF	FF FF	FF FF	FF FF
1070	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
1080	FF	FF	FF	FF	FF	$\mathbf{F}\mathbf{F}$	FF	FF	FF	FF
1090	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
1100 1110	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF
1120	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
1130	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
1140	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
1150 1160	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF
1170	гг FF	гг FF	гг FF	гг FF	гг FF	гг FF	гг FF	FF	FF	FF
1180	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
1190	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
1200	FF									







Page 43 of 46	ge 43 of 46	6
---------------	-------------	---

		- 0	~ ~	0.0	~ ~	~ ~	0.4	1.0		0.0	
0000	A5	D0	02	00	02	02	04	16	D8	00	
0010	0B	00	FF	FF	80	00	00	00	00	00	
0020 0030	5C 00	FC 00	FC 00	30 00	20 00	60 63	C0 63	40 63	00	00 10	
0030	00	00	00	00	00	03 1F	03 24	26	2B	10 36	
0040	4A	5B	64	5C	5C	06	24 1F	20	2b 2F	06	
0050	4A 48	об 06	63	0C	0C	00 0C	0C	10	2r 13	17	
0070	63	63	63	43	4F	54	5D	77	A1	с6	
0080	D7	C7	C4	00	FF	FD	16	D8	D8	FF	
0090	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0100	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0110	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0120	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0130	\mathbf{FF}	FF	$\mathbf{F}\mathbf{F}$	$\mathbf{F}\mathbf{F}$	$\mathbf{F}\mathbf{F}$	$\mathbf{F}\mathbf{F}$	$\mathbf{F}\mathbf{F}$	FF	FF	FF	
0140	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0150	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0160	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0170	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0180	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0190	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0200	FF	FF	FF	FF	FF	FF FF	FF FF	FF	FF	FF	
0210 0220	FF FF	FF FF	FF FF	FF FF	FF FF	FF	rr FF	FF FF	FF FF	FF FF	
0220	FF	FF	FF	FF	FF	FF	FF	FF	FF	гг FF	
0240	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0250	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0260	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0270	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0280	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0290	\mathbf{FF}	FF	$\mathbf{F}\mathbf{F}$	$\mathbf{F}\mathbf{F}$	$\mathbf{F}\mathbf{F}$	$\mathbf{F}\mathbf{F}$	$\mathbf{F}\mathbf{F}$	FF	FF	FF	
0300	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0310	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0320	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0330	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0340	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0350 0360	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF	
0370	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0380	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0390	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0400	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0410	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0420	$\mathbf{F}\mathbf{F}$	FF	$\mathbf{F}\mathbf{F}$	$\mathbf{F}\mathbf{F}$	$\mathbf{F}\mathbf{F}$	FF	$\mathbf{F}\mathbf{F}$	FF	FF	FF	
0430	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0440	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0450	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0460	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0470	FF FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0480 0490	гг 73	FF 7A	FF 7E	FF 73	FF 79	FF 7d	FF 73	FF 78	7B 7E	7E 72	
0500	78	7E	72	78	7E	72	78	7E	72	78	
0510	7E	72	77	7E	72	77	7E	72	77	7E	
0520	72	76	7E	72	76	7E	72	76	7E	72	
0530	76	7E	71	76	7E	71	75	7E	71	75	
0540	7E	71	75	7E	71	74	7E	71	74	7E	
0550	71	73	7E	71	73	7E	71	73	7E	71	
0560	73	7D	71	72	7D	71	72	7D	71	71	
0570	7D	71	71	7D	71	71	7D	71	70	7D	
0580	71	70	7D	71	6F	7D	71	6F	7D	71	
0590	6E	7E	71	6E	7E	71	6D	7E	70	6D	
0600	7E 70	70 6 P	6D 7 D	7E	70 6 P	6C	7D	70 67	6C 7D	7D 70	
0610 0620	70 6A	6B 7D	7D 70	70 69	6B 7D	7D 70	70 69	6A 7D	7D 70	70 68	
0630	7D	70	68	09 7D	70	68	09 7D	70	67	00 7D	
0000	עי	10	00	10	10	00	עו	10	07	10	





0000	A5	С0	03	00	03	03	0B	16	D8	00
0010	37	00	FF	FF	60	00	10	00	00	00
0020	5C	FC	FC	30	20	60	С0	40	FF	00
0030	00	00	00	00	00	00	63	63	01	44
0040	00	00	00	00	00	FF	1F	24	26	2в

D

BOSCH



0050	36 4	4A !	5в	64	5C	ΟF	FF	06	1F	06
0060 0070			48 63	19 FF	0C 43	0C 4F	0C 54	0C 5D	10 77	13 A1
0800	C6 I	D7 (C7	00	FF	FD	16	D8	D8	FF
0090 0100			FF FF							
0110 0120			FF FF	80 FF	52 FF	00 00	AB FF	8B FF	5F 81	62 79
0130	88 -	788	8C	72	90	6C	96	64	98	64
0140 0150			9D A4	62 60	A0 A5	61 61	A2 A4	62 61	A2 A5	61 60
0160 0170			A5 A8	60 61	A6 A9	60 62	A6 A9	60 61	A7 AA	60 61
0180	AA (61 <i>i</i>	AB	61	AB	61	AB	61	84	41
0190 0200			8C D2	2A 6B	96 CF	89 91	A0 8C	B6 DE	96 A5	34 C0
0210 0220			8C 93	28 7D	91 BE	55 6E	96 D4	2F 69	7a A7	23 3C
0230	9D 3	32 I	В4	4B	В1	43	8C	5F	91	84
0240 0250			84 9B	89 87	8C 8C	78 73	AA 93	5F 70	B1 87	64 7D
0260 0270			8E 8C	69 78	8E 98	73 78	87 91	78 7F	96 8E	70 87
0280	8C -	7F 8	89	7F	87	89	82	8E	7F	84
0290 0300			82 87	7A 7D	82 89	75 7a	84 87	75 7a	87 84	7D 7D
0310 0320			84 84	7F 87	7F 7F	7F 82	7F 7F	7F 78	7F 7F	89 7a
0330	7D 8	87 '	7F	82	84	7A	7D	7F	7F	7F
0340 0350			82 82	7A 7D	7F 7F	7A 7F	7F 7F	7F 7F	82 84	7F 7d
0360 0370			82 7F	7F 82	82 7F	7F 82	7F 7F	7F 7d	82 7F	7F 7A
0380	82 -	7F 8	84	7A	82	75	84	82	84	87
0390 0400			89 84	7F 7F	87 7F	82 7F	87 7D	84 84	84 7D	7F 89
0410 0420			7F 87	89 7F	82 84	82 7D	84 84	7F 7F	82 82	82 7A
0430	82 -	75 8	82	75	84	7A	84	7F	84	7F
0440 0450	7f (7 F '	82 7F	82 7F	7F 7F	7F 7F	7F 82	7F 82	82 82	7F 82
0460 0470			82 82	7F 7d	82 82	7F 7d	84 82	82 7F	82 82	82 7F
0480	82 -	7F (7F	82	7F	7F	7F	7D	FF	FF
0490 0500			FF FF							
0510 0520			FF FF							
0530 0540			FF FF							
0550	FF H	FF 1	FF							
0560 0570			FF FF							
0580 0590	FF H	FF 1	FF	FF FF	FF	FF	FF	FF	FF	FF
0600	FF H		FF FF	FF	FF FF	FF FF	FF FF	FF FF	FF FF	FF FF
0610 0620			FF FF							
0630	FF H	FF 1	FF FF							
0640 0650	FF H	FF 1	FF							
0660 0670			FF FF							
0680	FF H	FF 1	FF							
0690	FF H	FF 1	FF							

BOSCH







$\begin{array}{cccccccccccccccccccccccccccccccccccc$
1070 FF <
1120 FF <

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.

DOT HS 812 769 July 2019



U.S. Department of Transportation

National Highway Traffic Safety Administration



14347-072519-v2