



U.S. Department  
of Transportation

**National Highway  
Traffic Safety  
Administration**



---

DOT HS 812 534

June 2018

**Special Crash Investigations  
Non-Traffic Surveillance  
Remote Hyperthermia Fatality  
Investigation  
Vehicle: 2003 Mitsubishi  
Galant  
Location: South Carolina  
Incident Date: July 2014**

## DISCLAIMER

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof. The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration. The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points are coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

This report and associated case data are based on information available to the Special Crash Investigation team on the date this report was published.

### Suggested APA Format Citation:

Crash Research & Analysis, Inc. (2018, June). *Special crash investigations non-traffic surveillance remote hyperthermia fatality investigation; vehicle: 2003 Mitsubishi Galant; location: South Carolina; incident date: July 2014* (Report No. DOT HS 812 534). Washington, DC: National Highway Traffic Safety Administration.

## TECHNICAL REPORT STANDARD TITLE PAGE

<i>1. Report No.</i> DOT HS 812 534	<i>2. Government Accession No.</i>	<i>3. Recipient's Catalog No.</i>	
<i>4. Title and Subtitle</i> Special Crash Investigations Non-Traffic Surveillance Remote Hyperthermia Fatality Investigation Vehicle: 2003 Mitsubishi Galant Location: South Carolina Incident Date: July 2014		<i>5. Report Date:</i> June 2018	
		<i>6. Performing Organization Code</i>	
<i>7. Author</i> Crash Research & Analysis, Inc.		<i>8. Performing Organization Report No.</i> CR16036	
<i>9. Performing Organization Name and Address</i> Crash Research & Analysis, Inc. P.O. Box 302 Elma, NY 14059		<i>10. Work Unit No.</i>	
		<i>11. Contract or Grant No.</i> DTNH22-12-C-00269	
<i>12. Sponsoring Agency Name and Address</i> National Highway Traffic Safety Administration 1200 New Jersey Avenue SE. Washington, D.C. 20590		<i>13. Type of Report and Period Covered</i> Technical Report Incident Date: July 2014	
		<i>14. Sponsoring Agency Code</i>	
<i>15. Supplementary Note</i> An investigation of the circumstances surrounding the hyperthermia fatality of a 3-year-old child in a 2003 Mitsubishi Galant.			
<i>16. Abstract</i> The interest in this remote investigation involve the circumstances surrounding the hyperthermia-related fatality of a 3-year-old male who was found inside a 2003 Mitsubishi Galant that was parked on the lawn area of his home. The child exited the house while his parents were asleep during the midday hours. The child and a family dog entered the parked Mitsubishi. The police reported that the driver's door of the Mitsubishi would not stay open at its detent and would swing closed and latch. The child was found unconscious inside the parked vehicle by his mother approximately one hour after he exited the residence. The family called the emergency response system and immediately placed the child in cold water in the bathtub in an attempt to lower his body temperature. The responding Emergency Medical Service (EMS) requested helicopter transport to a regional pediatric trauma center where he expired due to complications of hyperthermia approximately 3.5 days after the incident.			
<i>17. Key Words</i> hyperthermia, rocker switch, door release lever, door detent		<i>18. Distribution Statement</i> This document is available to the public through the National Technical Information Service, www.ntis.gov.	
<i>19. Security Classif. (of this report)</i> Unclassified	<i>20. Security Classif. (of this page)</i> Unclassified	<i>21. No. of Pages</i> 23	<i>22. Price</i>

**TABLE OF CONTENTS**

BACKGROUND ..... 1

INCIDENT SITE ..... 2

2003 MITSUBISHI GALANT ..... 2

    Description ..... 2

    Glazing ..... 3

    Exterior Door Handles ..... 3

    Interior Door Release Levers ..... 3

    Door Locking System ..... 4

    Door Detent ..... 5

INCIDENT ..... 5

NON-MOTORIST DEMOGRAPHICS ..... 7

NON-MOTORIST INJURIES ..... 7

INCIDENT SITE DIAGRAM ..... 8

APPENDIX A: Non-Traffic Surveillance Forms ..... 1-1

**NON-TRAFFIC SURVEILLANCE  
SPECIAL CRASH INVESTIGATIONS  
CASE NO. CR16036  
REMOTE HYPERTHERMIA FATALITY INVESTIGATION  
VEHICLE: 2003 MITSUBISHI GALANT  
LOCATION: SOUTH CAROLINA  
INCIDENT DATE: JULY 2014**

***BACKGROUND***

The interest in this remote investigation involve the circumstances surrounding the hyperthermia-related fatality of a 3-year-old male who was found inside a 2003 Mitsubishi Galant (**Figure 1**) that was parked on the lawn area of his home.

The child exited the house while his parents were asleep during the midday hours. The child and a family dog entered the parked Mitsubishi. The police reported that the driver's door of the Mitsubishi would not stay open at its detent and would swing closed and latch. The child was found unconscious inside the parked vehicle by his mother approximately one hour after he

exited the residence. The family called the emergency response system and immediately placed the child in cold water in the bathtub in an attempt to lower his body temperature. The responding Emergency Medical Service (EMS) requested helicopter transport to a regional pediatric trauma center where he expired due to complications of hyperthermia approximately 3.5 days after the incident. The dog was found deceased inside the vehicle.



**Figure 1: Image of the 2003 Mitsubishi Galant on the lawn area of the incident. (Image obtained from the investigating police department.)**

The incident was identified by the National Highway Traffic Safety Administration and assigned to the Special Crash Investigations (SCI) group for further research in November 2016. This research was aimed to chronicle the circumstances of these types of incidents and provide direction to potential countermeasures. Approximately 700 children have died due to hyperthermia over a 19-year period (1998 to 2016) with 28 percent of these deaths attributed to children playing in unattended vehicles.<sup>1</sup>

The SCI team contacted the involved police agency and interviewed the investigating officer to obtain the circumstances of the incident. This interview, images of the Mitsubishi supplied by

---

<sup>1</sup> Null, J. (2016). Heatstroke Deaths of Children in Vehicles (Web page). San Jose, CA: Department of Meteorology and Climate Science, San Jose State University (2016), Retrieved from <http://noheatstroke.org>

the police, an exemplar vehicle inspection, supplemental internet research and medical data provide the basis for this remote SCI investigation.

### ***INCIDENT SITE***

This hyperthermia incident occurred on the lawn area of a private residence in a rural area during midday hours. The family residence was a mobile home that was oriented in a north/south direction on a large lawn area (**Figure 2**). The family vehicle, consisting of the Mitsubishi that was registered to the child's grandmother was parked on the lawn, east of the mobile home facing in a southwesterly direction. On the day of the incident the National Weather Service reported a temperature of 30 °C (86.0 °F) at 1155 hours,

approximately the time the child entered the Mitsubishi. At the recorded time, the heat index was 35 °C (95.1 °F) with 70 percent humidity and the wind was out of the north-northwest at 5.6 km/h (3.5 mph). The temperature increased to 32 °C (89.6 °F) at 1255 hours, the approximately time the child was found unconscious in the vehicle. At this recorded time, the heat index was 37.6 °C (99.8 °F) with 62 percent humidity with east-northeast winds reported at 9.3 km/h (5.8 mph). The sky was classified as party to mostly cloudy.



**Figure 2: Satellite image of the Incident Site. North lies at the top of the image.**

### ***2003 MITSUBISHI GALANT***

#### ***Description***

The involved vehicle was a 2003 Mitsubishi Galant GTZ 4-door sedan. The Vehicle Identification Number (VIN) was not recorded in the Police Incident Report. Based on the available police images, the Mitsubishi was black in exterior color. The vehicle was configured with a sunroof, a V-6 gasoline engine, 4-wheel disc brakes and 6-spoke alloy wheels. The transmission was a 4-speed automatic with a console-mounted shifter.

**Figure 3** is an exterior view of the Mitsubishi Galant.



**Figure 3: Front right exterior view of the 2003 Mitsubishi Galant. (Image obtained from the investigating police department.)**

The interior of the Mitsubishi consisted of front row bucket seats with adjustable head restraints and a three-passenger second row bench seat. The front seat backs were in the upright and usable position to an occupant at the time of the incident. All seating surfaces were leather. The entire interior was gray in color. **Figure 4** is a left interior view of the Mitsubishi's front row.



**Figure 4: Front row interior of the 2003 Mitsubishi Galant. (Image provided by the investigating police department.)**

### ***Glazing***

The Mitsubishi was configured with an AS1 laminated windshield, operable AS2 glazing at each door, fixed rear door quarter windows, an AS2 fixed backlight and an operable sunroof with AS3 glazing. The child's grandfather said the vehicle was equipped with aftermarket window tint. This aftermarket tint was visible on the second row doors. He further stated that some of the tint had to be removed as it was scratched by the dog during the incident. It is unknown if the aftermarket window tint was applied to both front doors and the backlight. The roof window was closed at the time of the incident; the position of the interior cover was unknown.

### ***Exterior Door Handles***

The four exterior door handles on the Mitsubishi were hinged at the top edge and rotated in an upward direction to release the door latch (**Figure 5**). The bottom edge of the driver's door latch was measured by the investigating officer at 78 cm (30.75 in) above the ground. The SCI team documented an exemplar Mitsubishi Galant and recorded the same measurement for the front handles. Fully rotated (lifted), the front door latches measured 81 cm (31.75 in) above the ground. The rear door handles on the exemplar vehicle measured 82 cm (32.25 in) and 85 cm (33.5 in) respectively. Keyed lock cylinders were incorporated into both front door handle assemblies.



**Figure 5: Exterior driver's door handle of the Mitsubishi. (Image provided by the investigating police department.)**

### ***Interior Door Release Levers***

The interior door release levers on the Mitsubishi were located in the upper-forward aspect of the door panels and consisted of an L-shaped lever requiring a horizontal pull to open the doors. The levers were 10 cm (3.75 in) in length, inclusive of the hinge point. The levers were flush-mounted to the door panel. **Figures 6 and 7** are exemplar views of the interior door release levers.



**Figure 6:** View of the exemplar driver's door interior release lever.



**Figure 7:** View of the exemplar second row left door interior release lever.

### ***Door Locking System***

A power locking system was standard equipment on the Mitsubishi. Remote locking and unlocking was accomplished by the battery-operated key fob. Based on the exemplar vehicle inspection, the fob was configured with two buttons; one to lock all four doors with a single engagement of the button, and one unlock button that unlocked the driver's door on a single engagement and the remaining three doors with two engagements of the button.

The interior-mounted power locking system consisted of rocker-type switches that were mounted on the up-sloped forward edge of the integrated armrest on both front door panels. The leading edge (forward) of the switch provided the locking function while the aft edge was the unlock mode. The rear doors were not equipped with power lock switches. **Figures 8 and 9** are exemplar views of the front row power locking rocker switches.



**Figure 8:** View of the exemplar driver's power locking switch.



**Figure 9:** View of the exemplar front row right power locking rocker switch.



The interior manual locking system consisted of rotating lock knob located directly above the interior door release lever (**Figure 10**) at each door. The color coordinated lock knobs matched the release levers. The leading edges of the knobs were marked with a high visibility orange stripe, visible only in the unlocked position. With the rotating knob pushed forward and flush with the release lever, the door would lock. Rotating the knob rearward unlocked the doors.



**Figure 10: Exemplar interior manual locking knob in unlocked position.**

With the doors locked either by key fob, utilizing the interior power locking switches, or manually locking all four doors independently, the front door release levers would override the lock for the specific door. The rear door locks would not unlock when the release lever was pulled. The rotating locking knob had to be manually rotated rearward to unlock the specific second row door.

### ***Door Detent***

The investigating officer reported that the driver's door of the Mitsubishi would not stay open at the time of the incident. Apparently the detent was worn allowing the door to self-close due to a shallow grade of the lawn area. The SCI inspection of the exemplar vehicle determined the doors were equipped with two detent positions located approximately at one-third and two-thirds of the door's travel.

### ***INCIDENT***

Prior to the incident, the 3-year-old child was inside the family's mobile home watching television with his 24-year-old mother. They were seated on the couch. The child's father was asleep in a separate room, as he had returned to the residence in the early morning, daylight hours from his work shift. The child's grandmother was in her room watching television. The child was police-reported as walking about the mobile home, from the living area to his grandmother's room on several occasions. The child's mother stated to the investigating police officer that she fell asleep on the couch with the child at her side at approximately 1200 hours. She referenced this time to a program that was airing on the television.

The child's mother awoke at approximately 1300 hours and noticed her son missing from the couch. She got up and started to look for him and began screaming his name in an attempt to locate the child. The mother looked outside and observed the emergency flashers activated on the grandmother's 2003 Mitsubishi. She ran to the vehicle and observed the child slumped over on the driver's seat. The mother opened the driver's door, removed the child from the vehicle and

carried him into the mobile home. The child was lethargic and mumbled to his mother as she splashed cold water on his face. The mother instructed the grandmother to call the emergency response system. The first call to the emergency response system was dropped due to a poor cellular connection. The second call was made and police and emergency medical services were dispatched at 1316 hours. EMS personnel arrived prior to the police. The time of the police arrival was reported at 1324 hours. The child was transported by helicopter to a regional pediatric trauma center and was admitted in critical condition. He expired 3.5 days following the incident. During the hospitalization, the child victim's kidneys failed and he developed internal pulmonary bleeding, consequences of the hyperthermia.

A reconstruction of the sequence of events was derived from the documentation of the investigating officer based on his interviews with the involved parties, his inspection of the mobile home, and the inspection and documentation of the Mitsubishi.

The mobile home was configured with a single exterior door. A storm door was mounted to the exterior frame of the entrance door. The officer described the door latches as follows: The storm door was operable and the latching mechanism was intact; however, there was a screw missing from the bottom of the latch. The mobile home door had a knob-operated locking system. To lock the door from the inside, the door knob had to be pushed forward to engage the lock. Turning the knob from the inside would release the lock feature. The child's grandfather installed a hasp-type lock on the inside of the door and used a carabiner to prevent the child from unlatching the hasp. At the time of the police inspection, there was no carabiner present.

The door to the mobile home opened onto a small wooden deck. A flight of five steps transitioned the deck to ground level. The Mitsubishi was parked on the lawn area in the vicinity of the deck. While the mother was sleeping, the child opened the doors of the mobile home and exited the residence onto the deck. From there he walked down the steps to the Mitsubishi. A family dog accompanied him to the vehicle. It is unknown if the dog was in the mobile home or was outside when the child emerged.

The child apparently opened the driver's door of the Mitsubishi and both he and the dog entered the vehicle. The police officer inspected the vehicle and documented the status of the driver's door. He reported the door would not stay open at the manufactured detent positions. Due to the slight slope of the lawn area, the door would close on its own. It was then theorized that as the child and dog entered the vehicle, the door closed behind them. The grandfather of the child stated in a follow-up interview that the child knew how to work the doors of the vehicle as he would play in it from time to time.

As the child and dog became entrapped within the Mitsubishi, one of them activated the hazard warning flashers. The hazard warning switch was located on the upper-mid instrument panel and

consisted of a hard push-type switch. To activate the flashers, the switch had to be depressed and the switch face would return to its original position. Depressing the switch again, once the flashers were activated, would turn off the flashers and return the switch to its neutral (off) position.

The family reported that post-event, they entered the Mitsubishi to drive to the hospital. It was at that time that they found the dog was deceased in the back seat area of the vehicle. The family also reported they had to clean the inside of the vehicle and removed some of the aftermarket window tint as the dog had scratched the tint film in an attempt to get out of the vehicle.

The total duration from the time the child exited the mobile home to his discovery in the Mitsubishi was estimated by his mother to be approximately one hour.

The investigating officer and medical staff documented superficial scratches on the child victim's extremities and torso during his hospitalization. It was suspected that these resulted from the dog that was in the vehicle with the child victim.

***NON-MOTORIST DEMOGRAPHICS***

The child involved in this hyperthermia investigation was a 3-year-old male with a police-reported height of 99 cm (39 in) and a weight of 24 kg (54 lb). His clothing worn at the time of the incident was not reported. In addition to the child, three adults were living at this residence. Supervision at the incident time was directed by his 24-year-old mother; his 24-year-old father was asleep in a separate room and his 46-year-old grandmother was in another room watching television.

***NON-MOTORIST INJURIES***

<b>Injury No.</b>	<b>Injury</b>	<b>AIS 2015</b>	<b>Involved Physical Component</b>	<b>IPC Confidence</b>
1	Hyperthermia	010200.1	Vehicle entrapment	Certain
2	Superficial abrasions of the right arm	710202.1	Dog scratches	Probable
3	Superficial abrasions of the left arm	710202.1	Dog scratches	Probable
4	Superficial abrasions of the right leg	810202.1	Dog scratches	Probable
5	Superficial abrasions of the left leg	810202.1	Dog scratches	Probable
6	Superficial abrasions of the torso	410202.1	Dog scratches	Probable

*Source – Police Incident Report*

**INCIDENT SITE DIAGRAM**



**Incident Site:  
Private Property**

**V1: 2003 Mitsubishi Galant**

	
Case Number:	CR16036

APPENDIX A: Non-Traffic Surveillance Forms



Not Applicable

U.S. Department of Transportation  
National Highway Traffic Safety Administration

**Reset Values**

**Print Forms**

# SCENE FORM

Special Crash Investigations  
Non-Traffic Surveillance

1. Case Number  
  C     R     1     6     0     3     6  

## IDENTIFICATION

2. Date of Crash   0     7   /   x     x   /   1     4  

3. Time of Crash   1     3     1     6  

Code reported military time of crash.

NOTE: Midnight = 2400  
Unknown = 9999

## AMBIENT CONDITIONS

4. Light Conditions

- Daylight
- Dark
- Dark but lighted
- Dawn
- Dusk
- Unknown

5. Atmospheric Conditions  
(Select all that apply)

- Clear-No adverse conditions
- Cloudy
- Rain
- Snow
- Fog, Smog, Smoke
- Sleet, Hail (freezing rain or drizzle)
- Blowing Snow
- Severe Crosswinds
- Blowing Sand, Soil, Dirt
- Other (specify): \_\_\_\_\_
- Unknown

6. Temperature

- Below 0 degrees Celsius (Below 32 F)
- 1-10 degrees Celsius (33-50 F)
- >10-24 degrees Celsius (51-75 F)
- Over 24 degrees Celsius (Over 75 F)
- Unknown

## SCENE INFORMATION

7. Type of area in which crash occurred  
(Select all that apply)

- Single family residential
- Row houses/townhouses
- Multi family housing
- Commercial
- Industrial
- Rural
- Unknown

8. Driver exterior sightline obstructions  
(Select all that apply)

- None
- Other vehicles
- Building
- Trees
- Shrubby
- Other (specify)   N/A
- Utility poles
- Signs
- Glare
- Unknown
- No driver present

9. Crash location

- Driveway
- Parking Lot
- Sidewalk
- Alley
- Intersection of driveway and sidewalk
- Road / street
- Roadside / shoulder
- Other (specify)   N/A
- Unknown

10. Non motorist sightline obstructions  
(Select all that apply)

- None
- Other vehicles
- Building
- Trees
- Shrubby
- Utility poles
- Signs
- Glare
- Other (specify)   N/A
- Unknown

11. Grade at parked position   9     9     9   %  
+ / -

12. Estimated distance from parked position to impact  
  0     0     0     0   m

13. Estimated speed at impact   0     0     0   kmph  
+ / -

14. Grade at impact   9     9     9   %

15. Estimated distance from impact to vehicle final rest  
  0     0     0     0   m

Unknown = 999 Reference Items 11,12, 13, 14, 15

Revised January 2018

Not Applicable

**Reset Values**



U.S. Department of Transportation  
National Highway Traffic Safety Administration

**VEHICLE FORM**

Special Crash Investigations  
Non-Traffic Surveillance

1. Case Number   C     R     1     6     0     3     6  

**VEHICLE IDENTIFICATION**

2. VIN   9     9     9     9     9     9     9     9     9     9     9     9     9     9     9     9  

3. Model Year   2     0     0     3  

4. Vehicle Make (specify):   Mitsubishi  

5. Vehicle Model (specify):   Galant  

**GLAZING**

Location	Presence (check)	Status (select)	Clarity (select)	Tint (check)	Glazing Obstructions (specify if present)
Windshield	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Fixed / <input type="checkbox"/> Closed / <input type="checkbox"/> Open / <input type="checkbox"/> Partially Open / <input type="checkbox"/> Unknown	<input type="checkbox"/> Clear / <input type="checkbox"/> Hazy / <input type="checkbox"/> Very Dirty / <input checked="" type="checkbox"/> Unknown	<input type="checkbox"/>	Not inspected
LF	<input checked="" type="checkbox"/>	<input type="checkbox"/> Fixed / <input checked="" type="checkbox"/> Closed / <input type="checkbox"/> Open / <input type="checkbox"/> Partially Open / <input type="checkbox"/> Unknown	<input type="checkbox"/> Clear / <input type="checkbox"/> Hazy / <input type="checkbox"/> Very Dirty / <input checked="" type="checkbox"/> Unknown	<input type="checkbox"/>	
RF	<input checked="" type="checkbox"/>	<input type="checkbox"/> Fixed / <input checked="" type="checkbox"/> Closed / <input type="checkbox"/> Open / <input type="checkbox"/> Partially Open / <input type="checkbox"/> Unknown	<input type="checkbox"/> Clear / <input type="checkbox"/> Hazy / <input type="checkbox"/> Very Dirty / <input checked="" type="checkbox"/> Unknown	<input type="checkbox"/>	
2 <sup>nd</sup> Left	<input checked="" type="checkbox"/>	<input type="checkbox"/> Fixed / <input checked="" type="checkbox"/> Closed / <input type="checkbox"/> Open / <input type="checkbox"/> Partially Open / <input type="checkbox"/> Unknown	<input type="checkbox"/> Clear / <input type="checkbox"/> Hazy / <input type="checkbox"/> Very Dirty / <input checked="" type="checkbox"/> Unknown	<input checked="" type="checkbox"/>	
2 <sup>nd</sup> Right	<input checked="" type="checkbox"/>	<input type="checkbox"/> Fixed / <input checked="" type="checkbox"/> Closed / <input type="checkbox"/> Open / <input type="checkbox"/> Partially Open / <input type="checkbox"/> Unknown	<input type="checkbox"/> Clear / <input type="checkbox"/> Hazy / <input type="checkbox"/> Very Dirty / <input checked="" type="checkbox"/> Unknown	<input checked="" type="checkbox"/>	
3 <sup>rd</sup> Left	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Fixed / <input type="checkbox"/> Closed / <input type="checkbox"/> Open / <input type="checkbox"/> Partially Open / <input type="checkbox"/> Unknown	<input type="checkbox"/> Clear / <input type="checkbox"/> Hazy / <input type="checkbox"/> Very Dirty / <input checked="" type="checkbox"/> Unknown	<input type="checkbox"/>	
3 <sup>rd</sup> Right	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Fixed / <input type="checkbox"/> Closed / <input type="checkbox"/> Open / <input type="checkbox"/> Partially Open / <input type="checkbox"/> Unknown	<input type="checkbox"/> Clear / <input type="checkbox"/> Hazy / <input type="checkbox"/> Very Dirty / <input checked="" type="checkbox"/> Unknown	<input type="checkbox"/>	
Backlight	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Fixed / <input type="checkbox"/> Closed / <input type="checkbox"/> Open / <input type="checkbox"/> Partially Open / <input type="checkbox"/> Unknown	<input type="checkbox"/> Clear / <input type="checkbox"/> Hazy / <input type="checkbox"/> Very Dirty / <input checked="" type="checkbox"/> Unknown	<input type="checkbox"/>	
Left Backlight	<input type="checkbox"/>	<input type="checkbox"/> Fixed / <input type="checkbox"/> Closed / <input type="checkbox"/> Open / <input type="checkbox"/> Partially Open / <input type="checkbox"/> Unknown	<input type="checkbox"/> Clear / <input type="checkbox"/> Hazy / <input type="checkbox"/> Very Dirty / <input type="checkbox"/> Unknown	<input type="checkbox"/>	
Right Backlight	<input type="checkbox"/>	<input type="checkbox"/> Fixed / <input type="checkbox"/> Closed / <input type="checkbox"/> Open / <input type="checkbox"/> Partially Open / <input type="checkbox"/> Unknown	<input type="checkbox"/> Clear / <input type="checkbox"/> Hazy / <input type="checkbox"/> Very Dirty / <input type="checkbox"/> Unknown	<input type="checkbox"/>	
Roof	<input checked="" type="checkbox"/>	<input type="checkbox"/> Fixed / <input checked="" type="checkbox"/> Closed / <input type="checkbox"/> Open / <input type="checkbox"/> Partially Open / <input type="checkbox"/> Unknown	<input type="checkbox"/> Clear / <input type="checkbox"/> Hazy / <input type="checkbox"/> Very Dirty / <input type="checkbox"/> Unknown	<input type="checkbox"/>	
Other (specify)	<input type="checkbox"/>	<input type="checkbox"/> Fixed / <input type="checkbox"/> Closed / <input type="checkbox"/> Open / <input type="checkbox"/> Partially Open / <input type="checkbox"/> Unknown	<input type="checkbox"/> Clear / <input type="checkbox"/> Hazy / <input type="checkbox"/> Very Dirty / <input type="checkbox"/> Unknown	<input type="checkbox"/>	

**TIRE DATA**

6. Vehicle Manufacturer Recommended Tire Size   P205/55R15  

7. LF Tire Size   Unknown  

9. RF Tire Size   Unknown  

8. LR Tire Size   Unknown  

10. RR Tire Size   Unknown  

Revised January 2018

Seats / Head Restraint Data				NOTES: Not inspected by SCI team.
Seat Position	Seat Type (Select from below )	Head Restraint (Check if available)	Head Restraint Adjustment (select)	
Front Left	1	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Full Down / Mid / Full Up	
Front Middle	0	<input type="checkbox"/>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Full Down / Mid / Full Up	
Front Right	1	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Full Down / Mid / Full Up	
2 <sup>nd</sup> Left	3	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Full Down / Mid / Full Up	
2 <sup>nd</sup> Middle	3	<input type="checkbox"/>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Full Down / Mid / Full Up	
2 <sup>nd</sup> Right	3	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Full Down / Mid / Full Up	
3 <sup>rd</sup> Left		<input type="checkbox"/>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Full Down / Mid / Full Up	
3 <sup>rd</sup> Middle		<input type="checkbox"/>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Full Down / Mid / Full Up	
3 <sup>rd</sup> Right		<input type="checkbox"/>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Full Down / Mid / Full Up	

**Seat Type codes:**

- |   |                                      |
|---|--------------------------------------|
| 0 = No seat or seat folded down           | 8 = Pedestal (i.e. column supported) |
| 1 = Bucket                                | 9 = Box mounted (i.e. van type)      |
| 2 = Bucket w/ folding back                | 10= Other seat type (specify)        |
| 3 = Bench                                 | 99= Unknown seat type                |
| 4 = Bench with folding back cushions      |                                      |
| 5 = Bench w/ folding back                 |                                      |
| 6 = Split bench w/ separate back cushions |                                      |
| 7 = Split bench w/ separate folding back  |                                      |

VEHICLE MEASUREMENTS		
Clearance Heights	Measurements (all from ground, and in centimeters)	NOTES
Beltline		Not inspected by SCI team.
Top of trunk/tailgate		
Bottom of bumper		
Trailer hitch (if applicable)		
Undercarriage		
Sway bar		
Axle		
Differential		
Other (specify):		
Sensor Height (if equipped)		
Camera Height (if equipped)		





Not Applicable

Undo Not Applicable

Reset Values

## Back Up / Parking Aid Form

Special Crash Investigations  
Non-Traffic Surveillance

<p>1. Case Number</p> <p style="text-align: center;">C   R   1   6   0   3   6</p> <p style="text-align: center;"><b>PARKING AID PRESENCE</b></p> <p>2. Type of backing/parking aid present</p> <p><input type="checkbox"/> OEM camera</p> <p><input type="checkbox"/> OEM ultrasonic/radar sensor</p> <p><input type="checkbox"/> OEM combination camera-ultrasonic/radar sensor</p> <p><input type="checkbox"/> OEM Fresnel lens</p> <p><input type="checkbox"/> OEM interior mirrors</p> <p><input type="checkbox"/> Aftermarket camera</p> <p><input type="checkbox"/> Aftermarket ultrasonic/radar sensor</p> <p><input type="checkbox"/> Aftermarket combination camera-ultrasonic radar sensor</p> <p><input type="checkbox"/> Aftermarket Fresnel lens</p> <p><input type="checkbox"/> Aftermarket interior mirrors</p> <p><input type="checkbox"/> Other (specify): _____</p> <p style="text-align: center;"><b>CAMERA INFORMATION</b></p> <p><i>Specify field of view measurements on diagram</i></p> <p>3. System make/model</p> <p>_____</p> <p>4. Video monitor type</p> <p><input type="checkbox"/> None present</p> <p><input type="checkbox"/> LCD (color)</p> <p><input type="checkbox"/> CRT (black &amp; white)</p> <p><input type="checkbox"/> Unknown</p> <p>5. Video display size _____ cm (Diagonal)</p> <p>6. Camera location</p> <p><input type="checkbox"/> None present</p> <p><input type="checkbox"/> Bumper</p> <p><input type="checkbox"/> License plate</p> <p><input type="checkbox"/> Tailgate/Hatch/Trunk</p> <p><input type="checkbox"/> Other (specify): _____</p>	<p>7. Video image quality under scene lighting conditions</p> <p><input type="checkbox"/> None present</p> <p><input type="checkbox"/> Good</p> <p><input type="checkbox"/> Average</p> <p><input type="checkbox"/> Poor (specify): _____</p> <p><input type="checkbox"/> Unknown</p> <p>8. Was the camera functioning properly</p> <p><input type="checkbox"/> None present</p> <p><input type="checkbox"/> Yes</p> <p><input type="checkbox"/> No, poor image quality due to glare</p> <p><input type="checkbox"/> No, poor image quality due to atmospheric conditions</p> <p><input type="checkbox"/> No, camera turned off</p> <p><input type="checkbox"/> No, camera inoperable</p> <p><input type="checkbox"/> Unknown</p> <p style="text-align: center;"><b>ULTRASONIC/RADAR SENSOR</b></p> <p><i>Specify object detection range on diagram</i></p> <p>9. System make/model</p> <p>_____</p> <p>10. Auditory warning illumination</p> <p><input type="checkbox"/> No sensor present</p> <p><input type="checkbox"/> Yes</p> <p><input type="checkbox"/> No</p> <p><input type="checkbox"/> Unknown</p> <p>11. Number of sensors _____</p> <p>12. Sensor locations (Select all that apply)</p> <p><input type="checkbox"/> No sensor present</p> <p><input type="checkbox"/> Left bumper</p> <p><input type="checkbox"/> Center bumper</p> <p><input type="checkbox"/> Right bumper</p> <p><input type="checkbox"/> License plate area</p> <p><input type="checkbox"/> Tailgate/Hatch/Trunk</p> <p>13. Was warning system functioning properly</p> <p><input type="checkbox"/> No sensor present</p> <p><input type="checkbox"/> Yes, system alerted driver</p> <p><input type="checkbox"/> No, system did not alert driver</p> <p><input type="checkbox"/> No, system turned off</p> <p><input type="checkbox"/> No, system inoperable</p> <p><input type="checkbox"/> Unknown</p>
---	--

Not Applicable

14. Did driver react to warning

- No sensor present
- Yes
- No
- Unknown
- Sensor present, did not sound

15. Did driver report common false warnings

- No sensor present
- Yes
- No
- Unknown

Not Applicable

No Driver Present



Undo Not Applicable

Reset Values

U.S. Department of Transportation  
National Highway Traffic Safety Administration

### DRIVER FORM

Special Crash Investigations  
Non-Traffic Surveillance

1. Case Number  
C R 1 6 0 3 6

**DRIVER PROFILE**

2. Driver's Age \_\_\_\_\_  
99 = Unknown

3. Driver's Sex  Male  
 Female  
 Unknown

4. Driver's Height \_\_\_\_\_ cm  
999 = Unknown

5. Driver's Weight \_\_\_\_\_ kg  
999 = Unknown

6. Driver eyewear worn  
(Select all that apply)  
 None  
 Eyeglasses  
 Sunglasses  
 Contacts  
 Unknown

7. Driver vision deficiency condition  
(Select all that apply)  
 None  
 Near sighted  
 Far sighted  
 Astigmatism  
 Other (specify): \_\_\_\_\_  
 Unknown

8. Non motorist's relationship to driver  
 No relationship  
 Child  
 Grandchild  
 Sibling  
 Neighbor  
 Friend  
 Other (specify): \_\_\_\_\_  
 Unknown

**DRIVER ACTIONS**

9. Driver approach to vehicle for entry  
 From left front  
 From left  
 From left rear  
 From right rear  
 From right front  
 Circled vehicle  
 Return trip (backing into driveway/lot)  
 Other (specify): \_\_\_\_\_  
 N/A  
 Unknown

10. Driver entry interruption  
(Select all that apply)  
 Direct trip from building to vehicle  
 Loaded items into vehicle  
 Spoke with family  
 Spoke with neighbors  
 Spoke with contacted nonmotorist  
 Return trip (backing into driveway/lot)  
 Other (specify): \_\_\_\_\_  
 N/A  
 Unknown

11. Purpose of backing  
 Leaving parking space in parking lot  
 Backing onto roadway from driveway  
 Entering parking space in parking lot  
 Backing into driveway from roadway  
 Other (specify): \_\_\_\_\_  
 N/A  
 Unknown

12. Where was driver going  
Description:  
\_\_\_\_\_  
\_\_\_\_\_

13. Driver in a hurry  
 Yes  No  N/A  
 No  Unknown

14. How did driver check behind (rear area of vehicle)  
after vehicle entry  
(Select all that apply)  
 Did not look  
 Checked mirrors  
 Turned right and looked back  
 Turned left and looked back  
 Viewed Camera  
 Listened for auditory/visual warning from system  
 Other (specify): \_\_\_\_\_  
 N/A  Unknown

15. Estimated time between vehicle entry and start  
of backing  
 0-10 Seconds  Over 60 Seconds  
 11-30 Seconds  N/A  
 31-60 Seconds  Unknown

Not Applicable

16. What direction was the driver looking during backing maneuver  
(Select all that apply)
- Straight ahead
  - Right
  - Left
  - Rearward
  - At object inside the car
  - At mirrors
  - Other (specify): \_\_\_\_\_
  - N/A
  - Unknown

17. Was the driver distracted during back up maneuver  
(Select all that apply)
- No non-driving activities
- External**
- Looking at other vehicles
  - Looking at other non motorist
  - Looking at intended turn destination
  - External focus, not specified
  - Other external focus (specify): \_\_\_\_\_
- Internal**
- Looking at other occupant
  - Talking to passenger
  - Dialing phone
  - Talking on phone
  - Listening to radio and/portable play back device
  - Adjusting radio/cd player
  - Adjusting climate controls
  - Using a device/controls integral to vehicle (specify): \_\_\_\_\_
  - Reading/adjusting navigation system
  - Eating or drinking
  - Smoking related
  - Retrieving fallen object (specify): \_\_\_\_\_
  - Internal focus, not specified
  - Focused on other internal object (specify): \_\_\_\_\_
  - N/A
  - Unknown

18. Driver avoidance actions prior to impact  
(Select all that apply)
- None
  - Braking
  - Steering left
  - Steering right
  - Accelerating
  - Other (specify): \_\_\_\_\_
  - N/A
  - Unknown

19. Did driver see struck non motorist prior to impact  
(Select all that apply)
- No, never saw non motorist
  - Saw non motorist prior to entering vehicle
  - Saw non motorist after entering vehicle
  - Other (specify): \_\_\_\_\_
  - N/A  Unknown

20. Est time between start of backing and impact
- <2 or = 1 second
  - 2-5 seconds
  - 6-10 seconds
  - > 10 seconds
  - N/A  Unknown

21. Driver interior sightline obstructions  
(Select all that apply)
- Pillar
  - Headrest
  - Cargo
  - Other occupant
  - Other (specify) \_\_\_\_\_
  - Unknown
  - None

22. Recent experience driving this vehicle
- More than 10 times the last three months
  - 6-10 times the last three months
  - 2-5 times the last three months
  - Less than 2 times the last three months
  - First time driving this vehicle
  - N/A
  - Unknown

23. Frequency of driving in this parking lot/driveway
- Daily
  - Weekly
  - Several times a month
  - Monthly
  - Rarely
  - First time in lot/driveway
  - N/A  Unknown

24. Driver Impairment  
(Select all that apply)
- No drugs or alcohol present
  - Alcohol present (specify BAC): \_\_\_\_\_
  - Drugs present (specify): \_\_\_\_\_
  - Unknown

25. Source of alcohol/drug results
- Police reported
  - Medical record
  - Other (specify) \_\_\_\_\_
  - Not Tested
  - Unknown if tested

Not Applicable



Not Applicable

U.S. Department of Transportation  
National Highway Traffic Safety Administration

# Non Motorist Form

**Reset Values**

Special Crash Investigations  
Non-Traffic Surveillance

1. Case Number  
C R 1 6 0 3 6

## NON-MOTORIST PROFILE

2. Non-motorist's Age 0 3  Months  
99 = Unknown  Years

3. Non-motorist's Sex  Male  
 Female  
 Unknown

4. Non-motorist's Height 0 9 9 cm  
999 = Unknown

5. Non-motorist's Weight 0 2 4 kg  
999 = Unknown

6. Medical outcome  
 Not injured  
 ER only  
 Hospitalized 1-4 days  
 Hospitalized 5 days or more  
 Treatment later  
 Fatal  
 Unknown

7. Source of most severe injury  
 Bumper  
 Tire  
 Undercarriage  
 Other Specify: Hyperthermia  
 Ground  
 N/A  
 Unknown

8. Non-motorist impairment  
(Select all that apply)  
 No drugs or alcohol present  
 Positive for alcohol (specify BAC): \_\_\_\_\_  
 Positive for drugs (specify): \_\_\_\_\_  
 Unknown

9. Source of alcohol/drug results  
 Police reported  
 Medical Report  
 Other (specify) \_\_\_\_\_  
 Not Tested  
 Unknown if tested

## NON-MOTORIST ACTIONS

10. Non-motorist attitude  
 Standing  On skates/skateboard  
 Bending at waist  On bike/scooter  
 Sitting  Other (specify) N/A  
 Crouching  Unknown  
 Kneeling

11. Non-motorist motion

Not moving  
 Walking slowly  
 Walking rapidly  
 Running or jogging  
 Skipping/Hopping/Jumping  
 Falling/Stumbling/Rising  
 On skates/skateboard  
 On bike/scooter  
 Other (specify): N/A  
 Unknown

12. Non-motorist approach relative to rear of vehicle

Stationary  
 From left  
 From right  
 From behind  
 Other (specify): N/A  
 Unknown

13. Non-motorist first avoidance action

No avoidance actions  
 Stopped  
 Accelerated pace  
 Ran away (along vehicle path)  
 Jumped  
 Turned away from vehicle  
 Turned toward vehicle and braced  
 Dove or fell away from vehicle  
 Other (specify): N/A  
 Unknown

14. Non-motorist primary focus of attention

Striking vehicle  
 Play object  
 Person  
 Surrounding traffic  
 Animal  
 Handheld electronic (phone, MP3 player, etc.)  
 Other Object (specify) N/A  
 Unknown

15. Were any other Non-motorists present?  
(Select all that apply)

Alone  
 One adult present  
 One other child present  
 Multiple adults present  
 Multiple children present  
 Unknown

Revised January 2018

**NON MOTORIST CLOTHING**

**NOTES:**

- Specify Color, Fabric and Texture/Weight for outermost layer only
- Indicate "NONE" if applicable
- Available codes:

	<u><b>Colors</b></u>		<u><b>Fabrics</b></u>		<u><b>Textures</b></u>		<u><b>Weights</b></u>
Black	Charcoal gray		Natural		Soft		Heavy
Lt gray/silver	Brown		Synthetic		Slick		Medium
Gold/tan	Purple		Blend		Coarse		Light
Dark blue	Light blue						
Dark green	Light green						
Maroon	Red						
Orange	Yellow						
White	Other (specify)						
Pink							

	<b>Clothing</b>	<b>Color</b>	<b>Fabric</b>	<b>Texture</b>	<b>Weight</b>
<b>H E A D W E A R</b>	Hat				
	Helmet				
	Hood				
	Other (specify): _____				
	Unknown				
<b>U P P E R  B O D Y</b>	Short Sleeve				
	Long Sleeve				
	Light Jacket				
	Heavy Jacket				
	Other (Specify): _____				
Unknown	Unknown	Unknown	Unknown	Unknown	Unknown
<b>L O W E R  B O D Y</b>	Shorts				
	Pants				
	Shoes				
	Other (specify): _____				
	Unknown	Unknown	Unknown	Unknown	Unknown

DOT HS 812 534  
June 2018



U.S. Department  
of Transportation

**National Highway  
Traffic Safety  
Administration**



136710-060518-v3