



U.S. Department  
of Transportation  
**National Highway  
Traffic Safety  
Administration**



---

DOT HS 812 639

October 2018

# **Special Crash Investigations On-Site Guardrail End Treatment Impact Investigation Vehicle: 2002 Kia Sportage Location: Missouri Crash Date: April 2016**

## DISCLAIMER

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof. The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants. Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicles or their safety systems.

This report and associated case data are based on information available to the Special Crash Investigation team on the date this report was published.

Suggested APA Format Citation:

Special Crash Investigation Team 2 (2018, October). *Special Crash Investigations On-Site Guardrail End Terminal Investigation; Vehicle: 2002 Kia Sportage; Location: Missouri; Crash Date: April 2016* (Report No. DOT HS 812 639). Washington, DC: National Highway Traffic Safety Administration.

### Technical Report Documentation Page

<p>1. <i>Report No.</i> DOT HS 812 639</p>	<p>2. <i>Government Accession No.</i></p>	<p>3. <i>Recipient's Catalog No.</i></p>	
<p>4. <i>Title and Subtitle</i> Special Crash Investigations On-Site Guardrail End Treatment Investigation Vehicle: 2002 Kia Sportage Location: Missouri Crash Date: April 2016</p>		<p>5. <i>Report Date:</i> October 2018</p>	
		<p>6. <i>Performing Organization Code</i></p>	
<p>7. <i>Author</i> Special Crash Investigations Team 2</p>		<p>8. <i>Performing Organization Report No.</i> IN16011</p>	
<p>9. <i>Performing Organization Name and Address</i> Transportation Research Center, Indiana University 501 South Madison Street, Suite 105 Bloomington, Indiana 47403-2452</p>		<p>10. <i>Work Unit No. (TRAIS)</i></p>	
		<p>11. <i>Contract or Grant No.</i> DTNH22-12-C-00270</p>	
<p>12. <i>Sponsoring Agency Name and Address</i> National Highway Traffic Safety Administration National Center for Statistics and Analysis 1200 New Jersey Avenue SE. Washington, D.C. 20590-0003</p>		<p>13. <i>Type of Report and Period Covered</i> Technical Report Crash Date: April 2016</p>	
		<p>14. <i>Sponsoring Agency Code</i> NSA-110</p>	
<p>15. <i>Supplementary Notes</i> On-site SKT guardrail end treatment investigation involving a 2002 Kia Sportage.</p>			
<p>16. <i>Abstract</i> This report documents the on-site investigation of the impact of a 2002 Kia Sportage into a sequential kinking terminal (SKT) guardrail end treatment that is of interest to the Federal Highway Administration (FHWA). This crash occurred on an exit ramp from the northbound lanes of an interstate highway and in an interchange area of three interstate highways. The Kia was a 4-door sport utility vehicle (SUV) equipped with frontal air bags and a driver's knee air bag. The vehicle was not equipped with an event data recorder that was supported by a commercially available tool. An unbelted 20-year-old male driver occupied the vehicle. The Kia was traveling north in the left lane of the exit ramp. The driver fell asleep and the vehicle departed the left side of the exit ramp and entered the gore where the front plane struck the SKT (Event 1). The impact extruded 8.7 m (28.6 ft) of guardrail and displaced eight posts. The impact caused the Kia to rotate counterclockwise and the right corner of the back plane struck the guardrail. The vehicle came to final rest heading southeast. The driver then drove the damaged vehicle to the east shoulder of the exit ramp and waited for emergency responders to arrive. The driver sustained police-reported "B" (non-incapacitating) injuries and was transported by ambulance to a hospital. The Kia was towed from the crash scene due to damage.</p>			
<p>17. <i>Key Words</i> guardrail end terminal guardrail motor vehicle traffic crash minor injury extrusion</p>		<p>18. <i>Distribution Statement</i> Document is available to the public from the National Technical Information Service, <a href="http://www.ntis.gov">www.ntis.gov</a>.</p>	
<p>19. <i>Security Classif. (of this report)</i>  Unclassified</p>	<p>20. <i>Security Classif. (of this page)</i>  Unclassified</p>	<p>21. <i>No. of Pages</i>  20</p>	<p>22. <i>Price</i></p>

## TABLE OF CONTENTS

<b>BACKGROUND .....</b>	<b>1</b>
<b>CRASH SUMMARY .....</b>	<b>2</b>
CRASH SITE .....	2
PRE-CRASH .....	2
CRASH.....	2
POST-CRASH .....	3
<b>END TERMINAL AND GUARDRAIL DAMAGE .....</b>	<b>3</b>
<b>2002 KIA SPORTAGE.....</b>	<b>4</b>
DESCRIPTION .....	4
EXTERIOR DAMAGE.....	4
INTERIOR DAMAGE.....	5
MANUAL RESTRAINT SYSTEMS.....	5
SUPPLEMENTAL RESTRAINT SYSTEMS .....	5
<b>2002 KIA SPORTAGE OCCUPANT .....</b>	<b>6</b>
DRIVER DEMOGRAPHICS .....	6
DRIVER INJURIES .....	6
DRIVER KINEMATICS.....	6
<b>CRASH DIAGRAM.....</b>	<b>8</b>
<b>APPENDIX A: IN-SERVICE END TREATMENT EVALUATION</b>	
<b>DATA COLLECTION FORM.....</b>	<b>A-1</b>

**INDIANA UNIVERSITY**  
**TRANSPORTATION RESEARCH CENTER**  
**ON-SITE GUARDRAIL END TREATMENT INVESTIGATION**  
CASE NUMBER - IN16011  
LOCATION - MISSOURI  
VEHICLE - 2002 KIA SPORTAGE  
CRASH DATE - APRIL 2016

**BACKGROUND**

This report documents the on-site investigation of an impact of a sport utility vehicle into a sequential kinking terminal (SKT) guardrail end terminal (**Figure 1**) that is of interest to the Federal Highway Administration (FHWA). This crash was identified by an engineer with the Missouri Department of Transportation who submitted photographs of the damaged guardrail end terminal to the FHWA. The FHWA determined that the guardrail end terminal and crash type were of interest. This crash investigation was then initiated by the National Highway Traffic Safety Administration in April 2016, and assigned to the Special Crash Investigations team at the Indiana University Transportation Research Center. This single-vehicle crash involved a 2002 Kia Sportage (**Figure 2**). The crash occurred in April 2016 at 1830 hours in Missouri and was investigated by a local police agency. The crash scene, SKT, and Kia were inspected in April 2016.

This crash occurred on an exit ramp from the northbound lanes of an interstate highway and in an interchange area of three interstate highways. The Kia was a 4-door SUV equipped with frontal air bags and a driver's knee air bag. The vehicle was not equipped with an event data recorder (EDR) that was supported by a commercially available tool. An unbelted 20-year-old male driver occupied the vehicle. The Kia was traveling north in the left lane of the exit ramp. The driver fell asleep and the vehicle departed the left side of the exit ramp and entered the gore where the front plane struck the SKT (Event 1). The impact extruded 8.7 m (28.6 ft) of guardrail and displaced seven posts. The impact caused the Kia to rotate counterclockwise (counterclockwise) and the right corner of the back plane struck the guardrail.

The vehicle came to final rest heading southeast. The driver then drove the damaged vehicle to the east shoulder of the exit ramp and waited for emergency responders to arrive. The driver



**Figure 1:** View north to the damaged guardrail



**Figure 2:** The damaged 2002 Kia Sportage

sustained police-reported “B” (non- incapacitating) injuries and was transported by ambulance to a hospital. The Kia was towed from the crash scene due to damage.

## CRASH SUMMARY

**Crash Site:** This crash occurred during daytime hours on an exit ramp of the northbound lanes of an interstate highway that was in the interchange area of three interstate highways. The weather conditions were clear with 16.1 kilometers (10 miles) visibility, east-southeast winds at 26 km/h (16 mph), a temperature of 9.4 °C (49 °F), and a dew point of -7.2 °C (19 °F), according to local weather reports.

The Kia was traveling north in the left exit ramp lane on the northbound side of an 11-lane divided interstate highway. The interstate had three concrete northbound through lanes and two concrete exit ramp lanes. The northbound lanes were separated from the six southbound lanes by a concrete median barrier. The northbound through lanes and exit ramp lanes were each 3.7 m (12.1 ft) wide. The exit ramp was bordered by a 1.8 m (5.9 ft) wide left shoulder and a 3.1 m (10.2 ft) wide right shoulder. A blocked-out W- beam guardrail equipped with an SKT end terminal was located on the west side of the exit ramp in the gore. The speed limit was 105 km/h (65 mph). The crash diagram is included at the end of this report.

**Pre-Crash:** The Kia was traveling north in the left exit ramp lane (**Figure 3**). The driver fell asleep and the vehicle departed the left (west) side of the exit ramp (**Figure 4**) and entered the gore heading straight at the SKT.


**Crash:** The left corner of the Kia’s front plane (**Figure 5**) struck the SKT (**Figure 6**). The right half of the front plane also sustained damage from contact with the traffic side of the guardrail as it was deformed and displaced as the vehicle rotated counterclockwise. The force direction on the Kia was in the 12 o’clock sector and the impact resulted in deployment of both frontal air bags and the driver’s knee air bag.



**Figure 3:** View south from the end of the damaged guardrail to the approach of the Kia



**Figure 4:** View northwest to the area of impact with the SKT



**Figure 5:** Damage to the Kia from impact with the SKT

WinSMASH could not be used to calculate delta-V since impacts with a yielding object are out of scope for the program; however, the barrier algorithm of WinSMASH was used to calculate a barrier equivalent speed (BES) of 26 km/h (16 mph) based on the crush to the front plane. The impact extruded 8.7 m (28.6 ft) of guardrail from the SKT and displaced eight posts as the vehicle rotated counterclockwise. The right corner of the vehicle's back plane struck the guardrail as the vehicle rotated (event 2), and the vehicle came to final rest heading southeast with the front portion of the vehicle on the roadway and the back portion on the west shoulder. The driver then drove the vehicle to the east shoulder of the exit ramp and waited for emergency responders to arrive according to the driver's statement to police. The police schematic also showed the final rest position of the vehicle on the east shoulder heading southwest.



**Figure 6:** The damaged SKT

**Post-Crash:** The police were notified of the crash at 1830 hours according to the police crash report and arrived on scene at 1839 hours. The driver sustained police-reported “B” (incapacitating) injuries and was transported by ambulance to a hospital. His level of treatment is not known.

#### END TERMINAL AND GUARDRAIL DAMAGE

A placard on the SKT identified the model as an “SKT 350 Guardrail Terminal” manufactured by Road Systems, Inc. The front plane impact of the Kia to the SKT resulted in the extrusion of 8.7 m (28.6 ft) of guardrail toward the field side (**Figure 7**). The guardrail was displaced from posts 0 to 6<sup>1</sup>. The anchor cable was displaced from the guardrail and was not present at the scene. Posts 0 and 1 were bolted, hinged steel posts. Post 0 was not present at the SCI inspection; however, the post hinge bolt was present and remained attached to the post base. No strut plate was present between posts 0 and 1. Post 1 was displaced to the ground in the downstream direction and remained attached to the post hinge bolt. Post 2 was displaced downstream 50 degrees off vertical. The offset block was displaced from the post and was not present at the scene. Post 3 was displaced downstream approximately 60 degrees off vertical and was twisted approximately 80 degrees toward the field side. The offset block was displaced off the post and was not present at the scene. Post 4 was displaced downstream approximately 45 degrees off vertical and was twisted approximately 80 degrees toward the field side. The offset block remained attached to the post. Post 5 was displaced downstream 60 degrees off



**Figure 7:** Extruded guardrail from the SKT and posts 6 to 12, view south

<sup>1</sup> Due to the SCI team's misunderstanding of a post numbering protocol change that occurred just prior to this investigation, post 1 was mistakenly numbered as post 0. The post number references in this report and the “In Service End Treatment Evaluation Data Collection Form” retains the post 1 reference as post 0 since otherwise it would not correspond to the photographic documentation.

vertical and twisted approximately 80 degrees to the field side. The offset block remained attached to the post. Post 6 was displaced downstream approximately 15 degrees off vertical and was twisted approximately 30 degrees toward the field side. The guardrail remained attached at post 7, which was displaced downstream approximately 20 degrees off vertical. A kink was formed in the guardrail at post 7 as the guardrail was displaced to the field side. Posts 8 to 12 were undamaged. There were small deformations in the guardrail near posts 8 and 10 that appeared related to the displacement of the guardrail during the crash. These were not considered kinks. Two kinks were located in the guardrail, one at post 7 and one near the bolt holes for post 6. The total length of damaged guardrail was 17.0 m (55.8 ft). MoDOT markings identifying sections of guardrail to be replaced ended just prior to post 12. The “In-Service End Treatment Evaluation Data Collection Form” is attached to the end of this report as **Appendix A**.

## **2002 KIA SPORTAGE**

### **DESCRIPTION**

The Kia was a front-wheel drive, five-occupant, 4-door SUV with VIN KNDJA723525xxxxxx that was equipped with a 2.4-liter, I-4 engine, automatic transmission, and electronic brake force distribution. The vehicle was not equipped with an EDR. The vehicle was also equipped with second generation frontal air bags, a driver’s knee air bag, and a tilt steering column. The tilt adjustment could not be determined since the steering column was displaced vertically and locked from driver contact. The specified wheelbase was 265 cm (104.3 in).

The vehicle manufacturer’s recommended tire size was P205/75R15. The vehicle was equipped with Hankook Optimo H724 tires of the recommended size. The manufacturer’s recommended cold tire pressure for the front and rear tires was 179 kPa (26 psi). The tires were in good condition prior to the crash. The left front tire was torn during impact with the SKT.

The front row was equipped with driver and front right occupant cloth-covered bucket seats with integral head restraints. The second row was equipped with a cloth-covered bench seat with folding backs and integral head restraints in the outboard seating positions. The driver’s seat track was adjusted between the forward and middle positions and the seat back was upright. The front right occupant’s seat track was adjusted to the rear-most position and the seat back was slightly reclined.

### **EXTERIOR DAMAGE**

**Exterior Damage Event 1:** The front plane sustained direct damage to 15 cm (5.9 in) of the left corner of the front bumper bar, left headlamp/turn signal assembly, fender, and hood from the initial impact with the SKT. Direct damage also occurred to the remaining 137 cm (53.9 in) portion of the front plane as the vehicle rotated counterclockwise and the guardrail deformed (**Figure 2**). This damage occurred above the bumper. The sheet metal of the hood was torn and the radiator and radiator frame were crushed. The totality of the damage involved the full width of the front plane, 152 cm (59.8 in). A set of crush measurements was taken on the bumper bar and a second set on the upper radiator frame. The maximum crush at the bumper level was 10 cm (3.9 in) occurring at C<sub>1</sub>. The maximum crush at the upper radiator frame was 49 cm (19.3 in), also occurring at C<sub>1</sub>. The two levels of crush measurements were averaged in accordance

with the crush measurement protocol and the crush values were:  $C_1 = 30$  cm (11.8 in),  $C_2 = 26$  cm (10.2 in),  $C_3 = 2$  cm (0.8 in),  $C_4 = 1$  cm (0.4 in),  $C_5 = 0$  cm,  $C_6 = 7$  cm (2.8 in).

**Damage Classification Event 1:** The Collision Deformation Classification (CDC) was 12FDEW3. The severity of the damage was moderate.

**Exterior Damage Event 2:** The Kia sustained direct damage to the right corner of the back plane (Figure 8) during the secondary impact with the guardrail as the vehicle rotated counterclockwise. The direct damage began at the right corner of the back bumper and extended 40 cm (15.7 in) to the left. The maximum residual crush was 3 cm (1.2 in) occurring at  $C_1$ . The crush values were:  $C_1 = 0$  cm,  $C_2 = 0$  cm,  $C_3 = 0$  cm,  $C_4 = 0$  cm,  $C_5 = 0$  cm,  $C_6 = 3$  cm (1.2 in).



**Figure 8:** Damage to the back plane of the Kia from secondary impact with the guardrail

**Damage Classification Event 2:** The CDC was 05BREE1. The severity of the damage was minor.

## INTERIOR DAMAGE

The interior of the Kia sustained no intrusions. The lower left instrument panel was fractured from contact by the driver's left knee. The center lower instrument panel was scuffed from contact by the driver's right knee. The steering column was displaced upward from contact by the driver's chest as it loaded through the deployed frontal air bag. The steering wheel was not deformed. All the doors and the back hatch remained closed and operational. There was no damage to any of the glazing.

## MANUAL RESTRAINT SYSTEMS

The front and second row seating positions were equipped with three-point lap and shoulder seat belts with sliding latch plates. The front row seat belts had adjustable upper anchors and pretensioners. Both upper anchors were adjusted to the full-down position. Both retractors functioned normally and actuation of the pretensioners could not be determined.

The driver was not restrained by the lap and shoulder seat belt. Inspection of the seat belt assembly revealed no evidence of loading to the latch plate belt guide, D-ring, or belt webbing.

## SUPPLEMENTAL RESTRAINT SYSTEMS

The Kia was equipped with second-generation frontal air bags and a driver's knee air bag. Both frontal air bags and the driver's knee air bag deployed during the impact with the SKT. There was no damage to any of the air bags.

## 2002 KIA SPORTAGE OCCUPANT

### DRIVER DEMOGRAPHICS

Age/Sex: 20 years/male  
Height: Unknown  
Weight: Unknown  
Eyewear: Unknown  
Seat Type: Bucket  
Seat Track Position: Between forward-most and middle  
Manual Restraint Usage: None  
Usage Source: Vehicle inspection  
Air Bags: Frontal and knee bags, deployed  
Alcohol/Drug Involvement: None  
Egress From Vehicle: Unknown  
Transport From Scene: Ambulance  
Medical Treatment: Unknown

### DRIVER INJURIES

Injury No.	Injury	AIS 2015	Involved Physical Components (IPC)	IPC Confidence Level
1 2	Contusions (bruising) and lacerations, small, on face, not further specified	210402.1 210602.1	Air bag, driver's frontal	Certain
3	Hemorrhage (epistaxis) nose, not further specified	251004.1	Air bag, driver's frontal	Certain
4	Contusion (bruising) on his chest, not further specified	410402.1	Steering wheel hub and/or spokes and rim	Certain
5	Contusion (bruising) on his back, not further specified	410402.1	Seat back, driver's	Probable
6	Lacerations, small, on his right leg, not further specified	810602.1	Center lower instrument panel	Certain
7	Lacerations, small, on his left leg, not further specified	810602.1	Left lower instrument panel, left of steering column	Certain

Source: Police Crash Report.

### DRIVER KINEMATICS

The driver was not restrained by the lap and shoulder seat belt. The seat track was adjusted between the forward-most and middle positions and the seat back was upright. The frontal impact with the SKT resulted in deployment of the driver's frontal air bag and knee air bag. The driver was displaced forward and his face and chest loaded the deployed frontal air bag. He sustained contusions and small lacerations on his face and a bloody nose from contact with the frontal air bag. His chest loaded through the frontal air bag and contacted the steering wheel resulting in



contusions to his chest. He also sustained small lacerations to both legs from contact with the lower instrument panel. The driver rebounded into his seat and sustained a contusion to his back from contact with the seat back. The driver was transported by ambulance to a hospital. His level of treatment is not known since the hospital that he was reportedly transported to had no record of his treatment. The injuries to the driver reported in the police crash report narrative were all of minor severity.



### Exit Ramp from Northbound Lanes of Interstate Highway

Speed Limit = 105 km/h (65 mph)

1 = 2002 Kia Sportage



	 <a href="http://www.nhtsa.gov">www.nhtsa.gov</a>
Case Number:	IN16011

Appendix A  
In-Service End Treatment Evaluation  
Data Collection Form



Case No.: IN16011

PREPOPULATED DATA (BY OTHERS)			
Date of Crash	April 2016	TIME OF CRASH (MILITARY)	Unknown
Case Number	IN16011	State	Missouri
Traffic Route	Interstate	Direction (Southbound = SB)	NB
Ambient Conditions (at time of crash)			
Temperature (°F)	Unknown	Lighting	Unknown
Atmospheric	Unknown		

SCENE INFORMATION	
Type of area where crash occurred	<input type="checkbox"/> Urban <input type="checkbox"/> Rural <input checked="" type="checkbox"/> Suburban
Terminal on a horizontal curve?	<input type="checkbox"/> No <input type="checkbox"/> Curve/LT <input checked="" type="checkbox"/> Curve/RT
Estimated or Reconstructed Speed at Impact (MPH)	Unknown
Est. distance (straight line) from terminal impact to COM final rest position (ft.)	Z = 47 ft
Est. distance (longitudinal) along guardrail from terminal impact to COM final resting location (ft.)	X = 47 ft
Est. distance (normal) from either 1. the white paint line; or 2. roadway/shoulder/pavement edge to COM rest position (ft.)	Y = 2 ft into left exit ramp lane and 8 ft from traffic side of guardrail
Super elevation	<input type="checkbox"/> +2% <input type="checkbox"/> -2% <input checked="" type="checkbox"/> NONE or FLAT
Curve Radius (ft.)	1,359

**KEY:**

- COM - Center of Mass of Vehicle
- Distance Measurements



Case No.: IN16011

ON-SCENE INFORMATION	
End Treatment Type	<input type="checkbox"/> Extruder <input type="checkbox"/> ET2000 <input type="checkbox"/> ET-PLUS 4in <input type="checkbox"/> ET-PLUS 5in <input checked="" type="checkbox"/> SKT <input type="checkbox"/> FLEAT <input type="checkbox"/> SOFT STOP
	<input type="checkbox"/> Telescope <input type="checkbox"/> X-LITE <input type="checkbox"/> X-TENSION
Curb? s	<input checked="" type="checkbox"/> No <input type="checkbox"/> AASHTO Type A <input type="checkbox"/> AASHTO Type B <input type="checkbox"/> AASHTO Type C <input type="checkbox"/> AASHTO Type D <input type="checkbox"/> AASHTO Type E <input type="checkbox"/> Yes <input type="checkbox"/> AASHTO Type F <input type="checkbox"/> AASHTO Type G <input type="checkbox"/> AASHTO Type H
Curb Height:	

GUARDRAIL INSTALLATION										
Post No.	Post		Offset Block		PRE-Existing Damage			Offset to post or post hole (ft.)		Spacing to next post (ft. -in.)
	Type	Dim.	Type	Dim.	Yes No Unknown	Describe	Travel way	Curb		
	Steel Wood Other	D x W (in.) or Dia. (in.)	Steel Wood Composite	D x W (in.)						
0	Steel	6 x 4	None		Unk			6.9		7ft 6 in
1	Steel	6 x 4	None		Unk			7.1		Unk
2	Steel	6 x 4	Unk	Unk	Unk			7.2		Unk

Case No.: IN16011

Post No.	Post		Offset Block		PRE-Existing Damage		Offset to post or post hole (ft.)		Spacing to next post (ft. -in.)
	Type	Dim.	Type	Dim.	Yes No Unknown	Describe	Travel way	Curb	
	Steel Wood Other	D x W (in.) or Dia. (in.)	Steel Wood Composite	D x W (in.)					
3	Steel	6 x 4	Unk	Unk	Unk		7.2		Unk
4	Steel	6 x 4	Composite	8x 4	Unk		7.2		Unk
5	Steel	6 x 4	Composite	8 x 4	Unk		7.2		Unk
6	Steel	6 x 4	Composite	8 x 4	Unk		7.2		6 ft 1 in
7	Steel	6 x 4	Composite	8 x 4	Unk		7.2		5 ft 7 in
8	Steel	6 x 4	Composite	8 x 4	No		7.4		6 ft 2 in

Case No.: IN16011

Post No.	Post		Offset Block		PRE-Existing Damage		Offset to post or post hole (ft.)		Spacing to next post (ft. -in.)
	Type	Dim.	Type	Dim.	Yes No Unknown	Describe	Travel way	Curb	
	Steel Wood Other	D x W (in.) or Dia. (in.)	Steel Wood Composite	D x W (in.)					
9	Steel	6 x 4	Composite	8 x 4	No		7.2		6 ft 6 in
10	Steel	6 x 4	Composite	8 x 4	No		7.2		6 ft 0 in
11	Steel	6 x 4	Composite	8 x 4	No		7.2		6 ft 5 in
12	Steel	6 x 4	Composite	8 x 4	No		7.2		6 ft 5 in

Additional Comments

Due to SCI Team’s misunderstanding of a post numbering protocol change that occurred just prior to this investigation, post 1 was mistakenly identified as post 0. This data form retains the identification of the first post as post 0 so that this form is consistent with the post numbering in the photographic documentation.

Case No.: IN16011

EXTRUDER			
Feeder Channel Width at impact head	<input type="checkbox"/> 4 inches <input type="checkbox"/> 5 inches <input checked="" type="checkbox"/> Other 4.5 in		
Guide Chute Exit Height (in.)	13.5 in		
Connection of feeder channels to head damaged?	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes	Are Welds Broken?	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes
Anchor Cable Present?	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes	Connected?	<input type="checkbox"/> No <input type="checkbox"/> Yes
Rail Extrusion?	<input type="checkbox"/> No <input checked="" type="checkbox"/> Yes	Length (ft. in.)	28 ft 7 in
Rail Extrusion Direction	<input type="checkbox"/> Traffic Side <input checked="" type="checkbox"/> Field Side		
Total Length of Rail Damaged (ft.) [total length would include extruded rail plus damaged rail downstream from head.]	55.8		

TELESCOPE			
Rail Displacement	<input type="checkbox"/> No	<input type="checkbox"/> Yes; Length:	No of Panels Displaced <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6

ALL-SYSTEM PERFORMANCE			
Railkinks Downstream of Head?	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	No. of Kinks in Rail: 2
Was there intrusion into the Occupant Compartment by foreign object (guardrail)?	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes		
Did vehicle impact other objects after impact with terminal?	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes		
Object Contacted			

ALL-SYSTEM PERFORMANCE ENVIRONMENT			
SIDESLOPE	50 ft in advance of Post 0	At Post 0	50 ft Past Post 0
Percent - %	Unk	-4%	-10%
Adjacent Lane Width (ft)	12.1 ft		
Lane Type (NAS EDS Variable: Sur. Type)	Concrete		
Shoulder Type	Concrete		

Case No.: IN16011

Shoulder Width (ft)	5.9
Guardrail Height (in)	25.5

VEHICLE INFORMATION	
Vehicle Type (NHTSA Input)	Sport Utility Vehicle
Vehicle Identification Number (VIN)	KNDJA723525xxxxxx
Vehicle Mass (NASS var.: veh.wgt)	3360 lbs
Vehicle orientation upon impact	<input checked="" type="checkbox"/> Case Type 1 <input type="checkbox"/> Case Type 2 <input type="checkbox"/> Case Type 3 <input type="checkbox"/> Case Type 4 <input type="checkbox"/> Case Type 5 <input type="checkbox"/> Case Type 6 <input type="checkbox"/> Case Type 7 <input type="checkbox"/> Case Type 8 <input type="checkbox"/> Other
If 'Other', describe	
Collision Deformation Classification	12FDEW3
Delta-V	Unknown (WinSMASH BES = 16 mph)
Occupant Compartment Penetration of rail	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes; Describe:
Quarter Turns (NASS EDS variable: Rollover)	<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8 <input type="checkbox"/> 9 <input type="checkbox"/> 10 <input type="checkbox"/> 11 <input type="checkbox"/> 12 <input type="checkbox"/> 13 <input type="checkbox"/> 14 <input type="checkbox"/> 15 <input type="checkbox"/> 16 <input type="checkbox"/> 17+
Object Precipitating Rollover, (NASS EDS variable: Rollobj)	N/A
Rollover Type, Terhune Scale, (NASS EDS variable: rolintyp)	N/A

DOT HS 812 639  
October 2018



U.S. Department  
of Transportation  
**National Highway  
Traffic Safety  
Administration**

