

U.S. Department of Transportation

National Highway Traffic Safety Administration

DOT HS 812 954



June 2020

Special Crash Investigations: On-Site Guardrail End Terminal Crash Investigation; Vehicle: 2004 Jeep Grand Cherokee; Location: Missouri; Crash Date: November 2017

DISCLAIMER

This publication is distributed by the U.S. Department of Transportation, National Highway Traffic Safety Administration, in the interest of information exchange. The opinions, findings and conclusions expressed in this publication are those of the authors and not necessarily those of the Department of Transportation or the National Highway Traffic Safety Administration. The United States Government assumes no liability for its contents or use thereof. If trade or manufacturers' names are mentioned, it is only because they are considered essential to the object of the publication and should not be construed as an endorsement. The United States Government does not endorse products or manufacturers.

Suggested APA citation:

 Indiana University Transportation Research Center (2020, June). Special Crash Investigations: On-Site Guardrail End Terminal Crash Investigation; Vehicle: 2004 Jeep Grand Cherokee; Location: Missouri; Crash Date: November 2017 (Report No. DOT HS 812 954). National Highway Traffic Safety Administration.

TECHNICAL REPORT DOCUMENTATION PAGE

12011.110				
1. Report No. DOT HS 812 954	2. Government Accession No.	3. Recipient's Catalog	No.	
4. Title and Subtitle Special Crash Investigations:		5. <i>Report Date:</i> June 2020		
On-Site Guardrail End Terminal C Vehicle: 2004 Jeep Grand Cherok Location: Missouri; Crash Date: November 2017	6. Performing Organiz	ation Code		
7. Author Indiana University Transportation	Research Center	8. Performing Organiz IN17035	cation Report No.	
9. Performing Organization Name and	Address	10. Work Unit No. (TRA	(IS)	
Indiana University Transportation		11. Contract or Grant N	lo.	
501 South Madison Street, Suite 1 Bloomington, Indiana 47403-2452		DTNH22-12-C-00	270	
12. Sponsoring Agency Name and Addre.		13. Type of Report and	Period Covered	
National Highway Traffic Safety National Center for Statistics and	Technical Report			
1200 New Jersey Avenue SE	Analysis (INSA-110)	14. Sponsoring Agency	Code	
Washington, D.C. 20590-0003				
data are based on information ava published. <i>16. Abstract</i> This report documents the on-site end terminal that is of interest to t north side of the eastbound lanes with dual-stage frontal air bags. T the Bosch Crash Data Retrieval to right curve in an undetermined ea high rate of speed several miles p departed the left side of the roadw displaced the guardrail system and during the rollover and came to re dragged by another vehicle. The J	investigation of an SUV impact to an investigation of an SUV impact to an he Federal Highway Administration. of a five-lane, divided interstate high the vehicle was not equipped with an ool. An unbelted 23-year-old male dro stbound lane. Witnesses reported to p rior to the crash site and the vehicle w yay into the median and the front plan d the Jeep rolled over, right-side-lead est on the westbound roadway and wa eep came to final rest on its wheels in ronounced deceased at the crash scene	ion team on the date this n ET-Plus 10 cm (4 in.) n This crash occurred in th way. The Jeep was a 4-d event data recorder (ED by the vehicle. The Jeep police that the vehicle pa was "swerving all over th the struck the end termina ing. The unbelted driver as subsequently run over n the median facing north	nodel guardrail he median on the oor SUV equipped R) supported by was traveling in a ssed them at a he road." The Jeep I. The impact was ejected and possibly h. The driver	
17. Key Words ET-Plus guardrail end, motor ve fatal injury	chicle traffic crash, terminal,	18. Distribution Statement Document is available to the public from the National Technical Information Service, www.ntis.gov.		
19 Security Classif. (of this report) Unclassified	20. Security Classif. (of this page) Unclassified	21. No. of Pages 25	22. Price	
Form DOT 1700.7 (8-72)	Reproduction of complete	d page authorized		

TABLE OF CONTENTS

BACKGROUND1
CRASH SUMMARY
Crash Site
Pre-Crash
Crash
Post-Crash
END TERMINAL AND GUARDRAIL DAMAGE
2004 JEEP GRAND CHEROKEE
Description
NHTSA Recalls
Exterior Damage
Event Data Recorder
Interior Damage
Manual Restraint Systems7
Supplemental Restraint Systems7
2004 JEEP GRAND CHEROKEE OCCUPANT
Driver Demographics
Driver Injuries
Driver Kinematics
CRASH DIAGRAM
APPENDIX A: FHWA Guardrail Form

Special Crash Investigations On-Site Guardrail End Terminal Crash Investigation Case Number: IN17035 Vehicle: 2004 Jeep Grand Cherokee Location: Missouri Crash Date: November 2017

BACKGROUND

This report documents the on-site investigation of an SUV impact to an ET-Plus 10 cm (4 in.) model guardrail end terminal (Figure 1) that is of interest to the Federal Highway Administration (FHWA). This crash was identified by an engineer with the Missouri Department of Transportation, who submitted digital images of the damaged guardrail end terminal and vehicle to the FHWA. The FHWA determined that the guardrail end terminal and crash type were of interest. This crash investigation was then initiated by the National Highway Traffic Safety Administration in November 2017 and assigned to the Special Crash Investigations team at the Indiana University Transportation Research Center. This single-vehicle crash involved a 2004 Jeep Grand Cherokee (Figure 2). The crash occurred in Missouri in November 2017 in the early morning hours and was investigated by a local police agency. The guardrail, crash site, and vehicle were inspected in November 2017.

This crash occurred in the median on the north side of the eastbound lanes of a five-lane, divided, interstate highway. The Jeep was a 4door SUV equipped with dual-stage frontal air bags. The vehicle was not equipped with an event



Figure 1: Jeep's road departure and initial contact with the ET-Plus.



Figure 2: The Jeep's front/left damage.

data recorder (EDR) that was supported by the Bosch Crash Data Retrieval tool. An unbelted 23year-old male drove the vehicle. The Jeep was traveling in a right curve in an undetermined eastbound lane. Witnesses reported to police that the vehicle passed them at a high rate of speed several miles prior to the crash site and that the vehicle was "swerving all over the road." The Jeep departed the left side of the roadway into the median and the front plane struck the end terminal. The impact displaced the guardrail system and the Jeep rolled over, right-side-leading. The unbelted driver was ejected during the rollover and came to rest on the westbound roadway and was subsequently run over by another vehicle. The Jeep came to final rest on its wheels in the median facing north. The driver sustained fatal injuries and was pronounced deceased at the crash scene. The Jeep was towed from the crash scene due to damage.

CRASH SUMMARY

Crash Site

This crash occurred during dark early morning in the median of the eastbound and westbound lanes of a five-lane, divided, interstate highway. The weather conditions were clear visibility, northwest winds at 16 km/h (10 mph), a temperature of 0.6 °C (33 °F), and a dew point of -3.3 °C (26 °F), according to local weather reports. The eastbound lanes of the interstate consisted of two concrete through lanes and a right exit lane. The eastbound travel lanes curved to the right and had a calculated radius of curvature of 567.3 m (1,861.2 ft). These lanes were bordered by a 3.0 m (9.8 ft) wide concrete/bituminous median shoulder and a 1.8 m (5.9 ft) wide concrete right shoulder. The exit ramp and left through lanes were each 3.7 m (12.1 ft) wide. The right through lane was 3.4 m (11.2 ft) wide. A grass median with a cable guardrail system separated the east and westbound travel lanes. An additional W-beam guardrail system with the ET-Plus 10 cm (4 in.) model end terminal was located on the travel lane side of the cable median barrier beginning at the apex of the right curve. The first 7 posts of the guardrail system were wood. The roadway pavement markings consisted of a solid yellow median edge line, broken white lane lines, and a solid white right edge line. The speed limit was 113 km/h (70 mph). A crash diagram is included at the end of this report.

Pre-Crash

The Jeep was traveling eastbound at a witnessreported high rate of speed. The witnesses further stated that as the Jeep passed them several kilometers prior to the impending crash site, the driver was swerving between the travel lanes. As the Jeep driver entered the right curve, the Jeep drifted to the left and departed the travel lane onto the left (north) shoulder (**Figure 3**). There was no physical evidence on the roadway to support avoidance maneuvers by the driver of the Jeep. Due to the lack of pre-crash yaw marks, the Jeep was presumed to be tracking immediately prior to impact.



Crash

The front plane, left corner area (see **Figure 2**) struck the end terminal (Event 1). The engagement with the end terminal extended along the left plane involving the front wheel, cowl, and left front door, resulting in lower A-pillar separation from sill and a latch/striker failure. The Jeep began to rotate counterclockwise, resulting in approximately 8 m (26 ft) of tire marks on the concrete shoulder and dirt shoulder that were attributed to the right wheels. The right front wheel furrowed into the ground and the vehicle tripped into a right-side-leading rollover on top of the guardrail (Event 2). The vehicle's right, top, left and undercarriage planes contacted the guardrail. During the rollover, the driver was ejected through the left front door opening. The

vehicle separated from the guardrail and rolled to final rest upright in the median facing north after rolling over an estimated 12 quarter turns over an approximate distance of 36 m (118.1 ft).

Post-Crash

The driver of the Jeep came to rest in the right eastbound lane. The first blood stain on the concrete surface was located approximately 46 m (150.0 ft) east of the initial point of impact with the end terminal. A witness reported his body was run over by another vehicle. Blood evidence was present on the road surface for a distance of 30 m (98.0 ft). A witness stopped at the crash site and dragged the driver's body to the south shoulder to avoid additional vehicle contact. The driver sustained fatal injuries and was pronounced deceased at the crash site. His body was transported to the medical examiner's facility where a non-invasive autopsy was performed. The Jeep was towed from the crash site to a local tow facility where it was inspected for this investigation.

END TERMINAL AND GUARDRAIL DAMAGE

The front plane impact of the Jeep to the end terminal extruded 1.7 m (5.6 ft) of guardrail to the field side (Figures 4 and 5) and damaged 34.1 m (111.9 ft) of guardrail and 16 posts. The direct damage involved the full height and width 71 cm [28.0 in] and 30 cm [11.8 in]) of the face of the ET-Plus. Posts 1 to 7 were constructed of wood. The remaining posts were constructed of steel. Posts 1 and 2 were not equipped with offset blocks. Posts 3 to 9 had wood offset blocks. The remaining posts had composite offset blocks. Wood posts 1 to 7 were fractured and displaced during the crash. Post 8 was bent downstream approximately 55 degrees and the wood offset block was slightly damaged and the bolt was pulled through the guardrail. Post 9 was bent downstream approximately 20 degrees and the wood offset block was damaged and the bolt pulled through the guardrail. Post 10 was not bent. The composite offset block was slightly damaged and the bolt pulled through the guardrail. Post 11 was bent downstream approximately 20 degrees and the offset block was damaged and the bolt was pulled through the guardrail. Post 12 was bent downstream approximately 10 degrees and the composite offset block was damaged and the bolt pulled through the guardrail. Post 13 was bent



Figure 4: Guardrail kinking (west facing lookback view).



Figure 5: ET-Plus and extruded guardrail (west facing lookback view).

downstream approximately 20 degrees and the composite offset block was separated from the post. Post 14 was bent downstream approximately 60 degrees and the offset block was damaged

and the bolt pulled through the guardrail. Posts 15 and 16 were displaced downstream approximately 50 degrees and the composite offset blocks were damaged and the bolt pulled through the guardrail. The guardrail was kinked in 13 locations. The width of the feeder channel was 12.7 cm (5.0 in.) and the guide chute exit height was 40.1 cm (15.8 in.).

The connection of the feeder channel to the head was damaged and the welds (**Figure 6**) were broken. The anchor cable was present at the time of the impact but separated due to the crash force. The anchor was displaced to the area between Posts 3 and 4. The height of the undamaged guardrail was 38.1 cm (15.0 in.). The FHWA guardrail form is appended to the end of this report.

2004 JEEP GRAND CHEROKEE

Figure 6: Broken welds at feeder channel.

Description

The Jeep Cherokee Limited was manufactured in

April 2003 and identified by Vehicle Identification Number 1J4GW58N84Cxxxxxx. It was a 4door SUV with a rear lift gate and a roof window. Built on a 269 cm (105.9 in.) wheelbase, the Jeep was powered by a 4.7-liter, V-8 engine linked to a 5-speed automatic transmission with a console-mounted shift lever with 4-wheel drive. The service brakes were power-assisted 4-wheel disc with ABS and electronic brake force distribution. The gross vehicle weight rating was 2,495 kg (5,500 lb) with gross axle weight ratings of 1,248 kg (2,750 lb) front and 1,339 kg (2,950 lb) rear. The vehicle manufacturer's recommended tire size was P235/65R17 with recommended cold tire pressures of 228 kPa (33 psi) for the front and rear axles. At the time of the crash, the Jeep was equipped with Yokohama Avid Touring S tires of the recommended size.

The interior of the Jeep was configured for seating of five occupants (2/3) with front row bucket seats and a three-passenger second row bench seat. All seating surfaces were leather. The front row and second row left and right seat positions were equipped with adjustable head restraints. The driver's head restraint was adjusted 6 cm (2.5 in.) above the seat back. The driver's seat track was power adjustable and was adjusted between the middle and rear-most positions. The recline position of the seat back at the time of the crash is not known since the seat back was displaced and deformed during the crash. Safety systems included manual 3-point lap and shoulder seat belts for the driver and second row left and right positions and a center rear lap belt. Supplemental protection was provided by dual-stage frontal air bags for the driver and front right positions and retractor pretensioners. Both frontal air bags deployed during the crash.

NHTSA Recalls

A VIN search of the NHTSA Safety Issues and Recalls website (NHTSA.gov/recalls) identified two open recalls for the 2004 Jeep Cherokee at the time of the crash. The recalls are as follows.

Date: April 07, 2009 Manufacturer Recall Number: 114 NHTSA Recall Number: 09V-117 Recall Status: Recall Incomplete Summary: This recall pertains to the electric front seat heating elements that may overheat causing an interior fire or injury under certain operating conditions.

Date: January 27, 2015 Manufacturer Recall Number: R06 NHTSA Recall Number: 15V-046 Recall Status: Recall Incomplete

Summary: The air bag system occupant restraint control (ORC) module may experience a front air bag and/or seat belt pretensioner inadvertent deployment. An inadvertent deployment while

driving could distract the driver and cause a crash without warning.

Exterior Damage

Exterior Damage Event 1: The Jeep sustained damage to the front and left planes during the impact with the guardrail end terminal (**Figure** 7). The direct contact damage to the front plane occurred at the left corner. Due to overlapping damage, the length of the direct contact damage on the front plane could not be determined and was estimated at 20 cm (7.9 cm). Engagement with the end terminal involved the bumper and bumper fascia, the left headlamp/turn signal assembly, left fender, left front tire and wheel, and left front door. A crush profile to the front plane could not be documented due to overlapping damage.

Damage Classification Event 1: The Collision Deformation Classification was 12FLEE6 (0 degrees). The damage was rated severe.

Exterior Damage Event 2: The right, top, left planes and undercarriage sustained direct and induced damage during the rollover (**Figure 8**). The most severe damage occurred to the rear portion and forward right aspect of the top plane.



Figure 7: Front plane impact area on the Jeep.



Figure 8: Right side rollover damage depicting the maximum vertical deformation located at Row 1.

The maximum vertical deformation occurred at the right roof side row in Row 1 and measured 62 cm (24.4 in.). The maximum lateral deformation was located at the top of the right B-pillar and measured 32 cm (12.6 in.). Damage occurred to the undercarriage with overlapping damage to the right, top, and left planes when the vehicle interacted with the guardrail during the rollover.

Damage Classification Event 2: The CDC for the rollover was 00TDDO6. The damage pattern was rated severe.

Event Data Recorder

The Jeep was not equipped with an EDR that was supported by the Bosch CDR tool.

Interior Damage

The interior of the Jeep sustained severe intrusion of the passenger compartment. The most severe intrusion involved the right A-pillar/roof side rail (**Figure 9**) and right moon roof track, both of which intruded vertically over 61 cm (24 in.). The right windshield header at the center and right seating positions also intruded vertically 30 - 46 cm (11.8 – 18.1 in.) and 46-61 cm (18.1 – 24 in.), respectively. Evidence of occupant contact consisted of a scuff on the upper rear of the left

front door, likely from the driver's left flank and scuffs on the left B-pillar (**Figure 10**), probably from the driver's left hip. Scuffs were also found on the left roof side rail, possibly from the driver's head (**Figure 11**). The driver's chest loaded the air bag, which also loaded and deformed the steering wheel rim and steering column (**Figure 12**). The windshield was cracked and out of place from impact forces. The second left and right rear glazing was undamaged. The remaining glazing was disintegrated from impact forces.

The left and right front doors came open due to latch/striker failure and lower A-pillar separation from the sill. The left front seat was deformed from guardrail intrusion. The left and right rear doors and the tailgate were jammed shut.



Figure 9: Intrusion of right A-pillar/roof side rail/windshield header (Pole represents guard rail).



Figure 10: Occupant scuffs on left B-pillar.



Figure 11: Occupant contact on left roof side rail.

Manual Restraint Systems

The front and second row left and right seat positions were equipped with 3-point lap and shoulder seat belts. The front row seat belts had sliding latch plates and adjustable upper anchors. The driver's adjustable anchor was in the fulldown position. Second row seat belts were configured with light weight locking latch plates. The driver's retractor was an emergency locking retractor (ELR) with a pretensioner. Neither pretensioner actuated during the crash. Inspection of the driver's seat belt assembly revealed no evidence of usage in the crash as it was stowed against the B-pillar.



Figure 12: Deployed air bag (packed) and loading on lower steering wheel rim/column.

Supplemental Restraint Systems

The Jeep was equipped with dual-stage frontal air bags for the driver and right passenger positions. Both air bags deployed during the crash. The driver's air bag was mounted in the four-spoke steering wheel rim and concealed by H-configuration module cover flaps. The air bag in its deflated state was 56 cm (22.0 in.) in diameter and was tethered. There was a blood transfer on the left upper quadrant of the air bag, but no damage to the fabric or the inflator.

The front right air bag deployed through a single cover flap in the right mid instrument panel. A tear was present in the right side panel of the air bag from probable contact with the intruding roof structure and trim during the rollover.

2004 JEEP GRAND CHEROKEE OCCUPANT

Driver Demographics

01	
Age/sex:	23 years/male
Height:	193 cm (76 in.)
Weight:	110 cm (242 lb)
Eyewear:	Unknown
Seat type:	Bucket
Seat track position:	Between middle and rear-most
Manual restraint usage:	None
Usage source:	Vehicle inspection, occupant ejection
Air bags:	Frontal, deployed
Alcohol/drug involvement:	BAC=.227 g/dL; positive for THC
Egress from vehicle:	Totally ejected during the rollover
Transport from scene:	Medical examiner
Medical treatment:	None, non-invasive autopsy

Driver Injuries

Injury No.	Injury	Injury Severity AIS 2015	Involved Physical Component (IPC)	IPC Confidence Level
1	Pneumocephalus	140682.3	Isolated IPC Primary: Other vehicle or object – Ground Alternate: Exterior of other motor vehicle – Tires and wheels	Probable Possible
2	Occipital skull fracture	150400.2	Isolated IPC Primary: Other vehicle or object – Ground Alternate: Exterior of other motor vehicle – Tires and wheels	Probable Possible
3	Parietal skull fracture, left	150400.2	Isolated IPC Primary: Other vehicle or object – Ground Alternate: Exterior of other motor vehicle – Tires and wheels	Probable Possible
4	Left femur fracture, NFS	853000.3	Isolated IPC Primary: Exterior of other motor vehicle – Tires and wheels Alternate: Other vehicle or object – Ground	Probable Possible
5	Bilateral rib fractures, NFS	450210.2	Isolated IPC Primary: Other vehicle or object – Ground Alternate: Exterior of other motor vehicle – Tires and wheels	Probable Possible
6	Comminuted left humerus shaft fracture	751271.2	Isolated IPC Primary: Other vehicle or object – Ground Alternate: Exterior of other motor vehicle – Tires and wheels	Probable Possible
7	Full thickness laceration to posterior scalp	110804.2	Isolated IPC Primary: Other vehicle or object – Ground Alternate: Exterior of other motor vehicle – Tires and wheels or more vehicles	Probable Possible
8	Laceration to anterior scalp	110600.1	Isolated IPC	Probable

Injury No.	Injury	Injury Severity AIS 2015	Involved Physical Component (IPC)	IPC Confidence Level	
			Other vehicle or object -		
			Ground		
			Isolated IPC	5 1 11	
	Strin explains right aids at our		Primary: Other vehicle	Probable	
9	Skin avulsion right side at ear down to bone	210804.2	or object – Ground Alternate: Exterior of	Possible	
	down to bone		other motor vehicle –	1 0551010	
			Tires and wheels		
			Isolated IPC		
			Primary: Other vehicle	Probable	
10	Full thickness laceration to left	210804.2	or object – Ground		
10	jaw down to bone	210804.2	Alternate: Exterior of	Possible	
			other motor vehicle –		
			Tires and wheels		
11	Laft museuma fractura	251800.1	Isolated IPC	Probable	
11	Left zygoma fracture	251800.1	Other vehicle or object - Ground	Probable	
			Isolated IPC		
12	Laceration to inner right ear	240208.1	Other vehicle or object -	Probable	
		2.0200.1	Ground	11000010	
	I		Isolated IPC		
13	Laceration to area above right	210600.1	Other vehicle or object -	Probable	
	eye		Ground		
	Multiple superficial punctate		Isolated IPC		
14	lacerations behind right ear	210602.1	Other vehicle or object -	Probable	
	<u></u>		Ground		
15	Abrasion to right eye area	210202.1	Isolated IPC Other vehicle or object -	Probable	
13	Abrasion to right eye area	210202.1	Ground	FIODADIE	
			Isolated IPC		
16	Abrasion to right cheek	210202.1	Other vehicle or object -	Probable	
	e		Ground		
			Isolated IPC		
17	Abrasion to nose	210202.1	Other vehicle or object -	Probable	
			Ground		
10		410000 1	Isolated IPC	D 1 11	
18	Avulsion to skin of right back	410800.1	Other vehicle or object -	Probable	
			Ground		
19	Avulsion to skin of left chest	410800.1	Isolated IPC Other vehicle or object -	Probable	
19	Available to skill of left cliest	+10000.1	Ground	11004010	
			Isolated IPC		
20	Abrasion to right back	410202.1	Other vehicle or object -	Probable	
	<u> </u>		Ground		
			Isolated IPC		
21	Abrasion to left back	410202.1	Other vehicle or object -	Probable	
			Ground		

Injury No.	Injury	Injury Injury AIS 2015 Injury Involved Physica Component (IPC		IPC Confidence Level
22	Multiple abrasions to right chest	410202.1	Isolated IPC Other vehicle or object - Ground	Probable
23	Multiple abrasions to left chest	Aultiple abrasions to left chest 410202.1 Isolated IPC Ground		Probable
24	Abrasions to left abdomen	510202.1	Isolated IPC Other vehicle or object - Ground	Probable
25	Avulsion to skin of left forearm down to bone	710804.2	Isolated IPC Primary: Exterior of other motor vehicle – Tires and wheels Alternate: Other vehicle or object – Ground	Probable Possible
26	Laceration to left hand	710600.1	Isolated IPC Other vehicle or object - Ground	Probable
27	Abrasion to right hand	710202.1	Isolated IPC Other vehicle or object - Ground	Probable
28	Abrasion to right shoulder	710202.1	Isolated IPC Other vehicle or object - Ground	Probable
29	Contusion to inner right wrist	710402.1	Isolated IPC Other vehicle or object - Ground	Probable
30	Abrasion to left elbow	710202.1	Isolated IPC Other vehicle or object - Ground	Probable
31	Abrasion to right elbow	710202.1	Isolated IPC Other vehicle or object - Ground	Probable
32	Abrasion to left upper arm	710202.1	Isolated IPC Other vehicle or object - Ground	Probable
33	Abrasions to left forearm	710202.1	Isolated IPC Other vehicle or object - Ground	Probable
34	34 Laceration to left heel down to bone		Isolated IPC Primary: Exterior of other motor vehicle – Tires and wheels Alternate: Other vehicle or object – Ground	Probable Possible

Injury No.	Injury	Injury Severity AIS 2015	Involved Physical Component (IPC)	IPC Confidence Level Probable	
35	Avulsion of toenails and tissue of right foot	810800.1	Isolated IPC Other vehicle or object - Ground		
36	Avulsion to skin of left hip	810800.1	Isolated IPC Other vehicle or object - Ground	Probable	
37	Avulsion to skin of rear and side of left thigh	810800.1	Isolated IPC Other vehicle or object - Ground	Probable	
38	Laceration to rear of right thigh	810600.1	Isolated IPC Other vehicle or object - Ground	Probable	
39	Laceration between right toes 1-2	810600.1	Isolated IPC Other vehicle or object - Ground	Probable	
40	Laceration to right shin	810600.1	Isolated IPC Other vehicle or object - Ground	Probable	
41	Contusion to right foot	810402.1	Isolated IPC Other vehicle or object - Ground	Probable	
42	Contusion to left foot	810402.1	Isolated IPC Other vehicle or object - Ground	Probable	
43	Abrasion to left hip	810202.1	Isolated IPC Other vehicle or object - Ground	Probable	
44	Abrasion to right knee	810202.1	Isolated IPC Other vehicle or object - Ground	Probable	
45	Abrasion to left knee	810202.1	Isolated IPC Other vehicle or object - Ground	Probable	
46	Abrasion to left shin	810202.1	Isolated IPC Other vehicle or object - Ground	Probable	
47	Abrasion to right shin	810202.1	Isolated IPC Other vehicle or object - Ground	Probable	
48	Abrasion to right foot	810202.1	Isolated IPC Other vehicle or object - Ground	Probable	
49	Abrasion to rear of left thigh	810202.1	Isolated IPC Other vehicle or object - Ground	Probable	

Source: Autopsy report (external)

Driver Kinematics


The driver was seated in the Jeep with the seat track adjusted between the middle and rear-most positions. His head restraint was adjusted 6 cm (2.5 in.) above the seat back. The driver was not restrained by the manual seat belt system. At the time of the SCI inspection, the driver's seat belt was retracted and stowed against the B-pillar with no evidence of usage, loading, or damage. Additionally, the driver was completely ejected from the vehicle supporting the lack of seat belt use.

At initial impact with the end terminal, the frontal air bag system deployed. The unbelted driver initiated a forward trajectory and loaded the deployed air bag and the steering assembly. His loading force was transmitted through the air bag, deforming the lower left quadrant of the steering wheel rim and bending the mounting flange at the wheel/column juncture. The left front door opened as the latch released due to stress overload and the lower A-pillar separated from the sill due to guardrail engagement. As the Jeep began to rotate counterclockwise due to the offset left engagement, the driver was displaced to his right. The vehicle overturned on top of the damaged guardrail and completed multiple quarter turns. The driver's head scuffed the intruding right roof side rail. He was thrust to his left by the centripetal force of the rollover and was ejected through the left front door opening. During the ejection, his left hip contacted and scuffed the left lower B-pillar and his left flank contacted and scuffed the door armrest.

The driver was thrown from the vehicle onto the road surface of the eastbound travel lanes. Due to the long throw distance, he tumbled and rolled to rest. Witnesses then reported that the driver was struck by a passing tractor, semi-trailer. Based on images of the driver at the scene and a review of his multiple injuries, his left thigh was probably run over by tires of the tractor, semi-trailer. It is presumed that he was struck and dragged by a second vehicle for an unknown distance along the right eastbound lane. The driver sustained multiple fractures of the skull, ribs and extremities along with multiple deep lacerations, avulsions, and abrasions to his entire body from his initial impact with the concrete road surface and subsequent vehicle impacts and dragging along the road surface. Additionally, his clothing was torn and displaced. There was no evidence of crush type injures to his head or torso. The left femur appeared to have been run over and was severely distorted. Due to the severity and extensive injury to his body from the ejection, specific injuries were not sourced to the vehicle's interior.

A passer-by stopped at the crash site and dragged the driver's body from the right travel lane to the right shoulder to avoid further vehicle contact. The medical examiner removed the body from the crash site and a non-invasive autopsy was performed.

CRASH DIAGRAM




APPENDIX A: FHWA GUARDRAIL FORM


PREPOPULATED DATA (BY OTHERS)							
Date of Crash	te of CrashNovember 2017TIME OF CRASH (MILITARY)						
Case Number	IN17035	State	Missouri				
Traffic Route	Interstate	Direction (Southbound = SB)	WB				
	Ambient Con	ditions (at time of crash)					
Temperature (°F)	33	Lighting	Dark				
Atmospheric	Clear						

SCENI	SCENE INFORMATION						
Type of area where crash occurred	Urban Rural Suburban						
Terminal on a horizontal curve?	□No □Curve/LT ⊠Curve/RT						
Estimated or Reconstructed Speed at	Unknown						
Impact (MPH)							
Est. distance (straight line) from terminal	Z = 151 ft						
impact to COM final rest position (ft.)							
Est. distance (longitudinal) along guardrail							
from terminal impact to COM final resting	X = 150 ft						
location (ft.)							
Est. distance (normal) from either							
1. the white paint line; or	Y = 33 ft						
2. roadway/shoulder/pavement edge	1 55 11						
to COM rest position (ft.)							
Super elevation	$\blacksquare +2\%$ (+4%) $\Box -2\%$ \Box NONE or FLAT						
Curve Radius (ft.)	1,860.7						

KEY:

- COM Center of Mass of Vehicle
- Distance Measurements





ON-SCENE INFORMATION								
End Treatment	Extruder	D ET2000	ET-PLUS 4in	ET-PLUS 5in	Пskt	FLEAT	SOFT STOP	
Туре	Telescope	D X-LITE	X -TENSION					
		ГО Туре А 🗖	AASHTO Type B 🗖	AASHTO Type C	DAASHT	D Type D 🗖 AA	SHTO Type E	
Curb?								
S								
Curb Height	-							

					GUARDR	AIL INSTALLATION			
	Р	ost	Offset B	lock		PRE-Existing Damage		Offset to post or post hole (ft.)	
Post No.	Type Steel Wood Other	Dim. D x W (in.) or Dia. (in.)	Type Steel Wood Composite	Dim. D x W (in.)	Yes No Unknown	Describe	Travel way	Curb	Spacing to next post (ftin.)
0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1	Wood	7.5 x 7.8	None	N/A	Unk		5.5	N/A	6' 3''
2	Wood	7.8 x 7.8	None	N/A	Unk		5.1	N/A	5' 9"

In-Service End Treatment Evaluation *Case No.: IN17035*

	Post		Offset Block			PRE-Existing Damage		o post or ole (ft.)	
Post No.	Type Steel Wood Other	Dim. D x W (in.) or Dia. (in.)	Type Steel Wood Composite	Dim. D x W (in.)	Yes No Unknown	Describe	Travel way	Curb	Spacing to next post (ftin.)
3	Wood	Unk	Wood	Unk	Unk		5.6	N/A	5' 10"
4	Wood	Unk	Wood	Unk	Unk		5.2	N/A	5' 8"
5	Wood	Unk	Wood	Unk	Unk		5.0	N/A	6' 2"
6	Wood	Unk	Wood	Unk	Unk		5.2	N/A	6' 4''
7	Wood	Unk	Wood	Unk	Unk		5.2	N/A	6' 4''
8	Steel	6.0 x 4.0	Wood	7.5 x 6.0	Unk		5.0	N/A	6' 3"

In-Service End Treatment Evaluation *Case No.: IN17035*

	Post		Offset Block		PRE-Existing Damage		Offset to post or post hole (ft.)		
Post No.	Type Steel Wood Other	Dim. D x W (in.) or Dia. (in.)	Type Steel Wood Composite	Dim. D x W (in.)	Yes No Unknown	Describe	Travel way	Curb	Spacing to next post (ftin.)
9	Steel	6.0 x 4.0	Wood	7.5 x 6.0	Unk		5.2	N/A	5' 11"
10	Steel	5.8 x 4.0	Composite	7.5 x 4.0	Unk		5.2	N/A	6' 2"
11	Steel	5.8 x 4.0	Composite	7.8 x 4.0	No		5.1	N/A	6' 2"
12	Steel	6.0 x 4.0	Composite	8.0 x 4.0	No		5.1	N/A	6' 2"

Additional Comments

EXTRUDER				
Feeder Channel Width at impact head	¥4inches	5 inches O ther		
Guide Chute Exit Height (in.)	15.8			
Connection of feeder	ΠNo	And Walds Duslary	\square No \bowtie Yes	
channels to head damaged?	Xyes	Are Welds Broken?		
Anchor Cable Present?	ΠNo	Connected?	\mathbf{X}_{No} $\mathbf{\Box}_{\mathrm{Yes}}$	
Anchor Cable Present?	Xyes			
Rail Extrusion?	ΠNo	Length (ft. in.)	5' 8"	
Kan Extrusion?	Xyes	Length (it. iii.)		
Rail Extrusion Direction	Traffic Side	Field Side		
Total Length of Rail Damaged (ft.)	112			
[total length would include extruded	112			
rail plus damaged rail downstream				
from head.]				

TELESCOPE					
Rail Displacement	No	TYes;	Length:	No of Panels Displaced	$\square 1 \square 2 \square 3$ $\square 4 \square 5 \square 6$

ALL-SYSTEM PERFORMANCE				
Railkinks Downstream of Head?	□No	; ;	No. of Kinks in Rail: 13	
Was there intrusion into the Occupant Compartment by foreign object (guardrail)?				
Did vehicle impact other objects after impact with terminal? $\Box_{No} \boxtimes_{Yes}$				
Object Contacted Cable Barrier Guardrail and Ground				

ALL-SYSTEM PERFORMANCE ENVIRONMENT				
SIDESLOPE	50 ft in advance of Post 1	At Post 1	50 ft Past Post 1	
Percent - %	-7%	-7%	-7%	
Adjacent Lane Width (ft)	12.1			
Lane Type (NAS EDS Variable: Sur. Type)	Concrete			
Shoulder Type	Concrete/Bituminous			

Data Collection Form

In-Service End Treatment Evaluation *Case No.: IN17035*

Shoulder Width (ft)	5.9
Guardrail Height (in)	15

VEHICLE INFORMATION			
Vehicle Type (NHTSA Input)	Sport Utility Vehicle		
Vehicle Identification Number (VIN)	1J4GW58N84Cxxxxxx		
Vehicle Mass (NASS var.: veh.wgt)	4,094		
Vehicle orientation upon impact	 Case Type 1 Case Type 2 Case Type 3 Case Type 4 Case Type 5 Case Type 6 Case Type 7 Case Type 8 Other 		
If 'Other', describe			
Collision Deformation Classification	12FLEE6		
Delta-V	Unknown, Severe damage		
Occupant Compartment Penetration of rail	■No Yes , Describe: Rail intruded through roof during rollover when top plane landed on the rail		
Quarter Turns (NASS EDS variable: Rollover)	$\square 1 \square 2 \square 3 \square 4 \square 5 \square 6 \square 7 \square 8 \square 9 \square 10$ $\square 11 \boxtimes 12 \square 13 \square 14 \square 15 \square 16 \square 17+$		
Object Precipitating Rollover, (NASS EDS variable: Rollobj)	Non-collision		
Rollover Type, Terhune Scale, (NASS EDS variable: rolintyp)	Turnover		

DOT HS 812 954 June 2020



U.S. Department of Transportation

National Highway Traffic Safety Administration



14751-060820-v2