



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**



DOT HS 813 767

March 2026

**Special Crash Investigations:
On-Site Ambulance Crash
Investigation;
Vehicle: 2018 Chevrolet Silverado
3500 Type I Ambulance;
Location: Kentucky;
Crash Date: April 2024**

This page is intentionally left blank.

DISCLAIMER

This publication is distributed by the U.S. Department of Transportation, National Highway Traffic Safety Administration, in the interest of information exchange. The opinions, findings and conclusions expressed in this publication are those of the authors and not necessarily those of the Department of Transportation or the National Highway Traffic Safety Administration. The United States Government assumes no liability for its contents or use thereof. If trade or manufacturers' names are mentioned, it is only because they are considered essential to the object of the publication and should not be construed as an endorsement. The United States Government does not endorse products or manufacturers.

Suggested APA Format Citation:

Crash Research & Analysis, Inc. (2026, March). *Special Crash Investigations: On-site ambulance crash investigation; 2018 Chevrolet Silverado 3500 Type I Ambulance; Location: Kentucky; Crash Date: April 2024*. (Report No. DOT HS 813 767). National Highway Traffic Safety Administration. <https://doi.org/10.21949/zqh3-cd81>

This page is intentionally left blank.

Technical Report Documentation Page

1. Report No. DOT HS 813 767	2. Government Accession No.	3. Recipient's Catalog No.	
4. Title and Subtitle Special Crash Investigations: On-Site Ambulance Crash Investigation; Vehicle: 2018 Chevrolet Silverado 3500 Type I Ambulance; Location: Kentucky; Crash Date: April 2024		5. Report Date March 2026	
		6. Performing Organization Code	
7. Author Crash Research & Analysis, Inc.		8. Performing Organization Report No. CR24010	
9. Performing Organization Name and Address Crash Research & Analysis, Inc. PO Box 302 Elma, NY 14059		10. Work Unit No. (TRAIS)	
		11. Contract or Grant No. 693JJ919C000004	
12. Sponsoring Agency Name and Address National Highway Traffic Safety Administration 1200 New Jersey Avenue SE Washington, DC 20590		13. Type of Report and Period Covered Technical Report Crash Date: April 2024	
		14. Sponsoring Agency Code	
15. Supplementary Notes Each crash represents a unique sequence of events and generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle or their safety systems. This report and associated case data are based on information available to the Special Crash Investigation team on the date this report was submitted. Digital Object Identifier https://doi.org/10.21949/zqh3-cd81			
16. Abstract This on-site investigation documents the front plane underride crash of a 2018 Chevrolet Silverado 3500 Type I ambulance and a 2021 Kenworth T3 series refrigerated box truck. The front of the ambulance struck and underrode the left side of the Kenworth. The crash resulted in fatal injuries to the ambulance's belted 26-year-old male EMT driver and 75-year-old male patient secured to the cot, and police-reported B-level (non-incapacitating) injuries to the belted 22-year-old male EMT seated in the patient compartment. The ambulance emergency lights and siren were not activated. The Kenworth was stopped at a stop sign to make a left turn. As it began the left turn, the front plane of the ambulance struck the left side of the Kenworth and underrode it.			
17. Key Words underride, intersection crash, fatal injury, ambulance, EMT		18. Distribution Statement Document is available to the public from the DOT, National Highway Traffic Safety Administration, National Center for Statistics and Analysis, https://crashstats.nhtsa.dot.gov .	
19. Security Classif. (of this report) Unclassified	20. Security Classif. (of this page) Unclassified	21. No. of Pages 79	22. Price

This page is intentionally left blank.

Table of Contents

Background	1
Ambulance Service Information	2
Summary.....	3
Crash Site	3
Pre-Crash.....	3
Crash	4
Post-Crash.....	5
2018 Chevrolet Silverado 3500 Type I Ambulance.....	7
Description.....	7
Exterior Damage	7
Event Data Recorder	8
Interior Damage	9
Manual Restraint Systems.....	9
Supplemental Restraint Systems.....	10
Ambulance Patient Compartment.....	10
Patient Cot System.....	11
2018 Chevrolet Silverado Type I Ambulance Occupants	15
Driver Demographics.....	15
Driver Injuries.....	15
Driver Kinematics	20
EMT Demographics.....	20
EMT Injuries.....	20
EMT Kinematics.....	20
Patient Demographics	21
Patient Injuries	21
Patient Kinematics	23
2021 Kenworth T3.....	25
Description.....	25
Exterior Damage	25
Kenworth Occupant	26
Crash Diagram	27
Appendix A: 2018 Chevrolet Silverado Event Data Recorder Report	A-1

This page is intentionally left blank.

Special Crash Investigations
On-Site Ambulance Crash Investigation
Case Number: CR24010
Vehicle: 2018 Chevrolet Silverado 3500 Type I Ambulance
Location: Kentucky
Crash Date: April 2024

Background

This on-site investigation documents the front plane underride crash of a 2018 Chevrolet Silverado 3500 Type I ambulance (Figure 1) and a 2021 Kenworth T3 series refrigerated box truck (Figure 2). The front of the ambulance struck and underrode the left side of the Kenworth. The crash resulted in fatal injuries to the ambulance's driver and patient, and police-reported B-level (non-incapacitating) injuries to the emergency medical technician (EMT) seated in the patient compartment.

This crash occurred in April 2024 and was identified by the National Highway Traffic Safety Administration's Office of Emergency Medical Services. Investigation of the crash was assigned to the Special Crash Investigations (SCI) team at Crash Research & Analysis, Inc. in April 2024. The SCI team established cooperation with the police in April 2024. The investigating officer arranged a group inspection of the vehicles that included attorneys and investigators/reconstructionists. Inspection of the vehicles and the crash scene were completed in June 2024.



Figure 1. The 2018 Chevrolet Silverado 3500 Type I ambulance



Figure 2. The 2021 Kenworth T3 (detached box immediately behind)

The crash occurred in the three-leg intersection of an undivided U.S. highway and a county roadway. The ambulance was traveling north on the U.S. highway and the driver intended to go straight ahead. The vehicle's emergency lights and siren were not activated. The Kenworth was stopped at a stop sign, facing west on the county roadway. As the driver began the left turn across the highway the front plane of the ambulance struck its left side and underrode it. During its approach the ambulance had begun braking and steering to the right. The impact separated the cargo box from the Kenworth and both vehicles were redirected north, across the southbound lanes, and onto the west roadside. The ambulance came to final rest facing north and the Kenworth facing west.

The ambulance was driven by a belted 26-year-old male and transported a belted 22-year-old male EMT and a 75-year-old male patient secured to the patient cot. The driver and patient were

fatally injured and transported to the medical examiner. The EMT was taken by ambulance to a hospital where he was admitted for one night. The Kenworth driver sustained police-reported C-level (possible) injuries, and an ambulance took him to a hospital. His injury information is unknown. Both vehicles were towed due to damage.

On-site investigation included documentation and measurement of the ambulance's exterior and interior damage and intrusion, identification of occupant contact points, assessment of the manual and supplemental restraint systems, and detailed inspection of the patient compartment and its Stryker Power-Pro 2 patient cot. Additional on-site work included documentation of the crash site's physical environment using photographs and a total station mapping system. A surveillance camera from a business at the intersection recorded the crash and the police gave the video to the SCI team. The Chevrolet had an event data recorder (EDR) that was imaged by the police and a PDF copy of the data was given to the SCI investigator.

Ambulance Service Information

The SCI team collected the following information from the municipal ambulance service, that had been in operation for 41 years, providing non-emergency transfer as well as 911 service. Its area of responsibility was 1,753 square km (677 square miles) with a reported population of 65,654 that were covered by 13 ambulances.

The service required its drivers to take the Volunteer Firemen's Insurance Services emergency vehicle operators' course as well as State fire rescue training. This training was provided by in-house and State fire/rescue training personnel and included classroom and driving instruction. Defensive driving was included in the training and recertification was required every 2 years. The driver was an EMT who had been employed by the service for 16 months. He had been an EMT for 2 years. His work schedule was random and he had been working for 1.5 hours at the time of the crash. He did not work the day before the crash.

The EMT in the patient compartment was a part-time employee and had been with the service for 2 months. His work schedule was variable. He had been working for 1.5 hours at the time of the crash.

The patient sustained a fall at a regional hospital and was being transported to an urban medical center.

Summary

Crash Site

The crash occurred during the day in the intersection of a 6-lane undivided U.S. highway and a two-lane undivided county roadway. Weather and police reports indicated dry conditions, a temperature of 20 °C (68 °F), and 16 km/h (10 mph) winds from the southwest. The ambulance's five-lane highway was level bituminous and was oriented southwest/northeast. The roadway curved slightly left with a radius of 1,084 m (3,556 ft). There were two through lanes in each direction that were separated by a center left turn lane. There was also a right turn lane on the northbound side of the trafficway. All lanes were 3.6 m (12.0 ft) wide and the speed limit was 89 km/h (55 mph). The Kenworth's country roadway had one lane in each direction that were 4 m (13.1 ft) wide in a general east/west direction but at the junction with the U.S. highway, the roadway was oriented in a northwest/southeast direction. There was no posted speed limit for this roadway. A crash diagram is included at the end of this report.

Pre-Crash

The ambulance was traveling northeast in the second through lane at an EDR recorded speed of 142 km/h (88 mph) 5.0 seconds prior to algorithm, enable (AE). The driver intended to continue straight ahead (Figure 3). People in surrounding traffic who saw the ambulance reported it was weaving in and out/around traffic. Its emergency lights and siren were not activated. A surveillance camera located on a business at the intersection recorded the crash and the video showed the Kenworth initially facing northwest and stopped at the stop sign, just in front of the stop bar. The driver then pulled forward about 1.5 m (5 ft) and stopped again. The driver was intending to cross the northbound lanes of traffic and turn left onto the U.S. highway (Figure 4) to go south. The video showed the Kenworth proceeding northwest, into the center of the intersection and the ambulance could be seen approaching from the south. Based on roadway markings made by the police, the ambulance driver braked and steered to the left in an attempt to avoid contact with the Kenworth. The EDR recorded the driver began braking 2.0 seconds prior to AE. At AE the speed of the ambulance was 108 km/h (67 mph).




Figure 3. Northeast view, ambulance's pre-crash travel path to impact area (note: construction barrels were not present at time of crash)




Figure 4. Northwest view, Kenworth's pre-crash travel path to impact area (note: construction barrels were not present at time of crash)

Crash

The front of the ambulance struck the left side of the Kenworth at the back and behind of the left corner of its cab (Event 1). During the impact, the ambulance's front plane underrode the refrigerated cargo box and truck frame (Figure 5). The impact separated the cargo box from the truck's frame (Figure 6). Both vehicles were redirected to the left, across both southbound lanes and onto the west roadside. The ambulance came to final rest facing north and the Kenworth was facing west.



Figure 5. West view, video surveillance of impact. Image used with permission.



Figure 6. Video surveillance of impact, truck/ cargo box separation from truck frame (ambulance is under truck). Image used with permission.

Post-Crash

The EMT ambulance driver and patient were fatally injured and removed from the ambulance by rescue personnel. They were transported to a medical examiner. The EMT passenger exited the vehicle under his own power and tried to render aid to the driver and patient. He sustained police-reported B-level injuries and was transported by ambulance to a hospital where he was admitted for one night. Requests for his injury and treatment information were refused. The Kenworth driver sustained police-reported C-level injuries and was transported by ambulance to a hospital. His medical records were not obtained. Both vehicles were severely damaged and were towed from the crash scene.

This page is intentionally left blank.

2018 Chevrolet Silverado 3500 Type I Ambulance

Description

The Chevrolet was constructed as an incomplete vehicle with the VIN 1GB3KZCY8JFxxxxxx and had a 6.6-liter, 8-cylinder, diesel engine with 4-wheel drive. It was configured on a 426 cm (167.7 in) wheelbase and had antilock brakes on all 4 wheels, stability and traction control, emergency brake assist, seat belt retractor pretensioners, and dual stage frontal air bags. Crash avoidance features were optional for this model, and it is unknown if any of the features were present. The gross vehicle weight rating was 5,988 kg (13,200 lb) with a front rating of 2,540 kg (5,600 lb) and a rear rating of 4,423 kg (9,750 lb). The manufacturer's recommended tires size was LT235/80R17. The ambulance had Goodyear Wrangler Workhorse HT tires, all the recommended size. All tires were in good condition prior to the crash with a minimum of 7 mm (9/32 in) tread on each tire.

The patient compartment was manufactured by REV Ambulance Group Orlando, Inc.,¹ in May 2018, installed onto the Chevrolet chassis in the same year, and completed as a truck-based Type I ambulance. It was a certified "Star of Life" ambulance, conforming to Federal Specification KKK-A-1822F on the date of manufacture. This specification refers to the General Services Administration's standard for minimum specifications, test parameters, and criteria for design, performance, equipment, and appearances of ambulances.

Exterior Damage

The front plane of the ambulance struck the left side of the Kenworth at a speed estimated at 108 km/h (67 mph) and underrode the refrigerated cargo box and frame. The entire front plane sustained direct damage that extended rearward to the right front portion of the patient compartment (Figure 7). The Field L was 182 cm (71.7 in). Crush measurements were taken on the front bumper beam. Above-bumper crush measurements were not taken as there were no remaining measurable structures. The maximum residual bumper crush was 56 cm (22.0 in) and occurred 58 cm (22.8 in) left of the center line. The residual crush profile of the bumper was C1 = 52 cm (20.5), C2 = 56 cm (22.0 in), C3 = 55 cm (21.7 in), C4 = 50 cm (19.7 in), C5 = 50 cm (19.7 in), C6 = 42 cm (16.5 in). The WinSMASH program could not be used for this impact since medium-heavy vehicles are out of scope for the program. The Truck Deformation Classification² for frontal impact damage was 12FDAW9.

¹ Located in South El Monte, CA, it is a subsidiary of REV Group, Inc., Brookfield, WI.

² SAE J1301_202206 – SAE Recommended Practice describing truck (medium, heavy, and articulated combination) collision damage in an alphanumeric format.



Figure 7. Overhead view of front end/cab damage (WS header noted for reference)

Event Data Recorder

The Chevrolet had a sensing diagnostic control module mounted to the floor on the center tunnel. The module monitored the diagnostic functions of the vehicle's passive safety systems (air bags and seat belt pretensioners) and controlled their actuation and deployment based on crash event severity. It had EDR capabilities. The module was removed during the police investigation and imaged by the police via a direct-to-module connection using the Bosch Crash Data Retrieval tool and software version 23.4. A PDF copy of the data was given to SCI at the conclusion of the police investigation and is attached to the end of this report as Appendix A.

The EDR could record non-deployment and deployment events and could store up to three records. Non-deployment events record pre-crash and crash data but do not deploy an air bag. The minimum recorded vehicle velocity change that was needed to record a non-deployment event was 8 km/h (5 mph). The oldest non-deployment event could be overwritten by a deployment event, if all three records were full and the non-deployment event is not locked. A non-deployment event could also be overwritten by a more recent non-deployment event if all three records are full and the non-deployment is older than approximately 250 ignition cycles. Non-deployments could also be recorded if one of the following occurs without the deployment of any of the frontal air bags, side air bags, or roll bars: pretensioner only deployment, head rest deployment, battery cut-off deployment. Deployment events are locked events containing pre-crash and crash data and cannot be overwritten.

The EDR was imaged by the police on ignition cycle 16,551 and contained two deployment records. Event Record 1 was a historical event that occurred on ignition cycle 12,455 and was not related to this crash. Event Record 2 occurred on ignition cycle 16,551 and its data was attributed to this crash.

System Status at Event (Event Record 2): This deployment event was recorded because of the ambulance's impact with the Kenworth. The frontal air bag warning lamp status was "Off" prior to the impact and the event was completely recorded. The driver's seat belt status was "Not Buckled," and the frontal air bag suppression switch status (for the front passenger position) was "On" (enabled)". The maximum longitudinal and lateral delta Vs were -73 km/h (-45 mph) and -17 km/h (-11 mph) and occurred at 298 msec and 216 msec after AE. The first stage of both driver and passenger frontal air bags deployed 9 msec after AE. Neither air bag's second stage deployed. The seat belt pretensioners were commanded 9 msec after AE.

The pre-crash data reported that the ambulance was traveling 142 km/h (88 mph) 5.0 seconds prior to AE and steady accelerator pedal application of 32 or 33 percent. The accelerator pedal percentage became 0 percent -2.5 seconds prior to AE and the brake status was “On” -2.0 seconds prior to AE due to a presumed driver avoidance maneuver. Steering was not recorded. The ambulance’s pre-crash speed at AE was 108 km/h (67 mph).

Interior Damage

The ambulance cab sustained significant damage and intrusion from the impact with the Kenworth. The right A-pillar, right, and center instrument panels intruded longitudinally 67 cm (26.4 in), 58 cm (22.8 in), and 44 cm (17.3 in) (Figure 8). The contact to the Kenworth frame rail bent the steering wheel rim 14 cm (5.5 in), to a 90° angle rearward (Figure 9). The driver seat was deformed and came loose from the floor/seat track due to passenger compartment intrusion. There were blood stains on the driver’s air bag and windshield, but there were other no discernable occupant contacts in the vehicle interior.



Figure 8. Right A-pillar/IP intrusion




Figure 9. 90° steering wheel deformation during Kenworth frame underride

Manual Restraint Systems

The front row had lap and shoulder seat belts with sliding latch plates, adjustable D-rings, and retractor pretensioner. The driver’s adjustable D-ring was in the full down position. The driver was restrained by the lap and shoulder seat belt as evidenced by the extended webbing cut by rescue personnel, 14 cm (5.5 in) below the D-ring. It should be noted the EDR reported the seat

belt was not buckled. The seat belt pretensioner likely actuated since the remaining belt webbing would not retract into the B-pillar, consistent with usage.

Supplemental Restraint Systems

The ambulance had driver and front passenger dual stage frontal air bags, both of which deployed during the crash. The driver air bag was removed from the steering assembly by other unknown investigators prior to SCI inspection. Significant blood was found on the front (Figure 10) and back of the air bag fabric and there was a small tear on the back side lateral to the vent port.



Figure 10. Blood transfers on air bag

Ambulance Patient Compartment

The patient compartment had one right-side door and double doors on the back for patient/EMT egress. Storage cabinets were available along the left interior side and right front of the patient compartment. There was one rear-facing captain's chair at the forward end of the patient compartment, a bench seat on the left side, and two bench seats on the right side. The captain's chair had a 3-point lap and shoulder seat belt. The right bench had two 4-point shoulder harnesses, and 2-point lap belts. The left bench seat also had a 4-point harness with a 2-point lap belt. According to the police report, the EMT was seated and restrained in the rear-facing captain's chair at the time of the crash. The patient was restrained on the cot facing the rear, with the cot's backrest raised to an unknown angle.

There were no intrusions to the patient compartment but there was moderate impact damage to the right-side cabinets (Figure 11) and the front bulkhead (Figure 12).



Figure 11. Damaged right front cabinets




Figure 12. Damaged bulkhead

Patient Cot System

The Stryker Power-Pro 2 patient cot³ (S/N: 230600xxxx) was held in place by the electronic floor-mounted on/off loading system. The cot (Figure 13) was removed from the ambulance after the crash and later replaced back onto the floor mount. At the time of SCI inspection, the cot was fastened onto the mount. There was no power supply for the ambulance and the cot could not be removed.



Figure 13. Stryker Power Pro 2 patient cot

³ Stryker Corporation, Portage, MI.

Cot restraints were present at the lower leg, thigh, and shoulder levels. All restraint webbings were anchored in the proper positions except for the shoulder restraints. The left restraint was anchored to the horizontal hinge (Figure 14) which allowed the back support to be raised and lowered; the proper anchoring point was on the cot frame (Figure 15). The right restraint was anchored to the back support frame; the proper anchoring point for both shoulder restraints was on the cot frame (Figure 16). There was no damage to the cot frame or any of the shoulder restraints; however, the impact force displaced the right shoulder webbing anchor forward and mildly deformed the back support (see Figure 16). The only other damage noted was a broken oxygen cylinder mount under the head of the cot.




Figure 14. Left shoulder strap anchor location (hinge for back support)



Figure 15. Proper mounting location for left shoulder restraint webbing




Figure 16. Right shoulder strap anchor location

The pneumatic piston that raised and lowered the cot's back support was deformed (Figure 17) as a result of the crash. This indicated that the back support was raised during transport and that the patient's loading during the crash forced it downward to a horizontal position. There was no evidence to indicate that the patient cot separated from the floor mount during crash sequence. A representative of the ambulance service confirmed this.



Figure 17. Bent pneumatic piston for back support adjustment denoted by the yellow arrow

This page is intentionally left blank.

2018 Chevrolet Silverado Type I Ambulance Occupants

Driver Demographics

Age/sex: 26 years/male
 Height: 178 cm (70 in)
 Weight: 104 kg (230 lb)
 Eyewear: Unknown
 Seat type: Bucket seat (van type) with adjustable head restraint
 Seat track: Unknown
 Manual restraint usage: Lap and shoulder belt
 Usage source: Vehicle inspection, police crash report
 Air bags: Frontal available; deployed
 Alcohol/drug involvement: None
 Egress from vehicle: Fatal before removed from vehicle
 Transport from scene: None
 Type of medical treatment: None; fatally injured

Driver Injuries

Injury No.	Injury	Injury Severity AIS 2015	Involved Physical Components (IPC)	IPC Confidence Level
1	Gaping 9-inch laceration of left side of forehead and scalp, extending from approximately the midline of the left eyebrow to posterior midline, exposing a comminuted fracture of the skull and calvarium, rupture of dura matter, disruption of brain tissue; subscalp hemorrhage	150406.4	Isolated IPC Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Certain
2	Subdural hemorrhage	140650.3	Isolated IPC Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Certain
3	Subarachnoid hemorrhage	140693.2	Isolated IPC Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Certain

Injury No.	Injury	Injury Severity AIS 2015	Involved Physical Components (IPC)	IPC Confidence Level
4	Bilateral pulmonary contusions, NFS	441410.3	Tandem IPC Primary: Interior - Shoulder portion of belt restraint Secondary: Left Air Bag - Steering wheel hub Tertiary: Front – Steering wheel (combination of rim and hub/spoke)	Possible Probable Certain
5	Left distal humerus fracture, closed	751331.2	Isolated IPC Front - Left instrument panel	Probable
6	4 ¼ x 3-inch irregular discontinuous red-to-orange abrasion on right temporal and parietal scalp	110202.1	Isolated Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Certain
7	1 ¼ x up to 1 ½-inch laceration in a vaguely 90-degree angle shape around lateral side and top of right eye	210602.1	Isolated Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Certain
8	Laceration on right side of face, NFS	210600.1	Isolated Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Certain
9	10 ¼ x up to 9-inch laceration involving chin	210602.1	Isolated Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Certain
10	2 ¼ x 1 ½-inch irregular yellow-to-orange-to-red abrasion involving the lateral half of the left eyebrow and face and forehead lateral to left	210202.1	Isolated Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Certain

Injury No.	Injury	Injury Severity AIS 2015	Involved Physical Components (IPC)	IPC Confidence Level
	eyebrow; 1 ¼ x up to 1 ½-inch irregular discontinuous red abrasion in a vaguely 90-degree angle shape around lateral side and top of right eye; scattered irregular red abrasions on left cheek, each measuring up to ¾ inch; 10 ¼ x up to 9-inch irregular discontinuous red-to orange abrasion on right side of face and chin			
11	Laceration involving the right side of the neck and posterior neck, NFS	310600.1	Isolated Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Certain
12	10 ¼ x up to 9-inch irregular discontinuous red-to orange abrasion involving right side of neck and posterior neck	310202.1	Isolated Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Certain
13	5/8 x 1 1/16-inch linear red abrasion on left lateral neck	310202.1	Isolated Interior – Shoulder portion of belt restraint	Probable
14	1 ½ x ½-inch irregular yellow-tan contusion on left upper chest	410402.1	Isolated Interior – Shoulder portion of belt restraint	Probable
15	¼ x 1/8-inch irregular red-orange abrasion on right superior torso	410202.1	Isolated Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Probable
16	Laceration involving the left supraclavicular region, NFS	710600.1	Isolated Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Certain

Injury No.	Injury	Injury Severity AIS 2015	Involved Physical Components (IPC)	IPC Confidence Level
17	10 ¼ x up to 9-inch irregular discontinuous red-to-orange abrasion involving the left supraclavicular region	710202.1	Isolated Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Certain
18	2 x 1 ½-inch superficial laceration on superior left shoulder	710602.1	Isolated Interior – Shoulder portion of belt restrain	Probable
19	3 x 2-inch superficial laceration on distal dorsal right forearm	710602.1	Isolated Front – Center instrument panel	Possible
20	7 x 4-inch discontinuous irregular red-to-orange abrasion involving the anterior superior, and lateral right shoulder	710202.1	Isolated Exterior of Other Motor Vehicle – Other exterior of other motor vehicle (specify): Refrigerated cargo box	Certain
21	Scattered irregular red-to-orange abrasions on right upper extremity, each measuring up to ½-inch	710202.1	Isolated Front – Center instrument panel	Possible
22	3 x 2-inch irregular red-to-orange abrasions to distal dorsal right forearm	710202.1	Isolated Front – Center instrument panel	Possible
23	3 x 2 ½-inch irregular blue-gray to red-purple contusion on dorsal right hand	710402.1	Isolated Front – Center instrument panel	Possible
24	Scattered irregular abrasions on dorsal right hand	710202.1	Isolated Front – Center instrument panel	Possible
25	7 ½ x 6-inch irregular discontinuous blue-gray contusion on distal posterior and medial left arm	710402.1	Isolated Front – Left instrument panel	Possible
26	7 ½ x 6-inch red abrasion on distal posterior and medial left arm; 5 x 4-inch irregular discontinuous red abrasion overlying humerus fracture	710202.1	Isolated Front – Left instrument panel	Possible

Injury No.	Injury	Injury Severity AIS 2015	Involved Physical Components (IPC)	IPC Confidence Level
27	2 ½ x 1 ½-inch irregular red abrasion on proximal dorsal left forearm	710202.1	Isolated Front – Left instrument panel	Possible
28	2 x 1 ¼-inch irregular red abrasion on dorsal left hand	710202.1	Isolated Front – Left instrument panel	Possible
29	Scattered red contusions on left upper extremity, each measuring up to 1 ½-inches	710402.1	Isolated Front – Left instrument panel	Possible
30	Scattered linear to irregular red abrasions on left upper extremity, each measuring up to 1 ½-inches	710202.1	Isolated Front – Left instrument panel	Possible
31	2 x ¾-inch irregular blue-gray contusion on anterior left hip	810402.1	Isolated Interior – Lap portion of belt restraint	Probable
32	1 ½ x ¾-inch irregular red-purple contusion on distal medial left thigh	810402.1	Isolated Front – Steering wheel rim	Possible
33	2 ½ x 1 ¾-inch irregular blue-gray contusion on medial left knee	810402.1	Isolated Front – Left lower instrument panel (includes knee bolster)	Probable
34	2 x 1 ¾-inch contusion on mid anterior right leg; 2 ½ x 2 ½-inch irregular blue-gray contusion and overlying cutaneous impression on the proximal to mid anterior right leg; additional scattered faint irregular blue-gray to red-purple contusions on right lower extremity	810402.1	Isolated Front – Left lower instrument panel (includes knee bolster)	Probable
35	Additional scattered faint irregular blue-gray to red-purple contusions on left lower extremity	810402.1	Isolated Front – Left lower instrument panel (includes knee bolster)	Probable

Source: Autopsy report (internal)

Driver Kinematics

The driver was likely seated in a nominal upright position and was restrained by the seat belt based upon the SCI inspection of the seat belt. It should be noted the EDR reported the seat belt was not buckled. He had been on duty for 1.5 hours of his shift.

The ambulance struck the Kenworth's left side and underrode its refrigerated box unit. The driver responded to the frontal impact with a forward trajectory, and he loaded the lap and shoulder belt and deployed frontal air bag. This resulted in bilateral pulmonary contusions as well as abrasions, contusions, and lacerations to the left side of his neck and shoulder, as well as a contusion to his left hip from the lap belt. As he loaded the seat belt, the bottom of the cargo box intruded deep into the windshield and passenger compartment. The box struck the driver and caused the open skull fracture, brain hemorrhages, and the face and right upper arm injuries. He sustained a fractured left distal humerus and abrasions and contusions on both arms and hands from contact to the instrument panel. He sustained contusions to his lower legs from contact to the left lower instrument panel. The driver was fatally injured and required removal from the ambulance. He was transported to the county medical examiner.

EMT Demographics

Age/sex:	22 years/male
Height:	Unknown
Weight:	Unknown
Eyewear:	Unknown
Seat type:	Pedestal-mounted, rear-facing captain's chair with integral head restraint
Seat track:	None
Manual restraint usage:	Lap and shoulder belt
Usage source:	Police crash report
Air bags:	None available
Egress from vehicle:	Exited under own power
Transport from scene:	Ambulance to hospital
Type of medical treatment:	Hospitalized one night

EMT Injuries

Injury No.	Injury	Injury Severity AIS 2015	Involved Physical Components (IPC)	IPC Confidence Level
1	Unknown	Unknown	Unknown	Unknown

Medical information request denied

EMT Kinematics

Based on conversations with the investigating officer and a representative from the ambulance service, as well as vehicle inspection, the EMT was seated and belted in the rear-facing captain's chair at the time of the crash.

The frontal impact with the Kenworth displaced the EMT toward the front of the patient compartment and he loaded onto the seatback of the captain's chair. He remained belted in the

seat and rode down the force of the impact. He exited under his own power. He sustained police-reported B-level injuries and was transported by ambulance to a hospital where he was admitted for one night. Requests for his medical information were denied.

Patient Demographics

Age/sex: 75 years/male
 Height: 170 cm/67 in
 Weight: 129 kg/285 lb
 Eyewear: Unknown
 Seat type: Patient cot
 Seat track: Fixed
 Manual restraint usage: Lower leg, thigh, and shoulder harness of patient cot
 Egress from vehicle: Removed by rescue personnel
 Transport from scene: None
 Type of medical treatment: None; fatally injured

Patient Injuries

Injury No.	Injury	Injury Severity AIS 2015	Involved Physical Components (IPC)	IPC Confidence Level
1	Fracture of all ribs in multiple locations	450214.5	Isolated IPC Interior – Other interior object (specify): Cot back support	Possible
2	Transection of right lung	441432.4	Isolated IPC Interior – Other interior object (specify): Cot back support	Possible
3	Right hemothorax, 250 mL	442200.3	Isolated IPC Interior – Other interior object (specify): Cot back support	Possible
4	Open fracture of posterior left parietal scalp with associated subscalp hemorrhage	150404.3	Isolated IPC Interior – Other interior object (specify): Cot back support	Possible
5	Subarachnoid hemorrhage	140693.2	Isolated IPC Interior – Other interior object (specify): Cot back support	Possible
6	Rupture of pericardial sac	441602.2	Isolated IPC Interior – Other interior object (specify): Cot back support	Possible
7	Fracture of 5th cervical vertebra	650230.2	Isolated IPC	Possible

Injury No.	Injury	Injury Severity AIS 2015	Involved Physical Components (IPC)	IPC Confidence Level
			Interior – Other interior object (specify): Cot back support	
8	Fracture of 5th thoracic vertebra	650430.2	Isolated IPC Interior – Other interior object (specify): Cot back support	Possible
9	Fracture of 6th thoracic vertebra	650430.2	Isolated IPC Interior – Other interior object (specify): Cot back support	Possible
10	Scattered mesenteric hemorrhage	542010.2	Isolated Interior – Other interior object (specify): Cot restraint webbing	Possible
11	1 x ¼-inch irregular red abrasion on left parietal scalp	110202.1	Isolated Interior – Other interior object (specify): Cot back support	Possible
12	½ x 1/16-inch linear oblique red abrasion on right upper forehead at hairline; 1 x 1/16-inch linear oblique red abrasion on right lower forehead	210202.1	Unknown	Unknown
13	9 x up to 1-inch red-to-orange abrasion extending from the right lateral neck across the anterior neck to the left lateral neck	310202.1	Isolated Interior – Other interior object (specify): Cot restraint webbing	Probable
14	27-inch red abrasion extending from posterior right shoulder over superior right torso to lower medial left breast	410202.1	Isolated Interior – Other interior object (specify): Cot restraint webbing	Probable
15	5 x 2-inch irregular brown-to-tan contusion on right lower abdomen	510402.1	Isolated Interior – Other interior object (specify): Cot restraint webbing	Probable
16	8 x up to 1-inch red abrasion extending from medial posterior left	710202.1	Isolated Interior – Other interior object (specify): Cot restraint webbing	Probable

Injury No.	Injury	Injury Severity AIS 2015	Involved Physical Components (IPC)	IPC Confidence Level
	shoulder to middle anterior neck			
17	27-inch red abrasion extending from posterior right shoulder over superior right torso to lower medial left breast	710202.1	Isolated Interior – Other interior object (specify): Cot restraint webbing	Probable
18	5 ½ x 3-inch irregular purple-tan contusion on anteromedial left arm	710402.1	Isolated Interior – Other interior object (specify): Cot restraint webbing	Probable
19	¾ x ½-inch irregular red abrasion on anteromedial left arm overlying contusion	710202.1	Isolated Interior – Other interior object (specify): Cot restraint webbing	Probable
20	5 ½ x 3-inch irregular discontinuous red abrasion around right elbow	710202.1	Isolated Interior – Other interior object (specify): Cot restraint webbing	Probable
21	2 x ½-inch irregular skin avulsion on dorsal left hand	710802.1	Isolated Interior – Other interior object (specify): Cot frame	Possible
22	2 x 2-inch irregular discontinuous red abrasion on lateral right knee	810202.1	Isolated Interior – Other interior object (specify): Cot restraint webbing	Probable

Source: Autopsy (internal)

Patient Kinematics

Based on physical evidence and information from the ambulance service, the patient was restrained on the patient cot, with the backrest elevated to an unknown angle above horizontal. Cot restraints were in use at the lower leg, upper leg, and waist levels, and the shoulder harness straps crossed over the chest and were clipped into the waist level restraint.

The frontal impact with the Kenworth displaced the patient toward the front of the vehicle and he heavily loaded the shoulder straps and the back support. The mass of the patient (129 kg/285 lb) and the severity of the impact loaded and deformed the pneumatic piston that adjusted the back support. It was forced into a horizontal position. This impact resulted in fractures of all ribs and transection of the right lung and right hemothorax, three vertebra fractures, and an open fracture and abrasion of the left posterior parietal scalp. Loading on the other restraint webbing resulted in mesenteric hemorrhage as well as abrasions about the neck, shoulders, chest, and arms.

He sustained fatal injuries and required removal from the ambulance by rescue personnel. He was transported to the county medical examiner.

2021 Kenworth T3

Description

The Kenworth was a medium-heavy truck, incomplete vehicle with a refrigerated box mounted to the chassis. It was manufactured in September 2020 with the VIN 2NKHHM60MMxxxxx and had a 6.6 liter, in-line, 6-cylinder engine. The wheelbase was 523 cm (206 in) and the gross vehicle weight rating was 11,793 kg (26,000 lb).

Exterior Damage

The Kenworth's left plane was damaged during the impact with the ambulance. Direct damage began 142 cm (55.9 in) rear of the left front wheel, near the back of the cab, and extended 201 cm (79.1 in) rearward along the frame (Figure 18) and refrigerated cargo box. The cargo box separated from the frame during the impact (Figure 19). At inspection the cargo box was inverted, lying on its top surface. As the ambulance underrode the Kenworth, the diesel exhaust fluid tank ruptured and the diesel fuel tank was indirectly damaged. The WinSMASH program could not be used on this impact since medium-heavy vehicles are out of scope for the program. The TDC for this impact was 09LZAWB.



Figure 18. Kenworth damaged left plane





Figure 19. Refrigerated box, separated from the Kenworth frame

Kenworth Occupant

The Kenworth driver sustained police-reported B-level injuries and was transported by ambulance to a hospital. His specific injury and treatment information is unknown.

Crash Diagram



This page is intentionally left blank.

Appendix A: 2018 Chevrolet Silverado Event Data Recorder Report⁴

⁴ The EDR contained in this technical report was imaged by the police during their investigation and a PDF copy of the data was given to the SCI investigator. The PDF report that follows has been sanitized due to the potential of personally identifiable information.

IMPORTANT NOTICE: Robert Bosch LLC and the manufacturers whose vehicles are accessible using the CDR System urge end users to use the latest production release of the Crash Data Retrieval system software when viewing, printing or exporting any retrieved data from within the CDR program. Using the latest version of the CDR software is the best way to ensure that retrieved data has been translated using the most current information provided by the manufacturers of the vehicles supported by this product.

CDR File Information

User Entered VIN	1GB3KZCY8JF
User	
Case Number	
EDR Data Imaging Date	
Crash Date	
Filename	
Saved on	
Imaged with CDR version	Crash Data Retrieval Tool 23.4
Imaged with Software Licensed to (Company Name)	
Reported with CDR version	Crash Data Retrieval Tool 23.4
Reported with Software Licensed to (Company Name)	
EDR Device Type	Airbag Control Module
Event(s) recovered	Deployment, Deployment

Comments

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events for Front, Side, and Rear (FSR) Events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH [8 km/h]. A Non-Deployment Event contains Pre-Crash and Crash data. The oldest Non-Deployment event can be overwritten by a Deployment Event, if all three records are full and the Non-Deployment Event is not locked. A Non-Deployment Event can be overwritten by a more recent Non-Deployment Event if all three records are full and the Non-Deployment is older than approximately 250 ignition cycles. Also, a Non-Deployment event can be recorded if one of the following occurs without the Deployment of any of the frontal air bags, side air bags, or roll bars:

- Pretensioner(s) only Deployment
- Head Rest Deployment
- Battery Cut-Off Deployment

The second type of SDM recorded crash event for FSR Events is the Deployment Event. It also contains Pre-Crash and Crash data. Deployment Events cannot be overwritten or cleared by the SDM.

Rollover Events contains Pre-Crash and Crash data. Rollover event follow the same rules as FSR Deployment events. The SDM can store up to three Events.

Data:

For FSR Events, SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event and is also not the Barrier Equivalent Velocity. For Deployment and Non-Deployment Events, the SDM will record up to 300 milliseconds of data after time zero. The SDM will also record up to 300 milliseconds of Vehicle Acceleration data after time zero.

For Rollover Events, the SDM may record Lateral Acceleration, Vertical Acceleration, and Roll Rate data, if the SDM is rollover capable. This data reflects what the sensing system experienced during the recorded portion of the event. For Rollover Deployment Events, the SDM will record up to 700 milliseconds of data before the Deployment criteria is met and 290 milliseconds after the Deployment criteria is met.

-Deployment loops may be displayed as being deployed in a Non-Deployment event record, if a Deployment event is qualified during the Non-Deployment event. That is, if two or more events are occurring at the same time and one is a Non-Deployment event and one of the others is a Deployment event, and the Deployment event is qualified while the Non-Deployment is still active, the deployed loops may be recorded in the Non-Deployment event record.

-Time between events is recorded in 10 msec intervals and is displayed in seconds for a maximum time of 655.33 seconds. The counter measures the time from the start of one event to the start of the next event if both events occur within the same ignition cycle.

-The Maximum SDM Recorded Vehicle Velocity Change may occur between the recorded 10 millisecond sample points of the SDM Recorded Vehicle Velocity Change. The SDM will only record Maximum SDM Recorded Vehicle Velocity Change for the first 300 milliseconds of the event.

-If the SDM Recorded Vehicle Velocity Change data exceeds the max output range of -127 km/h then the exceeded values will be displayed with an offset of a +256 km/h. If the SDM Recorded Vehicle Velocity Change data exceeds the max output range of +126 km/h then the exceeded values will be displayed with an offset of a -256 km/h.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- Significant changes in the tire's rolling radius
- Final drive axle ratio changes
- Wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously. The 0.5 second Pre-crash data value (most recent recorded data point) is the data point last sampled before Time Zero. That is to say, the last data point may have been captured just before Time Zero but no more than 0.5 second before Time Zero. All subsequent Pre-crash data values are referenced from this data point.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

- The SDM receives a message with an "invalid" flag from the module sending the pre-crash data

-Pre-Crash Electronic Data Validity Check Status indicates "Data Not Available" if:

- No data is received from the module sending the pre-crash data

-For diesel powered vehicles, the data displayed as Throttle Position (%) is actually the data for the Air Inlet Flap Position. This is not the same as the throttle position for a gasoline powered engine.

-Belt Switch Circuit Status indicates the status of the seat belt switch circuit.

-The ignition cycle counter will increment when the power mode cycles from OFF/Accessory to RUN. Applying and removing of battery power to the module will not increment the ignition cycle counter.

-Ignition Cycles Since DTCs Were Last Cleared can be recorded with a maximum value of 253 cycles and can only be reset by a scan tool.

-Dynamic Deployment Event Counter tracks the number of Deployment events that have occurred during the SDM's lifetime.

-Dynamic Event Counter tracks the number of qualified events (either Deployments, Non-deploy, or Rollover events) that have occurred during the SDM's lifetime.

-For Deployment Events, DTC B0052 (Deployment commanded) shall be recorded with the remainder of the data for this event even though it occurred after Event Enable.

-Once a firing loop has been commanded to be deployed, it will not be commanded to be deployed again during the same ignition cycle. Firing loop times for subsequent deployment type events, during the same ignition cycle, will record the deployment times as N/A.


-In an event where the module is operating on energy reserve, the Dynamic counters may report a value that is less than the actual value. If the stored values in the Dynamic counters are less than the counter values in the event records or if more than one event record has the same counter value as another, the module may have been operating on its energy reserve.

-A Concurrent Event is when two events are happening nearly simultaneously. The "Concurrent Event Flag Set" parameter will indicate "Yes" if one event begins, but before that event is qualified, another event begins and is qualified.

A Non-Deployment event typically becomes qualified if that event exceeds the 5 MPH (8 km/h) delta V recording threshold and the event has concluded. A deployment event (FSR or Rollover) becomes qualified when a deployment has been commanded for that event.

Example of a Concurrent Event:

A Rollover event begins. Before the Rollover event is qualified, a Non-Deployment event begins and is qualified. Sometime after the Non-Deployment event is qualified, the Rollover event is qualified. The Non-Deployment event will be recorded in the first open record even though the Rollover event enabled before the Non-Deployment event. The Rollover event will be recorded in the next open record. The "Concurrent Event Flag Set" parameter will indicate "Yes" for the Rollover event. The "Time Between Events" parameter will indicate the time from the start of the Rollover event to the start of the Non-Deployment event.



Event Record #1	Event Record #2
Event Record Type = Non – Deployment	Event Record Type = Rollover
Concurrent Event Flag = No	Concurrent Event Flag = Yes
Time Between Events = NA	Time Between Events = XX seconds

- The GM parameter name is displayed in parentheses after the NHTSA Part 563 parameter name.
- The reported range of the longitudinal and lateral acceleration values is approximately ± 50 g.
- Due to a CDR Tool data imaging issue, all CDR files imaged from SDM-30 Delphi airbag control modules (ACM) using version 17.6 software are invalid and the ACM must be re-imaged using CDR version 17.6.1 and later software.
- All data should be examined in conjunction with other available physical evidence from the vehicle and scene.

Data Source:

- All SDM recorded data is measured, calculated, and stored internally, except for the following:
- Vehicle Status Data (Pre-Crash) is transmitted by the Body Control Module, via the vehicle’s communication network.
 - The Belt Switch Circuit is wired directly to the SDM.

Data Element Sign Convention:

The following table provides an explanation of the sign notation for data elements that may be included in this CDR report. Directional references to sign notation are all from the perspective of the driver when seated in the vehicle facing the direction of forward vehicle travel.

Data Element Name	Positive Sign Notation Indicates
Longitudinal Acceleration	Forward
Longitudinal Velocity Change	Forward
Lateral Acceleration	Left to Right
Lateral Velocity Change	Left to Right
Vertical Acceleration	Downward
Roll Rate	Clockwise Rotation

Hexadecimal Data:

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR tool.

01050_SDM30-delphi_r021

System Status at Time of Retrieval

Dynamic Deployment Event Counter	1
Multi-Event, Number of Events (Dynamic Event Counter)	1
Dynamic OnStar Notification Event Counter	1
Vehicle Identification Number (VIN)	1GB3KZCY8JF
Ignition Cycle, Download (Ignition Cycles at Investigation)	16551
End Model Part Number	00CE5141
System Type	Delphi with integrated IMU
Software Module Identifier 1	00CE5133
Software Module Identifier 2	05051755
Software Module Identifier 3	015D57C1
Manufacturing Traceability Data, LineID	K
Manufacturing Traceability Data, ShiftID	1
Manufacturing Traceability Data, Year	18
Manufacturing Traceability Data, DayOfTheYear	004
Manufacturing Traceability Data, Serial/Lot/BatchNumber	3M3CLL800
ESS # 1 Traceability Data, Component Identifier	??
ESS # 1 Traceability Data, Part Number/Broadcast Code	0000
ESS # 1 Traceability Data, Supplier Code	D
ESS # 1 Traceability Data, Traceability Number	A00000000
ESS # 2 Traceability Data, Component Identifier	??
ESS # 2 Traceability Data, Part Number/Broadcast Code	0000
ESS # 2 Traceability Data, Supplier Code	D
ESS # 2 Traceability Data, Traceability Number	A00000000
ESS # 3 Traceability Data, Component Identifier	AD
ESS # 3 Traceability Data, Part Number/Broadcast Code	8676
ESS # 3 Traceability Data, Supplier Code	D
ESS # 3 Traceability Data, Traceability Number	A00000000
ESS # 4 Traceability Data, Component Identifier	??
ESS # 4 Traceability Data, Part Number/Broadcast Code	0000
ESS # 4 Traceability Data, Supplier Code	D
ESS # 4 Traceability Data, Traceability Number	A00000000
ESS # 5 Traceability Data, Component Identifier	??
ESS # 5 Traceability Data, Part Number/Broadcast Code	0000
ESS # 5 Traceability Data, Supplier Code	D
ESS # 5 Traceability Data, Traceability Number	A00000000
ESS # 6 Traceability Data, Component Identifier	??
ESS # 6 Traceability Data, Part Number/Broadcast Code	0000
ESS # 6 Traceability Data, Supplier Code	D
ESS # 6 Traceability Data, Traceability Number	A00000000
ESS # 7 Traceability Data, Component Identifier	??
ESS # 7 Traceability Data, Part Number/Broadcast Code	0000
ESS # 7 Traceability Data, Supplier Code	D
ESS # 7 Traceability Data, Traceability Number	A00000000
ESS # 8 Traceability Data, Component Identifier	??
ESS # 8 Traceability Data, Part Number/Broadcast Code	0000
ESS # 8 Traceability Data, Supplier Code	D
ESS # 8 Traceability Data, Traceability Number	A00000000

System Status at Event (Event Record 1)

	Deployment
Event Record Type	Deployment
OnStar Deployment Status Data Sent	Yes
Complete file recorded (Event Recording Complete)	Yes
Crash Record Locked	Yes
OnStar SDM Recorded Vehicle Velocity Change Data Sent	Yes
Deployment Event Counter	1
Multi-Event, Number of Events (Event Counter)	1
OnStar Notification Event Counter	1
Time From Event 1 to 2 (Time Between Events) (seconds)	Data Not Available
Ignition Cycle, Crash (Ignition Cycles at Event)	12455
Algorithm Active: Frontal	Yes
Algorithm Active: Side	No
Algorithm Active: Rollover	No
Algorithm Active: Rear	Yes
Concurrent Event Flag Set	No
Event Severity Status: Frontal Pretensioner	Yes
Event Severity Status: Frontal Stage 1	Yes
Event Severity Status: Frontal Stage 2	No
Event Severity Status: Left Side	No
Event Severity Status: Right Side	No
Event Severity Status: Rear	No
Event Severity Status: Rollover	No
Safety Belt Status, Driver (Driver Belt Switch Circuit Status)	Not Buckled
Frontal air bag suppression switch status (Passenger SIR Suppression Switch Circuit Status)	On (Enabled)
Passenger Air Bag ON Indicator Status	On
Passenger Air Bag OFF Indicator Status	Off
Low Tire Pressure Warning Lamp Status 0.5 Seconds Prior to Time Zero	Off
Frontal Air Bag Warning Lamp (SIR Warning Lamp Status 0.5 Seconds Prior to Time Zero)	Off
SIR Warning Lamp ON/OFF Time Continuously (seconds)	655330
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	11890
Ignition Cycles Since DTCs Were Last Cleared 0.5 Seconds Prior to Time Zero	253
Maximum Delta-V, Longitudinal (Maximum Longitudinal SDM Recorded Vehicle Velocity Change for FSR Event) MPH [km/h]	-2 [-4]
Time, Maximum Delta-V (Time From FSR Time Zero to Maximum Longitudinal SDM Recorded Vehicle Velocity Change)(msec)	140
Maximum Delta-V, Lateral (Maximum Lateral SDM Recorded Vehicle Velocity Change for FSR Event) MPH [km/h]	-1 [-1]
Time Maximum Delta-V, Lateral (Time From FSR Time Zero to Maximum Lateral SDM Recorded Vehicle Velocity Change)(msec)	138
High Voltage Disable Notification Sent	Yes
Deployment Commanded in Energy Reserve Mode	No



DTCs Present at Time of Event (Event Record 1)

B0052-00

Event Data (Event Record 1)

Driver 1st Stage Deployment Loop Commanded	Yes
Passenger 1st Stage Deployment Loop Commanded	Yes
Driver 2nd Stage Deployment Loop Commanded	No
Passenger 2nd Stage Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop #1 Commanded	Yes
Passenger Pretensioner Deployment Loop #1 Commanded	Yes
Frontal Air Bag Deployment, Time to 1st Stage Deployment, Driver (Driver 1st Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	8
Frontal Air Bag Deployment, Time to 2nd Stage, Driver (Driver 2nd Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Frontal Air Bag Deployment, Time to 1st Stage Deployment, Right Front Passenger (Passenger 1st Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	8
Frontal Air Bag Deployment, Time to 2nd Stage, Right Front Passenger (Passenger 2nd Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Side air bag deployment, time to deploy, driver (Driver Thorax/Curtain Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Side air bag deployment, time to deploy, right front passenger (Passenger Thorax/Curtain Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Pretensioner Deployment, Time to Fire, Driver (Driver Pretensioner Time From Time Zero to Deployment Loop #1 or Loop #2 Command Criteria Met) (msec)	8
Pretensioner Deployment, Time to Fire, Right Front Passenger (Passenger Pretensioner Time From Time Zero to Deployment Loop #1 or Loop #2 Command Criteria Met) (msec)	8

Longitudinal Crash Pulse (Event Record 1)





Longitudinal Crash Pulse (Event Record 1)

Time (msec)	Delta-V, Longitudinal (SDM Recorded Vehicle Longitudinal Velocity Change for FSR Event) (MPH)	Delta-V, Longitudinal (SDM Recorded Vehicle Longitudinal Velocity Change for FSR Event) (km/h)
10	-0.6	-1.0
20	-1.2	-2.0
30	-1.9	-3.0
40	-1.2	-2.0
50	-1.2	-2.0
60	-1.9	-3.0
70	-1.2	-2.0
80	-1.9	-3.0
90	-2.5	-4.0
100	-2.5	-4.0
110	-2.5	-4.0
120	-2.5	-4.0
130	-2.5	-4.0
140	-2.5	-4.0
150	-2.5	-4.0
160	-2.5	-4.0
170	-2.5	-4.0
180	-2.5	-4.0
190	-2.5	-4.0
200	-2.5	-4.0
210	-2.5	-4.0
220	-2.5	-4.0
230	-2.5	-4.0
240	-2.5	-4.0
250	-2.5	-4.0
260	-2.5	-4.0
270	-2.5	-4.0
280	-2.5	-4.0
290	-2.5	-4.0
300	-2.5	-4.0

Longitudinal Crash Pulse (Event Record 1)

Time (msec)	Longitudinal Acceleration (SDM Recorded Vehicle Longitudinal Acceleration for FSR Event) (g)	Time (msec)	Longitudinal Acceleration (SDM Recorded Vehicle Longitudinal Acceleration for FSR Event) (g)	Time (msec)	Longitudinal Acceleration (SDM Recorded Vehicle Longitudinal Acceleration for FSR Event) (g)
2	-1.8	102	0.2	202	Data Not Available
4	-3.8	104	-0.2	204	Data Not Available
6	-4.6	106	-0.2	206	Data Not Available
8	-5.8	108	-0.6	208	Data Not Available
10	-2.6	110	-0.6	210	Data Not Available
12	-3.8	112	-0.6	212	Data Not Available
14	-2.6	114	-1.0	214	Data Not Available
16	-2.2	116	-1.0	216	Data Not Available
18	-0.6	118	-1.8	218	Data Not Available
20	-3.8	120	-1.8	220	Data Not Available
22	-2.6	122	-1.8	222	Data Not Available
24	0.6	124	-1.0	224	Data Not Available
26	1.4	126	-0.6	226	Data Not Available
28	-1.4	128	-0.6	228	Data Not Available
30	-2.2	130	-0.6	230	Data Not Available
32	0.2	132	-0.6	232	Data Not Available
34	1.8	134	-1.0	234	Data Not Available
36	-1.8	136	-0.6	236	Data Not Available
38	-0.2	138	-0.6	238	Data Not Available
40	0.6	140	-0.6	240	Data Not Available
42	-1.0	142	Data Not Available	242	Data Not Available
44	0.6	144	Data Not Available	244	Data Not Available
46	-0.6	146	Data Not Available	246	Data Not Available
48	1.0	148	Data Not Available	248	Data Not Available
50	0.6	150	Data Not Available	250	Data Not Available
52	-0.2	152	Data Not Available	252	Data Not Available
54	-1.4	154	Data Not Available	254	Data Not Available
56	-2.2	156	Data Not Available	256	Data Not Available
58	-1.8	158	Data Not Available	258	Data Not Available
60	-0.6	160	Data Not Available	260	Data Not Available
62	0.2	162	Data Not Available	262	Data Not Available
64	0.6	164	Data Not Available	264	Data Not Available
66	0.2	166	Data Not Available	266	Data Not Available
68	-0.2	168	Data Not Available	268	Data Not Available
70	-0.2	170	Data Not Available	270	Data Not Available
72	-0.2	172	Data Not Available	272	Data Not Available
74	-0.2	174	Data Not Available	274	Data Not Available
76	-0.6	176	Data Not Available	276	Data Not Available
78	-1.8	178	Data Not Available	278	Data Not Available
80	-2.2	180	Data Not Available	280	Data Not Available
82	-3.0	182	Data Not Available	282	Data Not Available
84	-2.6	184	Data Not Available	284	Data Not Available
86	-2.6	186	Data Not Available	286	Data Not Available
88	-1.8	188	Data Not Available	288	Data Not Available
90	-1.0	190	Data Not Available	290	Data Not Available
92	-1.0	192	Data Not Available	292	Data Not Available
94	-0.6	194	Data Not Available	294	Data Not Available
96	-0.2	196	Data Not Available	296	Data Not Available
98	-0.2	198	Data Not Available	298	Data Not Available
100	0.2	200	Data Not Available	300	Data Not Available

Lateral Crash Pulse (Event Record 1)



Lateral Crash Pulse (Event Record 1)

Time (msec)	Delta-V, Lateral (SDM Recorded Vehicle Lateral Velocity Change for FSR Event) (MPH)	Delta-V, Lateral (SDM Recorded Vehicle Lateral Velocity Change for FSR Event) (km/h)
10	0.0	0.0
20	-0.6	-1.0
30	-0.6	-1.0
40	0.0	0.0
50	0.0	0.0
60	-0.6	-1.0
70	-0.6	-1.0
80	-0.6	-1.0
90	-0.6	-1.0
100	-0.6	-1.0
110	-0.6	-1.0
120	-0.6	-1.0
130	-0.6	-1.0
140	-0.6	-1.0
150	-0.6	-1.0
160	-0.6	-1.0
170	-0.6	-1.0
180	-0.6	-1.0
190	-0.6	-1.0
200	-0.6	-1.0
210	-0.6	-1.0
220	-0.6	-1.0
230	-0.6	-1.0
240	-0.6	-1.0
250	-0.6	-1.0
260	-0.6	-1.0
270	-0.6	-1.0
280	-0.6	-1.0
290	-0.6	-1.0
300	-0.6	-1.0

Lateral Crash Pulse (Event Record 1)

Time (msec)	Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for FSR Event) (g)	Time (msec)	Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for FSR Event) (g)	Time (msec)	Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for FSR Event) (g)
2	-0.2	102	0.2	202	Data Not Available
4	0.2	104	-0.2	204	Data Not Available
6	-0.2	106	-0.2	206	Data Not Available
8	-1.0	108	-0.2	208	Data Not Available
10	-1.0	110	-0.2	210	Data Not Available
12	-2.2	112	-0.6	212	Data Not Available
14	-1.4	114	-0.2	214	Data Not Available
16	-2.6	116	-0.2	216	Data Not Available
18	-3.4	118	-0.2	218	Data Not Available
20	-3.4	120	-0.2	220	Data Not Available
22	-1.8	122	-0.2	222	Data Not Available
24	-1.4	124	-0.2	224	Data Not Available
26	1.0	126	-0.2	226	Data Not Available
28	1.4	128	-0.2	228	Data Not Available
30	-0.2	130	-0.2	230	Data Not Available
32	1.0	132	-0.6	232	Data Not Available
34	1.8	134	-0.6	234	Data Not Available
36	0.6	136	-0.6	236	Data Not Available
38	2.2	138	-0.2	238	Data Not Available
40	4.6	140	-0.2	240	Data Not Available
42	0.6	142	Data Not Available	242	Data Not Available
44	0.2	144	Data Not Available	244	Data Not Available
46	1.0	146	Data Not Available	246	Data Not Available
48	1.4	148	Data Not Available	248	Data Not Available
50	-1.8	150	Data Not Available	250	Data Not Available
52	0.6	152	Data Not Available	252	Data Not Available
54	0.2	154	Data Not Available	254	Data Not Available
56	-3.4	156	Data Not Available	256	Data Not Available
58	-3.0	158	Data Not Available	258	Data Not Available
60	-2.6	160	Data Not Available	260	Data Not Available
62	-1.8	162	Data Not Available	262	Data Not Available
64	-1.4	164	Data Not Available	264	Data Not Available
66	-1.4	166	Data Not Available	266	Data Not Available
68	-1.4	168	Data Not Available	268	Data Not Available
70	-0.6	170	Data Not Available	270	Data Not Available
72	-0.6	172	Data Not Available	272	Data Not Available
74	-0.6	174	Data Not Available	274	Data Not Available
76	0.2	176	Data Not Available	276	Data Not Available
78	0.2	178	Data Not Available	278	Data Not Available
80	-0.6	180	Data Not Available	280	Data Not Available
82	-1.4	182	Data Not Available	282	Data Not Available
84	-1.0	184	Data Not Available	284	Data Not Available
86	-1.0	186	Data Not Available	286	Data Not Available
88	-1.0	188	Data Not Available	288	Data Not Available
90	-0.6	190	Data Not Available	290	Data Not Available
92	-0.6	192	Data Not Available	292	Data Not Available
94	-0.2	194	Data Not Available	294	Data Not Available
96	-0.2	196	Data Not Available	296	Data Not Available
98	0.2	198	Data Not Available	298	Data Not Available
100	0.2	200	Data Not Available	300	Data Not Available

**Rollover Crash Pulse (Event Record 1)
SDM Recorded Vehicle Roll Rate**

Contains No Recorded Data

**Rollover Crash Pulse (Event Record 1)
Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for Rollover
Event)**

Contains No Recorded Data

**Vertical Crash Pulse (Event Record 1)
Normal Acceleration (SDM Recorded Vehicle Vertical Acceleration for Rollover
Event)**

Contains No Recorded Data

Pre-Crash Data -5.0 to -0.5 sec (Event Record 1)

Times (sec)	Accelerator Pedal, % Full (Accelerator Pedal Position)	Service Brake (Brake Switch Circuit State)	Engine RPM (Engine Speed)	Engine Throttle, % Full (Throttle Position)	Speed, Vehicle Indicated (Vehicle Speed) (MPH [km/h])
-5.0	32	Off	1856	0	76 [122]
-4.5	31	Off	1856	0	76 [122]
-4.0	28	Off	1856	0	76 [122]
-3.5	18	Off	1856	0	76 [122]
-3.0	18	Off	1856	0	76 [122]
-2.5	19	Off	1856	0	76 [122]
-2.0	19	Off	1856	0	76 [123]
-1.5	22	Off	1856	0	76 [122]
-1.0	0	Off	1856	0	76 [122]
-0.5	0	On	1792	0	75 [121]

Pre-Crash Data -2.0 to -0.5 sec (Event Record 1)

Times (sec)	Cruise Control Active	Cruise Control Resume Switch Active	Cruise Control Set Switch Active	Engine Torque (lb-ft [N-m])	Reduced Engine Power Mode Indicator
-2.0	No	No	No	214 [290]	Off
-1.5	No	No	No	215 [292]	Off
-1.0	No	No	No	1 [2]	Off
-0.5	No	No	No	-95 [-129]	Off

System Status at Event (Event Record 2)

	Deployment
Event Record Type	
OnStar Deployment Status Data Sent	No
Complete file recorded (Event Recording Complete)	Yes
Crash Record Locked	Yes
OnStar SDM Recorded Vehicle Velocity Change Data Sent	No
Deployment Event Counter	2
Multi-Event, Number of Events (Event Counter)	2
OnStar Notification Event Counter	2
Time From Event 1 to 2 (Time Between Events) (seconds)	Data Not Available
Ignition Cycle, Crash (Ignition Cycles at Event)	16551
Algorithm Active: Frontal	Yes
Algorithm Active: Side	No
Algorithm Active: Rollover	No
Algorithm Active: Rear	Yes
Concurrent Event Flag Set	No
Event Severity Status: Frontal Pretensioner	Yes
Event Severity Status: Frontal Stage 1	Yes
Event Severity Status: Frontal Stage 2	No
Event Severity Status: Left Side	No
Event Severity Status: Right Side	No
Event Severity Status: Rear	No
Event Severity Status: Rollover	No
Safety Belt Status, Driver (Driver Belt Switch Circuit Status)	Not Buckled
Frontal air bag suppression switch status (Passenger SIR Suppression Switch Circuit Status)	On (Enabled)
Passenger Air Bag ON Indicator Status	On
Passenger Air Bag OFF Indicator Status	Off
Low Tire Pressure Warning Lamp Status 0.5 Seconds Prior to Time Zero	Off
Frontal Air Bag Warning Lamp (SIR Warning Lamp Status 0.5 Seconds Prior to Time Zero)	Off
SIR Warning Lamp ON/OFF Time Continuously (seconds)	655330
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	3859
Ignition Cycles Since DTCs Were Last Cleared 0.5 Seconds Prior to Time Zero	253
Maximum Delta-V, Longitudinal (Maximum Longitudinal SDM Recorded Vehicle Velocity Change for FSR Event) MPH [km/h]	-45 [-73]
Time, Maximum Delta-V (Time From FSR Time Zero to Maximum Longitudinal SDM Recorded Vehicle Velocity Change)(msec)	298
Maximum Delta-V, Lateral (Maximum Lateral SDM Recorded Vehicle Velocity Change for FSR Event) MPH [km/h]	-11 [-17]
Time Maximum Delta-V, Lateral (Time From FSR Time Zero to Maximum Lateral SDM Recorded Vehicle Velocity Change)(msec)	216
High Voltage Disable Notification Sent	Yes
Deployment Commanded in Energy Reserve Mode	Yes



DTCs Present at Time of Event (Event Record 2)

B0052-00

Event Data (Event Record 2)

Driver 1st Stage Deployment Loop Commanded	Yes
Passenger 1st Stage Deployment Loop Commanded	Yes
Driver 2nd Stage Deployment Loop Commanded	No
Passenger 2nd Stage Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop #1 Commanded	Yes
Passenger Pretensioner Deployment Loop #1 Commanded	Yes
Frontal Air Bag Deployment, Time to 1st Stage Deployment, Driver (Driver 1st Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	9
Frontal Air Bag Deployment, Time to 2nd Stage, Driver (Driver 2nd Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Frontal Air Bag Deployment, Time to 1st Stage Deployment, Right Front Passenger (Passenger 1st Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	9
Frontal Air Bag Deployment, Time to 2nd Stage, Right Front Passenger (Passenger 2nd Stage Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Side air bag deployment, time to deploy, driver (Driver Thorax/Curtain Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Side air bag deployment, time to deploy, right front passenger (Passenger Thorax/Curtain Time From Time Zero to Deployment Command Criteria Met) (msec)	Data Not Available
Pretensioner Deployment, Time to Fire, Driver (Driver Pretensioner Time From Time Zero to Deployment Loop #1 or Loop #2 Command Criteria Met) (msec)	9
Pretensioner Deployment, Time to Fire, Right Front Passenger (Passenger Pretensioner Time From Time Zero to Deployment Loop #1 or Loop #2 Command Criteria Met) (msec)	9

Longitudinal Crash Pulse (Event Record 2)





Longitudinal Crash Pulse (Event Record 2)

Time (msec)	Delta-V, Longitudinal (SDM Recorded Vehicle Longitudinal Velocity Change for FSR Event) (MPH)	Delta-V, Longitudinal (SDM Recorded Vehicle Longitudinal Velocity Change for FSR Event) (km/h)
10	-1.2	-2.0
20	-2.5	-4.0
30	-3.7	-6.0
40	-6.2	-10.0
50	-9.9	-16.0
60	-12.4	-20.0
70	-14.9	-24.0
80	-18.0	-29.0
90	-21.1	-34.0
100	-23.6	-38.0
110	-25.5	-41.0
120	-27.3	-44.0
130	-29.2	-47.0
140	-32.3	-52.0
150	-34.8	-56.0
160	-36.7	-59.0
170	-38.5	-62.0
180	-39.8	-64.0
190	-41.6	-67.0
200	-42.3	-68.0
210	-43.5	-70.0
220	-44.1	-71.0
230	-44.7	-72.0
240	-44.7	-72.0
250	-44.7	-72.0
260	-44.1	-71.0
270	-44.7	-72.0
280	-44.7	-72.0
290	-45.4	-73.0
300	-45.4	-73.0

Longitudinal Crash Pulse (Event Record 2)

Time (msec)	Longitudinal Acceleration (SDM Recorded Vehicle Longitudinal Acceleration for FSR Event) (g)	Time (msec)	Longitudinal Acceleration (SDM Recorded Vehicle Longitudinal Acceleration for FSR Event) (g)	Time (msec)	Longitudinal Acceleration (SDM Recorded Vehicle Longitudinal Acceleration for FSR Event) (g)
2	-1.4	102	-3.4	202	-5.8
4	-3.0	104	-5.0	204	-3.4
6	-7.4	106	-11.4	206	-4.6
8	-8.2	108	-15.8	208	-4.6
10	-7.8	110	-11.8	210	-5.8
12	-6.6	112	-10.6	212	-5.4
14	-7.4	114	-15.0	214	-4.2
16	-4.6	116	-3.0	216	-3.0
18	-5.4	118	-2.2	218	-3.4
20	-3.4	120	-7.0	220	-2.6
22	-5.0	122	-17.4	222	-2.2
24	-4.2	124	4.2	224	-2.2
26	-9.8	126	-7.4	226	-2.6
28	-6.6	128	-11.8	228	-1.4
30	-7.0	130	-16.6	230	-2.6
32	-10.6	132	-13.0	232	-3.0
34	-8.2	134	-12.2	234	-1.8
36	-13.0	136	-13.8	236	-2.2
38	-4.6	138	-11.0	238	-1.0
40	-10.2	140	-9.0	240	0.2
42	-12.6	142	-10.2	242	1.8
44	-11.0	144	-12.6	244	0.2
46	-11.0	146	-11.0	246	1.0
48	-22.2	148	-14.6	248	1.8
50	-29.0	150	-13.0	250	2.6
52	-17.4	152	-13.8	252	1.8
54	-12.6	154	-9.4	254	0.2
56	-14.2	156	-11.0	256	-0.2
58	-14.2	158	-7.8	258	-0.2
60	-1.0	160	-11.0	260	-0.6
62	-13.0	162	-9.8	262	-1.0
64	-7.8	164	-11.4	264	-2.2
66	-13.8	166	-10.2	266	-2.2
68	-10.2	168	-3.4	268	-1.4
70	-11.0	170	-2.2	270	-0.6
72	-5.0	172	-3.8	272	-0.6
74	-18.2	174	-3.0	274	-1.8
76	-15.0	176	-8.6	276	-1.8
78	-16.6	178	-9.0	278	-1.8
80	-3.4	180	-8.6	280	-0.6
82	-22.2	182	-10.2	282	-0.6
84	-7.0	184	-7.8	284	-0.6
86	-11.8	186	-7.4	286	-0.6
88	-31.4	188	-6.2	288	-1.8
90	-23.4	190	-5.4	290	-1.0
92	-5.4	192	-5.8	292	0.2
94	-8.2	194	-5.0	294	-0.2
96	-11.0	196	-2.6	296	-0.6
98	-12.6	198	-3.0	298	-0.6
100	-13.8	200	-5.8	300	-0.6

Lateral Crash Pulse (Event Record 2)



Lateral Crash Pulse (Event Record 2)

Time (msec)	Delta-V, Lateral (SDM Recorded Vehicle Lateral Velocity Change for FSR Event) (MPH)	Delta-V, Lateral (SDM Recorded Vehicle Lateral Velocity Change for FSR Event) (km/h)
10	0.0	0.0
20	0.0	0.0
30	0.0	0.0
40	-0.6	-1.0
50	-0.6	-1.0
60	-0.6	-1.0
70	-2.5	-4.0
80	-1.9	-3.0
90	-0.6	-1.0
100	-1.9	-3.0
110	-3.1	-5.0
120	-3.7	-6.0
130	-4.3	-7.0
140	-5.0	-8.0
150	-6.2	-10.0
160	-7.5	-12.0
170	-8.7	-14.0
180	-9.3	-15.0
190	-9.9	-16.0
200	-10.6	-17.0
210	-10.6	-17.0
220	-10.6	-17.0
230	-9.9	-16.0
240	-9.3	-15.0
250	-9.3	-15.0
260	-9.3	-15.0
270	-9.3	-15.0
280	-9.3	-15.0
290	-9.3	-15.0
300	-9.3	-15.0

Lateral Crash Pulse (Event Record 2)

Time (msec)	Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for FSR Event) (g)	Time (msec)	Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for FSR Event) (g)	Time (msec)	Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for FSR Event) (g)
2	0.2	102	1.4	202	0.2
4	0.2	104	-4.2	204	-0.6
6	-0.2	106	1.4	206	0.2
8	-1.0	108	-2.2	208	-0.6
10	-0.6	110	-9.0	210	-0.2
12	-0.6	112	-7.0	212	-0.2
14	-2.2	114	-5.0	214	-0.6
16	1.4	116	-2.2	216	-0.2
18	3.0	118	-3.4	218	-0.6
20	-3.0	120	-3.0	220	0.2
22	-1.4	122	-5.4	222	0.6
24	5.8	124	1.8	224	1.0
26	-1.0	126	-13.8	226	1.4
28	1.0	128	3.8	228	3.0
30	0.2	130	-9.0	230	1.8
32	-0.6	132	-0.2	232	3.4
34	-3.4	134	-0.6	234	2.6
36	-0.6	136	-2.6	236	1.4
38	-6.6	138	-7.4	238	1.8
40	-9.8	140	-5.0	240	0.6
42	3.4	142	-2.2	242	0.6
44	8.2	144	-5.8	244	2.2
46	0.2	146	-5.4	246	-0.2
48	-9.8	148	-6.6	248	-0.2
50	2.2	150	-6.6	250	0.2
52	4.2	152	-4.2	252	0.2
54	1.4	154	-6.2	254	1.4
56	-2.6	156	-6.6	256	0.6
58	-3.8	158	-7.8	258	0.2
60	-10.2	160	-3.8	260	-0.2
62	0.2	162	-3.8	262	-1.0
64	-1.8	164	-5.8	264	0.2
66	-8.6	166	-7.8	266	-0.6
68	-11.4	168	-7.0	268	-0.2
70	-14.2	170	-2.6	270	0.2
72	-7.0	172	-7.8	272	1.0
74	-0.2	174	-1.0	274	1.4
76	6.2	176	-1.0	276	1.8
78	9.0	178	-5.8	278	1.8
80	4.2	180	-3.4	280	-1.0
82	17.4	182	-3.8	282	-1.8
84	9.4	184	-2.2	284	-0.6
86	6.2	186	-1.0	286	0.2
88	2.2	188	-5.8	288	-0.2
90	-6.6	190	-2.2	290	-0.6
92	-5.8	192	1.4	292	-0.6
94	-9.0	194	-2.2	294	-0.6
96	-7.8	196	-5.4	296	-0.2
98	-12.6	198	-1.0	298	0.2
100	-2.6	200	-1.0	300	-0.2

**Rollover Crash Pulse (Event Record 2)
SDM Recorded Vehicle Roll Rate**

Contains No Recorded Data

**Rollover Crash Pulse (Event Record 2)
Lateral Acceleration (SDM Recorded Vehicle Lateral Acceleration for Rollover
Event)**

Contains No Recorded Data

**Vertical Crash Pulse (Event Record 2)
Normal Acceleration (SDM Recorded Vehicle Vertical Acceleration for Rollover
Event)**

Contains No Recorded Data

Pre-Crash Data -5.0 to -0.5 sec (Event Record 2)

Times (sec)	Accelerator Pedal, % Full (Accelerator Pedal Position)	Service Brake (Brake Switch Circuit State)	Engine RPM (Engine Speed)	Engine Throttle, % Full (Throttle Position)	Speed, Vehicle Indicated (Vehicle Speed) (MPH [km/h])
-5.0	32	Off	2176	0	88 [142]
-4.5	33	Off	2176	0	88 [142]
-4.0	33	Off	2176	0	88 [142]
-3.5	33	Off	2176	0	88 [142]
-3.0	33	Off	2176	0	88 [142]
-2.5	0	Off	2176	0	88 [142]
-2.0	0	On	2112	0	88 [141]
-1.5	0	On	1856	0	83 [133]
-1.0	0	On	1536	0	66 [106]
-0.5	0	On	1344	0	67 [108]

Pre-Crash Data -2.0 to -0.5 sec (Event Record 2)

Times (sec)	Cruise Control Active	Cruise Control Resume Switch Active	Cruise Control Set Switch Active	Engine Torque (lb-ft [N-m])	Reduced Engine Power Mode Indicator
-2.0	No	No	No	-88 [-119]	Off
-1.5	No	No	No	-80 [-108]	Off
-1.0	No	No	No	-84 [-114]	Off
-0.5	No	No	No	-77 [-104]	Off

Hexadecimal Data

Hexadecimal data deleted due to the possible presence of personally identifiable information

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.

DOT HS 813 767
March 2026



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**



16569-032426-v3